

Attachment to AECM-83/0597
Page 1 of 2

Page 1 of 2

CONTROL BLOCK:										PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION									
MS GGS 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 55																			
REPORT SOURCE L 6 0 5 0 0 0 4 1 6 7 0 9 0 3 8 3 8 0 9 1 9 8 3 9 DOCKET NUMBER EVENT DATE REPORT DATE																			
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10																			
During performance of the 18 month Motor Operated Valve Thermal Overload																			
Protection Device Functional Test, overload protection devices for 3																			
isolation valves failed. The failure was such that the thermal overload																			
protection was not bypassed during emergency operation of the valve.																			
This was less conservative than the bases for T.S.3.8.4.2. The event is																			
reported pursuant to T.S.6.9.1.12.i. The valves involved were P41F005A,																			
B21F147A and P52F195.																			
SYSTEM CAUSE CAUSE COMPONENT COMP. VALVE CODE CODE SUBCODE CODE SUBCODE SUBCODE S D 11 B 12 C 13 Z Z Z Z Z Z 14 Z 15 Z 16 EVENT YEAR SEQUENTIAL OCCURRENCE REPORT REVISION NO. REPORT NO. CODE TYPE NO. 8 3 1 2 5 0 1 T 0 ACTION FUTURE EFFECT SHUTDOWN HOURS ATTACHMENT NPRO-4 PRIME COMPONENT TAKEN ACTION ON PLANT METHOD HOURS SUBMITTED FORM SUPP. MANUFACTURER X 18 X 19 Z 20 Z 21 0 0 0 0 Y 23 N 24 Z 25 Z 9 9 9 26																			
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27																			
The cause was due to valve wiring not being terminated per design																			
documents. The deficiencies have been corrected and the surveillance																			
has been completed satisfactorily. This is submitted as a final report.																			
FACILITY % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION STATUS 28 0 0 0 29 NA B 31 Surveillance Testing ACTIVITY CONTENT AMOUNT OF ACTIVITY LOCATION OF RELEASE RELEASED OF RELEASE 33 34 NA NA 36																			
PERSONNEL EXPOSURES 39																			
NUMBER TYPE DESCRIPTION 37 Z 38 NA																			
PERSONNEL INJURIES 41																			
NUMBER DESCRIPTION 40 NA																			
LOSS OF OR DAMAGE TO FACILITY 43																			
TYPE DESCRIPTION 42 NA																			
PUBLICITY 45																			
ISSUED DESCRIPTION 44 NA																			
8309230471 830919 PDR ADOCK 05000416 S PDR IEZ2																			
NRC USE ONLY																			

Supplementary Information to
LER 83-125/01 T-0

Mississippi Power & Light Company
Grand Gulf Nuclear Station - Unit 1
Docket No. 50-416

Technical Specification Involved: 3.8.4.2
Reported Under Technical Specification: 6.9.1.12.1

Event Narrative

Overload protection bypass devices for motor operated valves Q1P41-F005A, Q1B21-F147A and P52-F195 failed the functional test performed on August 18 and August 19, 1983. The valves were not required to be operable in the present plant mode, Cold Shutdown. After an inspection, Engineering determined on September 3, that the thermal overload protection valves are not bypassed in the emergency mode as required by Technical Specification 3.8.4.2. This was reported on September 3 as a 24 hour reportable occurrence in accordance with Technical Specification 6.9.1.12.1.

The following are causes of the failures and corrective actions taken:

1. Valve P41-F005A

Cause: Two wires were connected to incorrect terminals.

Action: The wires were reconnected per design documents and the surveillance was performed satisfactorily.

2. Valve B21-F147A

Cause: Wiring was incorrectly installed due to connection lists which were not in accordance with upper tier documents. Relay B21 95-15 was not installed.

Action: The wiring was reconnected correctly, the relay was installed, and the surveillance was completed satisfactorily. The connection lists will be revised.

3. Valve P52-F195

Cause: Wiring was incorrectly installed due to connection lists which were not in accordance with upper tier documents.

Action: The wires were reconnected correctly and the surveillance was performed satisfactorily. The connection lists will be revised.



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

NUCLEAR PRODUCTION DEPARTMENT

September 19, 1983

U.S. Nuclear Regulatory Commission
Region II
101 Marietta St., N.W., Suite 2900
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station
Unit 1
Docket No. 50-416
License No. NPF-13
File: 0260/L-835.0
MOV Thermal Overload Protection
Devices Fail
LER 83-125/01 T-0
AECM-83/0597

On September 3, 1983, during performance of the eighteen month Motor Operated Valve Thermal Overload Protection Device Functional Test, overload protection devices for three isolation valves failed. The failure was such that the thermal overload protection was not bypassed during emergency operation of the valve. This was less conservative than the bases for Technical Specification 3.8.4.2. The event is reported pursuant to Technical Specification 6.9.1.12.1. Attached is LER 83-125/01 T-0 with Supplementary Information.

Yours truly,

L. F. Dale
for L. F. Dale
Manager of Nuclear Services

EBS/SHH:rg
Attachment

cc: Mr. J. B. Richard (w/a)
Mr. R. B. McGehee (w/o)
Mr. T. B. Conner (w/o)
Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a)
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Document Control Desk (w/a)
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Member Middle South Utilities System

OFFICIAL COPY

IE 22

11