

Florida Power

CORPORATION

Crystal River Unit 3
Docket No. 50-302

November 7, 1994

3F1194-04

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D. C. 20555

Subject: Licensee Event Report (LER) 94-006-00

Dear Sir:

Attached is Licensee Event Report (LER) 94-006-00 which is submitted in accordance with 10 CFR 50.73.

Sincerely,

G. L. Boldt
Vice President
Nuclear Production

GLB/JAF:ff

Attachment

xc: Regional Administrator, Region II
Project Manager, NRR
Senior Resident Inspector

150154

IFER
11

CRYSTAL RIVER ENERGY COMPLEX: 15760 W Power Line St • Crystal River, Florida 34428-6708 • (904) 795-6486

* Florida Progress Company

9411160272 941107
PDR ADDCK 05000302
S PDR

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503

ABSTRACT (Limit to 1400 spaces, i.e. approximately fifteen single space typewritten lines) (16)

FPC engineering personnel were reviewing a newly revised calculation for RPS trip setpoints, when it was discovered that setpoints may not be sufficiently conservative relative to TS. Due to a change in calculation methods or assumptions, the calculated instrument string error had increased in the new revision. It was determined that the Variable Low Pressure Trip (VLPT) setpoint was set at the TS limit without provision for instrument error. Later measurement determined that the VLPT setpoint for two of four RPS channels were found to be slightly outside the TS limit. The Shutdown Bypass trip setpoint was also found to be adjusted at its TS limit. This condition is reportable in accordance with 10CFR50.73(a)(2)(i)(B). The remainder of the RPS trip setpoints were determined to be in compliance with TS requirements. The cause was a personnel error by FPC engineering personnel. Corrective actions include: recalibration, procedure changes, and an evaluation to determine the need/benefit of reviewing setpoint calculations for other systems.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-630), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) Crystal River Unit 3 (CR3)	DOCKET NUMBER (2) 0 5 0 0 0 3 0 2	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		9 4 -	0 0 6 -	0 0 0	2	OF	0 6

TEXT (If more space is required, use additional NRC Form 366A's) (17)

EVENT DESCRIPTION:

On October 6, 1994, Florida Power Corporation's (FPC) Crystal River Unit 3 (CR-3) was in MODE ONE (POWER OPERATION), operating at 100% reactor power and generating 880 megawatts. At that time it was determined that the potential existed for CR-3 to have operated outside plant Technical Specifications (TS) relative to the Reactor Protection System (RPS) setpoints.

The RPS is designed to assure that specified acceptable fuel design limits are not exceeded during conditions of normal operation and anticipated transients. The RPS initiates a reactor trip signal whenever preset RPS setpoints are exceeded.

The RPS consists of the following eleven separate trip functions:

1. Nuclear Overpower;
2. RCS High Outlet Temperature;
3. RCS High Pressure;
4. RCS Low Pressure;
5. RCS Variable Low Pressure;
6. Reactor Building High Pressure;
7. Reactor Coolant Pump Power Monitor;
8. Nuclear Overpower RCS Flow And Measured Axial Power Imbalance;
9. Main Turbine Trip;
10. Loss Of Main Feedwater Pumps; and
11. Shutdown Bypass RCS High Pressure.

Figure 1 illustrates the reactor protection trips which define the normal operating envelope. Also included is a portion of the TS Safety Limit Curve for Reactor Coolant System Departure From Nucleate Boiling (TS Figure 2.1.1-1), and the Shutdown Bypass Pressure Trip setpoint. The plant typically operates within the "normal operating box", however, operation anywhere within the confines of the trip envelope is permitted. Any change in parameters which results in an excursion outside the trip envelope will result in a reactor trip. The trip envelope comprises the area bounded by the low pressure limit of 1800 pounds per square inch-gauge (psig.), the high pressure limit of 2355 psig., the high temperature limit of 618 degrees Fahrenheit, and the Variable Low Pressure Trip (VLPT) setpoint boundary (lower right corner of trip envelope) determined by the equation $[11.59 (\text{Loop } T_{\text{hot}}) - 5037.8]$ psig. The Shutdown Bypass trip setpoint is provided for periods of plant heatup, cooldown, or testing when it is desirable to maintain some control rods withdrawn with the reactor subcritical. This provides plant operators with a ready means to add negative reactivity to the core should shutdown margin be reduced inadvertently. In order to achieve this operational condition, the reactor trip functions associated with low RCS pressure or flow must be bypassed. The Shutdown Bypass feature of the RPS is used for this purpose as permitted by TS.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)

DOCKET NUMBER (2)

LER NUMBER (6)

PAGE (3)

Crystal River Unit 3 (CR3)

0 5 0 0 0 3 0 2 9 4 — 0 0 6 — 0 0 0 3 OF 0 6

TEXT (If more space is required, use additional NRC Form 366A's) (17)

On September 14, 1994 FPC engineering personnel were reviewing a newly revised calculation for RPS string errors. The calculation (produced by the Nuclear Steam Supply System (NSSS) vendor) titled "Calculation for Statistical Errors - Crystal River 3 RPS" was a revision to a previous calculation. Factored into the revised calculation were the effects of increased ambient temperatures resulting from Loss-Of-Coolant-Accident (LOCA) conditions. This enhancement was necessary to determine if the RPS instrument strings setpoints were adequate under these conditions. The Summary of Results for the revised calculation stated that increased errors in the high temperature trip, VLPT temperature loops, and an increased pressure trip time response were established. These errors were evaluated with respect to TS setpoints and accident analyses, and were found to be acceptable. The TS limits were unaffected and the RPS setpoints remained substantially the same between the old and new revisions, however the instrument string error had increased in the new revision for those setpoints noted above. Figure 2A illustrates the relationship and effects of the calibration setpoint, TS limits, and instrument string error tolerance. Figure 2B specifically illustrates the situation in which an instrument string could be within calibration specifications, yet be outside the TS limits.

During the review it was determined that the RCS VLPT setpoint was established at the TS limit. No calculated instrument error was used to offset the setpoint in a conservative direction. Therefore, the potential existed to exceed the TS RCS VLPT setpoint due to previous "as-left" tolerance and/or instrument drift. An action plan was developed to evaluate the RPS VLPT calibration setpoint, and further, to similarly evaluate all other RPS setpoints.

An analysis of the "as-left" data from the most recent RPS calibration (March 15, 1994) and the "as-found" data for the VLPT, recorded via the September 30, 1994 work instructions, was conducted. The analysis determined that the VLPT setpoint for RPS channels B & D were found to be slightly outside the TS curve in both the "as-left" condition from the performance of the RPS calibration on March 15, 1994 and the "as-found" data from work instructions performed on September 30, 1994. Based on this analysis, the two RPS VLPT channels would have tripped slightly outside TS limits. Additionally, the Shutdown Bypass trip setpoint was found to be adjusted at its TS setpoint. With no calculated error conservatively offsetting the RPS calibration setpoint from the TS setpoint, the Shutdown Bypass trip setpoint may have permitted operation outside TS limits. This condition for potential operation or condition outside plant TS is reportable in accordance with 10CFR50.73(a)(2)(i)(B). The remainder of the RPS trip setpoints were determined to be in compliance with TS requirements.

EVENT EVALUATION

By initiating a reactor trip when required, the RPS will limit the severity of the transient for each analyzed accident. The RPS consists of four identical channels.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)

DOCKET NUMBER (2)

LER NUMBER (6)

PAGE (3)

Crystal River Unit 3 (CR3)

0 5 0 0 0 3 0 2 9 4 - 0 0 6 - 0 0 0 4 OF 0 6

TEXT (If more space is required, use additional NRC Form 365A's) (17)

The system logic requires at least two of the four channels to trip before initiating a reactor trip. Although two of the four RPS VLPT channels had drifted slightly nonconservative relative to the TS setpoint, the remaining two channels were set to trip the reactor prior to reaching the TS limit. In the event of a failure of one or both of the conservatively calibrated channels the two nonconservatively calibrated channels would trip the reactor just outside the TS limit. In that case the conservatism between the TS setpoint and the safety limit curve would ensure that the reactor would trip prior to exceeding the safety limit. Additionally, none of the FSAR Chapter 14 Design Bases Accidents credit the VLPT for accident mitigation.

The Shutdown Bypass trip setpoint is not applicable for MODE 1 plant operations, but becomes an operational consideration at RCS pressures less than 1720 psig. The bases for this setpoint have been traced to a NSSS specification which established the setpoint to be "as high as possible to allow the maximum pressure range during physics testing", and "low enough below the Low Pressure trip setpoint such that pressure measurement errors could not prevent a trip from occurring".

Therefore, these setpoint discrepancies did not have a significant effect on the margin of safety provided to the general public.

CAUSE

The cause of this event was cognitive personnel error by FPC engineering personnel in that a deficiency existed in the understanding of the impact of the calculation on plant procedures and equipment prior to issuance of the calculation. The same equation described in TS was used to develop the calibration voltages, which established the potential to calibrate the RPS module within the procedural specifications yet fall outside the TS limits.

CORRECTIVE ACTION

Corrective actions for this event include the following.

1. System Engineering personnel will be required to review this event in order to ensure that future actions addressing setpoints will include proper consideration of instrument error.
2. The incorrect VLPT RPS setpoints have been recalibrated and the shutdown bypass setpoint is expected to be completed prior to December 15, 1994.
3. The applicable procedures and Calibration Data Sheets will be revised to reflect the new RPS setpoints.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) Crystal River Unit 3 (CR3)	DOCKET NUMBER (2) 0 5 0 0 0 3 0 2 9 4	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
			0 0 6	0 0	0 5	OF	0 6

TEXT (If more space is required, use additional NRC Form 386A's) (17)

4. An evaluation will be conducted to determine the need/benefit to develop or revise analyses and calculations to provide new calibration setpoints for other systems. These systems include the Engineered Safety Features Actuation System (ESFAS) and the Emergency Feedwater Initiation and Control (EFIC) system. Any setpoints determined to be nonconservative relative to TS limits will be reported via a supplement to this LER.

PREVIOUS SIMILAR EVENTS

There have been three previous reportable events involving RPS calibration.

ATTACHMENT

Figure 1 illustrates the reactor protection trip envelope, including a portion of the TS Reactor Coolant System Departure From Nucleate Boiling (DNB) Safety Limit curve, and the Shutdown Bypass low pressure limit level.

Figure 2A illustrates the relationship of the calibration setpoint, TS limits, and instrument string error tolerance.

Figure 2B illustrates the possible effects of calibration tolerance on TS limits when inadequate offset of RPS setpoint from TS setpoint is employed.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P&SO), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555. AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)

DOCKET NUMBER (2)

LER NUMBER (6)


PAGE (3)

Crystal River Unit 3 (CR3)

0 5 0 0 0 0 3 1 0 2 9 4 - 0 1 0 6 - 0 0 0 1 6 OF 0 5


TEXT (if more space is required, use additional NRC Form 305A's) (17)

FIGURE 1



REACTOR PROTECTION TRIP ENVELOPE

FIGURE 2



RPS CALIBRATION SETPOINTS