

3150-0011

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---|---|---------------|---|---|---|---|---|----|----------------|---|---|---|---|---|---|---|---|---|----|--------------|---|---|---|----|-----|----|--|--|---|
| 0 | 1 | A | L | J | M | F | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | | | 5 |
| 7 | 9 | 14 | | | | | | 15 | 25 | | | | | | | | | | 26 | 30 | | | | 57 | CAT | 58 | | | |
| | | LICENSEE CODE | | | | | | | LICENSE NUMBER | | | | | | | | | | | LICENSE TYPE | | | | | | | | | |

CON'T

REPORT SOURCE L 6 0 5 0 0 0 3 4 8 7 0 9 0 7 8 3 8 1 0 0 6 8 3 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | At 1740 on 9/7/83, during performance of FNP-0-STP-218.2 (Chlorine Analyzer
0 3 | QSV49AE3947B Calibration and Functional Test), the B train chlorine detector
0 4 | was declared inoperable when the zero potentiometer was found to be malfunction-
0 5 | ing. Tech. Spec. 3.3.3.6, in part, requires this detector to be operable. Tech.
0 6 | Spec. 3.3.3.6 action statement requirements were met. Health/safety of the
0 7 | public was not affected. This LER is applicable to both Unit 1 and Unit 2.
0 8 |

| SYSTEM CODE | | CAUSE CODE | | CAUSE SUBCODE | | COMPONENT CODE | | | | COMP. SUBCODE | | VALVE SUBCODE | | | | | |
|---------------------------|----|---------------|----|-----------------------|---------|-----------------|----|-------------|---------|----------------------|----|------------------|----|----------------------|----|------------------------|--|
| 0 | 9 | S | G | E | A | I | N | S | T | R | U | E | Z | | | | |
| 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | | | | |
| (17) LER/RO REPORT NUMBER | | EVENT YEAR | | SEQUENTIAL REPORT NO. | | OCCURRENCE CODE | | REPORT TYPE | | REVISION NO. | | | | | | | |
| 8 3 | | 8 3 | | 0 6 2 | | 0 3 | | L | | 0 | | | | | | | |
| 21 22 | | 23 24 | | 25 26 | | 27 28 | | 29 30 | | 31 32 | | | | | | | |
| ACTION TAKEN | | FUTURE ACTION | | EFFECT ON PLANT | | SHUTDOWN METHOD | | HOURS | | ATTACHMENT SUBMITTED | | NPRD-4 FORM SUB. | | PRIME COMP. SUPPLIER | | COMPONENT MANUFACTURER | |
| A | Z | Z | Z | Z | 0 0 0 0 | N | N | A | X 9 9 9 | | | | | | | | |
| 33 | 34 | 35 | 36 | 37 | 38 | 39 | 40 | 41 | 42 | 43 | 44 | 45 | 46 | 47 | 48 | | |

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 This event was caused by failure of the zero potentiometer. The potentiometer

1 1 was replaced and following satisfactory completion of FNP-0-STP-218.2, the B

1 2 train chlorine detector was declared operable at 0315 on 9/8/83.

1 3

1 4

8 9 80
FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)

1 5 E (28) 1 0 0 (29) NA B (31) Surveillance Test

7 8 9 10 12 13 44 45 46 80

ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 Z (33) Z (34) NA

7 8 9 10 11 44 45 46 80

| PERSONNEL EXPOSURES | | | | | | | | | | |
|---------------------|---|---|------|----|-------------|------|----|------|----|------|
| NUMBER | | | TYPE | | DESCRIPTION | | | | | |
| 1 | 7 | | 0 | 0 | 0 | (37) | Z | (38) | NA | (39) |
| 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 |

| PERSONNEL INJURIES | | NUMBER | | DESCRIPTION | |
|--------------------|---|--------|---|-------------|----|
| 1 | 8 | 0 | 0 | 0 | NA |

LOSS OF OR DAMAGE TO FACILITY
TYPE DESCRIPTION (43) NA

1 9
2 5 9 10

8310140235 831006
PDR ADOCK 05000348
S PDR

ISSUED DESCRIPTION (45) NA

NAME OF PREPARER W. G. Hairston, III

PHONE: (205) 899-5156