

Attachment to AECM-83/0635

Page 1 of 1

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[illegible]

CON'T

0 1 7 8 REPORT SOURCE L 6 0 5 0 0 0 4 1 6 7 0 7 0 8 8 3 8 1 0 0 5 8 3 9
74 75 EVENT DATE REPORT DATE 99

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During Technical Specification reviews, it was discovered that a surveillance test did not exist to test the carbon dioxide heat detectors in 19 safety-related rooms. A special test was used at the time (Nov. 2, 1982) to satisfy T.S.4.3.7.9. On July 8, 1983, it was discovered that the late date of May 2, 1983, was not adhered to. This is a final report. There has been no effect on the health and safety of the public nor did this condition constitute a threat to plant safety.

SYSTEM CODE A B		CAUSE CODE D	CAUSE SUBCODE Z	COMPONENT CODE I N S T R U				COMP. SUBCODE E	VALVE SUBCODE Z
11		12	13	14				15	16
9 10		11	12	13 14 15 16 17 18				19	20
EVENT YEAR 8 3		SEQUENTIAL REPORT NO. 0 8 9	OCCURRENCE CODE Q 3		REPORT TYPE X		REVISION NO. 1		
21 22		23 24 25 26	27 28 29		30 31		32		
ACTION TAKEN G	FUTURE ACTION Z	EFFECT ON PLANT Z	SHUTDOWN METHOD Z	HOURS 0 0 0 0		ATTACHMENT SUBMITTED N	NPRD-4 FORM SUB. N	PRIME COMP. SUPPLIER A	
17	18	19	20	22		23	24	25	
33	34	35	36	37 38 39 40		41	42	43	
COMPONENT MANUFACTURER F 0 8 0									
44		45 46 47 48		49 50 51 52		53 54 55 56		57	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Due to delays with the ongoing Surv. Review Program, the new procedure

11 was not issued until after the late date. The procedure was issued

12 on 7/20/83 and was completed successfully on September 12, 1983. An

13 hourly fire watch was in effect until completion of the surveillance

14 procedure.

7 8 9
FACILITY STATUS 1 5 0 28
% POWER 0 0 0 28 NA
OTHER STATUS 30
METHOD OF DISCOVERY A 31
DISCOVERY DESCRIPTION 32
Technical Specification Review

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)

1 6 7 8 9 10 11 NA

LOCATION OF RELEASE (36)

NA

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	37	2	38	NA	

PERSONNEL INJURIES		DESCRIPTION (41)	
NUMBER			
1	8	0	0
7	8	9	11
			12

IE22

LOSS OF OR DAMAGE TO FACILITY (43)
TYPE DESCRIPTION
1 9 2 42 NA
7 8 9 10
S PDR

[illegible]

NAME OF PREPARER D. E. Cathey

PHONE:

NRC USE ONLY

91 Y-026



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

October 5, 1983

NUCLEAR PRODUCTION DEPARTMENT

U. S. Nuclear Regulatory Commission
Region II
101 Marietta St., N.W., Suite 2900
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station
Unit 1
Docket No. 50-416
License No. NPF-13
File 0260/L-835.0
Update Report - CO₂ Heat
Detector's Surveillance
Performed Late
LER 83-089/03 X-1
AECM-83/0635

This is an update to a previous report submitted on August 8, 1983. The event for which the report was submitted occurred on July 8, 1983, when it was discovered that the surveillance for the carbon dioxide (CO₂) heat detectors in 19 safety-related rooms was not performed by its late date of May 2, 1983. The surveillance is required to satisfy Technical Specification 4.3.7.9.

All corrective action related to LER 83-089 is complete. Attached is LER 83-089/03 X-1, which is a final report.

Yours truly,

L. F. Dale

for L. F. Dale
Manager of Nuclear Services

EBS/SHH:sap
Attachment

cc: (See Next Page)

MISSISSIPPI POWER & LIGHT COMPANY

AECM-83/0635

Page 2

cc: Mr. J. B. Richard (w/a)
Mr. R. B. McGehee (w/o)
Mr. T. B. Conner (w/o)
Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a)
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Document Control Desk (w/a)
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555