

## LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 P A T M I 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 50

CON'T

0 1 REPORT SOURCE L 6 0 5 0 0 0 2 8 9 7 0 8 2 3 8 3 8 0 9 2 2 8 3 9  
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 On August 23, 1983 while attempting to isolate a condenser vacuum leak a valve  
0 3 was inadvertently closed which shutoff flow to RM-A5 (condenser exhaust monitor).  
0 4 Steam generators were not being steamed and there was no detectable gas activity  
0 5 on the secondary side. This event is considered reportable per Tech. Spec.  
0 6 6.9.2.B.2. Public health and safety were unaffected.  
0 7

0 8 9

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
7 8 9 10 11 12 13 14 15 16  
B B 11 A 12 B 13 Z Z Z Z Z Z 14 Z 15 Z 16  
17 LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.  
21 22 23 24 25 26 27 28 29 30 31 32  
8 3 0 1 9 0 3 L 0  
ACTION TAKEN FUTURE ACTION EFFECT ON FLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47  
H 19 Z 19 Z 20 Z 21 0 0 0 0 Y 23 N 24 Z 25 Z 9 9 9 26

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Individuals performing leak checks did not realize RM-A5 had been isolated.  
1 1 Approximately 40 minutes later error was corrected and sample flow restored to  
1 2 RM-A5. Individuals involved were instructed on necessary precautions when  
1 3 troubleshooting equipment and a need for appropriate communications with the  
1 4 Control Room.

1 5 FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
X 28 0 0 0 29 NRC Order B 31 Operator Observation

1 6 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
Z 33 Z 34 N/A N/A

1 7 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
0 0 0 37 Z 38 N/A

1 8 PERSONNEL INJURIES NUMBER DESCRIPTION (41)  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
0 0 0 40 N/A

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
Z 42 N/A

2 0 PUBLICITY ISSUED DESCRIPTION (45)  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
N 44

8310200061 830922  
PDR ADOCK 05000289  
S PDR

NRC USE ONLY

NAME OF PREPARER R. A. Szczech

PHONE (717) 948-8833

RM-A5 Isolated

I. Current Activities at the Time of the Occurrence

TMI-1 was preparing to heat up for steam generator testing following long term cold shutdown. Condenser vacuum was established.

II. Circumstances Leading to the Occurrence

On August 23, 1983, a Startup Engineer and an I&C Technician were leak-checking a newly installed gas sampling panel while condenser vacuum was established.

III. Description

At approximately 1355, in attempting to isolate a vacuum leak on the associated sample panel, the individuals closed a valve which also shut off flow to RM-A5 (condenser exhaust monitor). The individuals had not notified the Control Room and did not realize that they had isolated RM-A5. The error was realized approximately 40 minutes later, and flow was re-established to RM-A5. Since RM-A5 is required to be operable when condenser vacuum is established, this event is considered reportable in accordance with Technical Specification 6.9.2.B.2

IV. Resultant Events

No resultant events occurred, since the steam generators were not being steamed, and there was essentially no gas activity on either the secondary or the primary side, due to the long term cold shutdown.

V. Previous Events of a Similar Nature

None.

VI. Root Cause

The root cause is personnel error in failing to realize the consequences of their action and in failing to communicate their actions to the Control Room.

VII. Immediate Corrective Action

Flow was restored to RM-A5 after approximately 40 minutes

VIII. Long Term Corrective Action

The individuals involved were counseled and all I&C personnel were instructed on the importance of communications with the Control Room and the requirement for taking care when troubleshooting equipment.

A memo describing the circumstances surrounding the event was issued to all maintenance foreman who discussed the incident and its causes with their personnel. This memo was also issued to the Manager of Startup and Test who instructed his personnel on the need to coordinate valve operations and evolutions with the Control Room.

IX. Component Failure Data

None



GPU Nuclear Corporation  
Post Office Box 480  
Route 441 South  
Middletown, Pennsylvania 17057-0191  
717 944-7621  
TELEX 84-2386  
Writer's Direct Dial Number:

September 22, 1983  
5211-83-261

Dr. T. E. Murley  
Region I, Regional Administrator  
U. S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406

Dear Sir:

Three Mile Island Nuclear Station, Unit 1 (TMI-1)  
Operating License No. DPR-50  
Docket No. 50-289  
LER 83-019/03L-0

This letter transmits Licensee Event Report 83-019/03L-0 concerning inadvertent isolation of condenser exhaust monitor. Public health and safety were unaffected.

Sincerely,

A handwritten signature in dark ink, appearing to read "H. D. Hukill for".

H. D. Hukill  
Director, TMI-1

HDH:RAS:vjf

Enclosures

cc: R. Conte  
Document Management Branch

IE22  
11