

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 FL S L S 2 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
7 3 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 38

01 REPORT SOURCE L 5 0 5 0 0 0 3 8 9 7 0 1 9 0 7 8 3 3 1 0 0 7 8 3 3  
7 3 30 DOCKET NUMBER 38 39 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While in Mode 4, Hot Shutdown, with the "2B" Shut Down Cooling (SDC) train  
03 in operation and the "2A" SDC train in the injection mode and the "B" loop  
04 Reactor Coolant Pumps (RCPs) inoperable, the "A" loop RCPs were made  
05 inoperable. This is not in accordance with T.S. 3.4.1.3. This condition  
06 was rectified within 24 hours. This is the first occurrence of this type.  
07 The health and safety of the public were not in jeopardy.  
08

09 C F 11 A 12 A 13 C K T B R K 14 A 15 Z 16  
7 3 9 EVENT CODE 10 CAUSE CODE 11 CAUSE SUBCODE 12 COMPONENT CODE 13 COMP. SUBCODE 14 VALVE SUBCODE 15  
17 LER/RO REPORT NUMBER 18 3 21 22 23 24 25 26 27 28 29 30 31 32  
ACTION TAKEN 33 FUTURE ACTION 34 EFFECT ON PLANT 35 SHUTDOWN METHOD 36 HOURS 37 ATTACHMENT SUBMITTED 38 NPD-4 FORM SUB. 39 PRIME COMP SUPPLIER 40 COMPONENT MANUFACTURER 41  
H 19 Z 19 Z 20 Z 21 0 0 0 0 0 0 N 23 N 24 N 25 W 1 2 1 1 25

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Upon investigation it was discovered that the "A" loop RCPs were  
11 erroneously racked out. Upon noticing the SDC/RCP combination the "A"  
12 RCPs were immediately racked back in. The operators have been counseled  
13 as to the importance of adhering to the T.S.  
14

15 G 13 0 0 0 0 19 NA 30 A 31 Operator Observation  
7 3 9 FACILITY STATUS 10 % POWER 11 OTHER STATUS 12 METHOD OF DISCOVERY 13 DISCOVERY DESCRIPTION 14

15 Z 33 Z 34 NA 35 NA 36  
7 3 9 ACTIVITY CONTENT 10 RELEASED OF RELEASE 11 AMOUNT OF ACTIVITY 12 LOCATION OF RELEASE 13

17 0 0 0 37 Z 38 NA 39  
7 3 9 PERSONNEL EXPOSURES 10 NUMBER 11 TYPE 12 DESCRIPTION 13

18 0 0 0 40 NA 41  
7 3 9 PERSONNEL INJURIES 10 NUMBER 11 DESCRIPTION 12

19 Z 42 NA 43  
7 3 9 LOSS OF OR DAMAGE TO FACILITY 10 TYPE 11 DESCRIPTION 12

20 N 44 NA 45  
7 3 9 PUBLICITY 10 ISSUED 11 DESCRIPTION 12

NAME OF PREPARER J. P. Brannin

PHONE: (305) 465-3550 (x3427)



October 7, 1983  
PNS-LI-83-650

Mr. James P. O'Reilly  
Regional Administrator, Region II  
U. S. Nuclear Regulatory Commission  
101 Marietta Street N.W., Suite 2900  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 389-83-56

ST. LUCIE UNIT 2

DATE OF OCCURRENCE: SEPTEMBER 7, 1983

TECHNICAL SPECIFICATION 3.4.1.3

SHUTDOWN COOLING

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30-day notification of the subject occurrence.

Very truly yours,

J. W. Williams, Jr.  
Vice President  
Nuclear Energy

JWW/PLP/js

Attachment

cc: Director, Office of Inspection and Enforcement (30)  
Harold F. Reis, Esquire  
File 933.1 SL

83 OCT 12 PM 12:54

U.S. NRC REG.-II  
Atlanta, Ga.

OFFICIAL COPY

TE 22 11