

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N Y R E G 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 58

CON'T  
0 1 REPORT SOURCE L 6 0 5 0 0 0 2 4 4 7 0 9 1 6 8 3 8 1 0 2 6 8 3 9  
80 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
0 2 While reducing power per Operating Procedure 0-2.1, a trip occurred from 17% power  
0 3 resulting in violations of Technical Specifications 3.1.1.1a and 3.1.1.1c. The  
0 4 load reduction was in response to a Limiting Condition of Operation (Boric Acid  
0 5 Storage Tanks less than 12 wt. percent)(LER# 83-026). There was no threat to  
0 6 public health or safety.

0 7  
0 8  
0 9  
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
Z Z 11 A 12 A 13 X X X X X X 14 Z 15 Z 16  
LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.  
8 3 0 2 7 0 3 L 0  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
H 18 H 19 Z 20 C 21 0 0 2 7 Y 23 N 24 N 25 Z 9 9 9 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
1 0 The Operator, in the process of reducing load to minimum prior to manually removing  
1 1 the unit from the line arrived at a procedural point of switching auxiliary  
1 2 electrical loads. He lost his place on the procedure and inadvertently opened a  
1 3 switch from the unit transformer to the 11A bus before X-tying the bus to incoming  
1 4 feed via 12A bus. Several 4160V motors tripped including the "A" Reactor Coolant

(Continued on next page)  
FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)  
1 5 D 28 0 1 7 29 N/A A 31 Operator Observation  
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)  
1 6 Z 33 Z 34 N/A  
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)  
1 7 0 0 0 37 Z 38 N/A  
PERSONNEL INJURIES NUMBER DESCRIPTION (41)  
1 8 0 0 0 40 N/A  
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)  
1 9 Z 42 N/A  
PUBLCITY ISSUED DESCRIPTION (45)  
2 0 N 44 N/A

8310250217 831006  
PDR ADOCK 05000244  
S PDR

Everett J. Beatty

IE22

PHONE 315-524-4446 Ext. 300

Cause Description and Corrective Actions (cont'd)

Pump (RCP) and "A" main feed pump (MFWP). With both feed pump breakers open a turbine trip occurred (no reactor trip with power less than 50%). The reactor trip occurred due to low low steam generator level in the "B" Loop. The switching error resulted in a loss of one RCP (Technical Specification 3.1.1.1a) and the loss of the MFWP resulted in the low low level in the "B" steam generator (Technical Specification 3.1.1.1c).

The Operator and the Shift Supervisor were requested to attend a meeting with Operations Supervision where it was established that closer attention to operating procedures is strongly recommended.



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

JOHN E. MAIER  
Vice President

October 6, 1983

TELEPHONE  
AREA CODE 716 548-2700

Dr. Thomas E. Murley, Regional Administrator  
U.S. Nuclear Regulatory Commission  
Region I  
631 Park Avenue  
King of Prussia, PA 19406

Subject: LER 83-027/03L, A Unit Trip due to Personnel Error  
Resulting in a Loss of Reactor Coolant Loops with  
the Reactor Coolant System Temperature greater than  
350°F  
R.E. Ginna Nuclear Power Plant, Unit No. 1  
Docket No. 50-244

Dear Dr. Murley,

In accordance with Technical Specifications, article 3.1.1.1a (when the reactor power is above 130 MWT, both Reactor Coolant Pumps and associated steam generators and Reactor Coolant Pumps shall be in operation), and article 3.1.1.1c (when the average coolant temperature is above 350°F, or when the reactor is at hot shutdown or critical with power less than 130 MWT, at least one coolant loop and associated steam generator and Reactor Coolant Pump shall be in operation), the attached Licensee Event Report LER 83-027/03L-0 is hereby submitted.

Very truly yours,

*John E. Maier*  
John E. Maier

Attachment

xc: Document Control Desk (1)

IE22  
1/1