



**GPU Nuclear Corporation**  
Post Office Box 388  
Route 9 South  
Forked River, New Jersey 08731-0388  
609 971-4000  
Writer's Direct Dial Number:

December 15, 1994  
C321-94-2308

U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, DC 20555


Dear Sir:

Subject: Oyster Creek Nuclear Generating Station  
Docket No. 50-219  
Licensee Event Report

Enclosed is Licensee Event Report 94-021.

If you should have any questions or require further information, please contact Mr. Terry Sensue, Oyster Creek Licensing Engineer at 609-971-4680.

Sincerely yours,

  
John J. Barton  
Vice President and Director  
Oyster Creek

9412230053 941215  
PDR ADDCK 05000219  
S PDR

JJB/TS:jc  
Enclosure

cc: Administrator, Region I  
Senior Resident Inspector  
Oyster Creek NRC Project Manager

220014

GPU Nuclear Corporation is a subsidiary of General Public Utilities Corporation

TE22  
11

**LICENSEE EVENT REPORT (LER)**

U.S. NUCLEAR REGULATORY COMMISSION  
APPROVED BY OMB NO. 3150-0104  
EXPIRES 5/31/95

FACILITY NAME (1)

Oyster Creek, Unit 1

DOCKET NUMBER (2)

05000219

PAGE (3)

1 OF 4

TITLE (4)

AUTOMATIC REACTOR SCRAM DUE TO HIGH REACTOR RECIRCULATION FLOW CAUSED BY PERSONNEL ERROR

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
11	19	94	94	021	0	12	15	94	FACILITY NAME	DOCKET NUMBER
OPERATING MODE (9)		N		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more) (11)						
POWER LEVEL (10)				20.402(b)		20.405(c)		<input checked="" type="checkbox"/> 50.73(a)(2)(iv)		73.71(b)
				20.405(a)(1)(i)		50.36(c)(1)		50.73(a)(2)(v)		73.71(c)
				20.405(a)(1)(ii)		50.36(c)(2)		50.73(a)(2)(vii)		OTHER
				20.405(a)(1)(iii)		50.73(a)(2)(i)		50.73(a)(2)(viii)(A)		Specify in Abstract below and in Text, NRC Form 366A
				20.405(a)(1)(iv)		50.73(a)(2)(ii)		50.73(a)(2)(viii)(B)		
				20.405(a)(1)(v)		50.73(a)(2)(iii)		50.73(a)(2)(x)		

LICENSEE CONTACT FOR THIS LER (12)

NAME

TOD FENTON - SYSTEM ENGINEER

TELEPHONE NUMBER (Include Area Code)

609-971-4044

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE).	<input checked="" type="checkbox"/> NO
---	--

EXPECTED SUBMISSION DATE (15)

MONTH DAY YEAR

ABSTRACT (16)

On November 19, 1994, during a refueling outage, an unexpected reactor scram occurred. While performing troubleshooting and a wiring repair on the Reactor Recirculation Flow Control System computer, an inadvertent introduction of a low speed demand succeeded by a high speed demand from the digital control system (DCS) led to total recirculation flow exceeding the high flow scram setpoint.

The cause of this event was personnel error due to misoperation of the DCS computer.

There is no safety significance to this event. The high flow scram feature was believed necessary to terminate a flow increase transient during power operation. GPUN has since proved that this limiting safety system setting is not necessary and has obtained NRC approval to remove this feature from the technical specifications.

Interim corrective action has been taken to ensure DCS maintenance activities have technical support and supervising personnel present during such activities. Also, the conduct of maintenance activities will be proceduralized to help minimize misoperation/misapplication of the DCS diagnostic tools.

**LICENSEE EVENT REPORT (LER)**  
TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION  
APPROVED BY OMB NO. 3150-0104  
EXPIRES 5/31/95

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
Oyster Creek, Unit 1	05000219	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 OF 4
		94	021	0	

**DATE OF OCCURRENCE**

This event occurred on November 19, 1994 at 1923 hours.

**IDENTIFICATION OF OCCURRENCE**

In the process of performing troubleshooting and a wiring repair of a computer (EIS-DCC) watchdog circuit, an unexpected reactor scram occurred. This event is reportable based on 10 CFR 50.73(a)(2)(iv).

**CONDITIONS PRIOR TO OCCURRENCE**

A refueling outage was in progress. The reactor mode switch was in the SHUTDOWN position with all control rods fully inserted. Reactor coolant temperature was 185°F and the reactor vessel was vented. All five reactor recirculation system (EIS-AD) pumps were running in preparation to perform the Nuclear Steam Supply System (NSSS) leak test.

**DESCRIPTION OF OCCURRENCE**

On November 19, 1994, Instrument and Control (I&C) technicians were assigned to troubleshoot and repair a wiring problem in the transfer of control logic (TOCL) circuit of the newly installed digital reactor recirculation flow control system (DCS)(EIS-JA). DCS primary computer DCC-X was in control maintaining each recirculation pump speed at 35Hz. DCS backup computer DCC-Y was in the off-line diagnostic mode and being used as an aid in the troubleshooting activity.

While wiring repairs were in progress, the DCC-X computer tripped into the inactive mode. This transferred the recirculation pumps speed control to the Moore controllers (EIS-SIK). This transfer was not noticed by either the Control Room Operators (CRO) or the technicians due to the bumpless nature of the control transfer function. The CRO also misinterpreted that the dual computer failure alarm was caused by the ongoing maintenance activity and had no potential affect on recirculation pump operation.

In order to support the NSSS leak test, a CRO adjusted the master recirculation flow controller (MRC) to 40Hz to increase recirculation pump speed to increase the reactor vessel temperature.

**LICENSEE EVENT REPORT (LER)**  
TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION  
APPROVED BY OMB NO. 3150-0104  
EXPIRES 5/31/95

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Oyster Creek, Unit 1	05000219	94	021	0	3 OF 4

**DESCRIPTION OF OCCURRENCE**

(Continued)

While performing the post maintenance testing on the wiring repairs, the backup DCC-Y computer was inadvertently placed in control since the primary DCC-X computer had tripped. With the DCC-Y computer still being in the off-line diagnostic mode, normal control features were not in effect. A signal was sent to all the recirculation pumps to decrease speed to 35Hz. 35Hz was the last value retained by the computer before being taken off-line.

To support the NSSS leak test, the CRO made several attempts to adjust the speed back to 40Hz. These attempts were unsuccessful because DCC-Y was controlling in the off-line diagnostic mode.

The off-line diagnostic mode was exited on DCC-Y. This action led to a low speed demand of near zero Hz, succeeded by high speed demand of 40Hz which was previously set on the MRC by the CRO. This large error signal caused an overshoot of recirculation pump speed which resulted in total recirculation flow exceeding the high flow scram setpoint. The CRO attempted to reduce pump speed when it was recognized that 40Hz was being exceeded but this action was not taken soon enough to prevent the scram signal from being generated.

Immediately following the reactor scram, the CRO placed all five individual recirculation pump speed controllers in MANUAL and adjusted all speeds to approximately 34Hz. The reactor scram signals were reset, the DCS maintenance activities were halted, and the reactor vessel heatup process was continued to support the NSSS leak test.

**APPARENT CAUSE OF OCCURRENCE**

The cause of this event is attributed to personnel error due to misoperation of the DCS computers. DCC-X was not realized to be in the tripped condition and DCC-Y was allowed to control recirculation pump speed while in the off-line diagnostic mode. This lead to an inadvertent introduction of a large process error which increased recirculation flow to the high flow scram setpoint of 115% of rated.

**LICENSEE EVENT REPORT (LER)**  
TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION  
APPROVED BY OMB NO. 3150-0104  
EXPIRES 5/31/95

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Oyster Creek, Unit 1	05000219	94	021	0	4 OF 4

**ANALYSIS OF OCCURRENCE AND SAFETY ASSESSMENT**

The high recirculation flow scram feature was provided to terminate a flow increase transient during power operation. Flow transients are normally protected against by employing the  $k_f$  factor and using mechanical stops on the recirculation pumps. Oyster Creek does not have mechanical stops on its recirculation pumps and maximum flow was believed to be beyond the limit for which the  $k_f$  factor provides protection. Thus this scram feature took the place of mechanical stops on the speed controller scoop tubes to limit the recirculation pump flow. GPUN previously performed a calculation to determine the maximum achievable total recirculation flow during power operations. This calculation revealed that the technical specification limiting safety system setting for the high flow scram setpoint could not be reached with all recirculation pumps running at maximum flow during power operations. GPUN prepared a technical specification change request, submitted it to the NRC, and it has recently been approved deleting the high recirculation flow scram setpoint.

Since the plant was shutdown with all control rods fully inserted, and the reactor coolant temperature was below 212°F with the reactor vessel vented, this event had no safety significance.

**CORRECTIVE ACTIONS**

Immediately following the reactor scram, the CRO placed all five individual recirculation pump speed controllers in MANUAL and adjusted all speeds to approximately 34Hz. The reactor scram signals were reset, the DCS maintenance activities were halted, and the reactor vessel heatup process was continued to support the NSSS leak test.

An interim action has placed increased administrative controls over all maintenance activities on the DCS. This includes ensuring that expert technical support and supervising personnel are present during such activities.

Development of a detailed maintenance procedure has been initiated. This will include prerequisites, precautions and limitations, and instructions to control the maintenance activities which will minimize the potential for personnel error from misoperation/misapplication of the DCS diagnostic tools.

Also, since the high flow scram feature has recently been removed from our technical specifications, a modification will be performed to remove this function from the active control circuitry.

**SIMILAR EVENTS**

None