

The Light company

Houston Lighting & Power South Texas Project Electric Generating Station P. O. Box 289 Wadsworth, Texas 77483


June 25, 1991
ST-HL-AE-3803
File No.: G26
10CFR50.73

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, DC 20555

South Texas Project Electric Generating Station
Unit 1
Docket No. STN 50-498
Licensee Event Report 91-017 Regarding
Control Room Ventilation Actuation to Recirculation
Mode Due to a Spurious Signal from a Toxic Gas Analyzer

Pursuant to 10CFR50.73, Houston Lighting & Power Company (HL&P) submits the attached Licensee Event Report (LER 91-017) regarding a control room ventilation actuation to the recirculation mode due to a spurious signal from a toxic gas analyzer. The safety systems performed as designed and the event did not have any adverse impact on the health and safety of the public.

If you should have any questions on this matter, please contact Mr. C. A. Ayala at (512) 972-8628 or myself at (512) 972-7205.


for William J. Jump
Manager,
Nuclear Licensing

KT/sgt

Attachment: LER 91-017 (South Texas, Unit 1)

IF22
11

Houston Lighting & Power Company
South Texas Project Electric Generating Station

ST-HL-AE-3803
File No.: G26
Page 2

cc:

Regional Administrator, Region IV
Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76011

George Dick, Project Manager
U.S. Nuclear Regulatory Commission
Washington, DC 20555

J. I. Tapia
Senior Resident Inspector
c/o U. S. Nuclear Regulatory
Commission
P. O. Box 910
Bay City, TX 77414

J. R. Newman, Esquire
Newman & Holtzinger, P.C.
1615 L Street, N.W.
Washington, DC 20036

D. E. Ward/T. M. Puckett
Central Power and Light Company
P. O. Box 2121
Corpus Christi, TX 78403

J. C. Lanier/M. B. Lee
City of Austin
Electric Utility Department
P.O. Box 1088
Austin, TX 78767

R. J. Costello/M. T. Hardt
City Public Service Board
P. O. Box 1771
San Antonio, TX 78296

Rufus S. Scott
Associate General Counsel
Houston Lighting & Power Company
P. O. Box 61867
Houston, TX 77208

INPO
Records Center
1100 Circle 75 Parkway
Atlanta, GA 30339-3064

Dr. Joseph M. Hendrie
50 Bellport Lane
Bellport, NY 11713

D. K. Lacker
Bureau of Radiation Control
Texas Department of Health
1100 West 49th Street
Austin, TX 78756-3189

Revised 01/29/91

L4/NRC/

LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) South Texas, Unit 1										DOCKET NUMBER (2) 0 5 0 0 0 4 9 8										PAGE (3) 1 OF 14					
TITLE (4) Control Room Ventilation Actuation of Recirculation Mode Due to a Spurious Signal from a Toxic Gas Analyzer																									
EVENT DATE (5)			LER NUMBER (6)				REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)															
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES					DOCKET NUMBER(S)											
0	5	2	6	9	1	9	1	0	1	7	0	0	0	6	2	5	9	1	0	5	0	0	0		
OPERATING MODE (9)		1		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5. (Check one or more of the following) (11)																					
POWER LEVEL (10)		1100		20.402(b)				20.406(c)				<input checked="" type="checkbox"/> 50.73(a)(2)(iv)				73.71(b)									
				20.406(a)(1)(i)				50.36(a)(1)				<input type="checkbox"/> 50.73(a)(2)(v)				73.71(c)									
				20.406(a)(1)(ii)				50.36(a)(2)				<input type="checkbox"/> 50.73(a)(2)(vi)				OTHER (Specify in Abstract below and in Text, NRC Form 366A)									
				20.406(a)(1)(iii)				50.73(a)(2)(i)				<input type="checkbox"/> 50.73(a)(2)(viii)(A)													
				20.406(a)(1)(iv)				50.73(a)(2)(ii)				<input type="checkbox"/> 50.73(a)(2)(viii)(B)													
				20.406(a)(1)(v)				50.73(a)(2)(iii)				<input type="checkbox"/> 50.73(a)(2)(ix)													
LICENSEE CONTACT FOR THIS LER (12)												TELEPHONE NUMBER													
NAME Charles Ayala - Supervising Licensing Engineer												AREA CODE 5 1 2 9 7 2 - 8 6 2 8													
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																									
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC						
SUPPLEMENTAL REPORT EXPECTED (14)												EXPECTED SUBMISSION DATE (15)													
YES (If yes, complete EXPECTED SUBMISSION DATE)												<input checked="" type="checkbox"/> NO													

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single space typewritten lines) (16)

On May 26, 1991, Unit 1 was in Mode 1 at 100 percent power. At 1534 hours, the control room ventilation system actuated to the recirculation mode as a result of a spurious trip from a toxic gas analyzer. The exact cause of the event could not be determined but has been attributed to poor electrical connection on one or more plug-in integrated circuit chips in the analyzer. Corrective actions include troubleshooting of the failed analyzer, further design improvements to minimize false actuation signals, and development of preventive maintenance tasks to periodically reseal integrated circuit chips in the toxic gas analyzers.

LER\91161002.U1

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503

FACILITY NAME (1) South Texas, Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 4 9 8	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		9 1	0 1 7	0 0	0 2	OF 0 4

TEXT (If more space is required, use additional NRC Form 366A's) (17)

DESCRIPTION OF EVENT:

On May 26, 1991, Unit 1 was in Mode 1 at 100 percent power. At 1534 hours, an automatic actuation of the control room ventilation to recirculation mode occurred as a result of a spurious signal from one of two toxic gas analyzers (XE-9326). Control room ventilation actuation to recirculation mode is an Engineered Safety Feature (ESF). An investigation was initiated and the recirculation mode damper lineup was verified. The NRC was notified of the unanticipated ESF actuation at 1704 hours on May 26, 1991.

There were no personnel working on or around the toxic gas analyzers when the actuation occurred. The Emergency Response Facility Data Acquisition and Display System (ERFDADS) computer display showed an extremely high concentration of vinyl acetate (on the order of 10^{34} ppm) which is indicative of an electronic failure. Approximately seven minutes after the actuation occurred, the analyzer stopped communicating with ERFDADS which is also indicative of an electronic failure.

The toxic gas analyzers consist of a microprocessor-based spectrographic analyzer cell which communicates electronically with a maintenance terminal (or ERFDADS) and an interface circuit board which operates peripheral devices such as sample solenoid valves and output relays. A manufacturer representative arrived on site May 29, 1991 to assist with cause determination and to rework the analyzer. The exact cause could not be determined, but based upon field experience, the manufacturer representative concluded that the erratic operation was caused by poor electrical connection on one or more plug-in integrated circuit (IC) chips. The IC chips were reseated to restore any degraded connections in the four analyzers at the South Texas plant (two in each unit). No failures or erratic operation have since been observed.

CAUSE OF EVENT:

The ESF actuation was caused by a spurious signal from a single toxic gas analyzer. The exact cause of the spurious signal could not be conclusively determined but has been attributed to poor electrical connection on one or more plug-in integrated circuit chips.

ANALYSIS OF EVENT:

Unplanned actuation of an Engineered Safety Feature is reportable pursuant to 10CFR50.73(a)(2)(iv). There were no adverse radiological or safety consequences as a result of the event. The control room ventilation system

LER\91161002.U1

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) South Texas, Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 4 9 8	LER NUMBER (4)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		9 1	0 1 7	0 0	0 3	OF 0 4

NOTE: If more space is required, use additional NRC Form 366A's (17)

ANALYSIS OF EVENT: (cont'd)

actuated to the recirculation mode as required. No toxic gas was determined to be present, and the event did not affect the normal operation of the unit.

While any unnecessary challenge to an Engineered Safety Feature is undesirable, actuation of the control room ventilation system to recirculation mode represents a minimal hazard since it could not cause, worsen, nor prevent mitigation of an accident.

CORRECTIVE ACTIONS:

The following corrective actions are being taken as a result of this event and two previous events which occurred in Unit 2 on May 16 and 21, 1991, reported as LER 91-006:

1. Analyzer XE-9236 was reworked and returned to service on May 30, 1991.
2. Management has approved modifications for both units which will replace and upgrade the Toxic Gas Monitoring System with State of the Art equipment. These modifications will enhance system reliability and minimize spurious ESF actuations caused by monitor anomalies. The implementation of the proposed design changes is being pursued as a high priority activity at STPEGS. Implementation of a portion of these design changes is predicated upon NRC approval of a Technical Specification change request which HL&P proposes to submit in August, 1991.
3. The integrated circuit chips have been reseated to restore any degraded connections in the four analyzers in both units.
4. Maintenance will develop preventive maintenance tasks to periodically reseat IC chips in the toxic gas analyzers. These PMs will be approved by July 30, 1991.

ADDITIONAL INFORMATION:

On October 26, 1990, a similar event, reported as LER 90-015, occurred in Unit 2 as a result of a spurious actuation from analyzer XE-9325. The cause of that event could not be conclusively determined but was attributed to failure of the analyzer's microprocessor interface circuit board. The circuit board was reworked and returned to service as a result of the event.

LER\91161002.U1

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)

DOCKET NUMBER (2)

LER NUMBER (6)

PAGE (3)

South Texas, Unit 1

0 5 0 0 0 4 9 8 9 1 0 1 7 0 0 0 4 OF 0 4

TEXT (If more space is required, use additional NRC Form 386A's) (17)

ADDITIONAL INFORMATION: (cont'd)

On May 16 and 21, 1991, two similar events, reported as LER 91-006, occurred in Unit 2 as a result of the spurious actuations from analyzer XE-9325. The cause of those events could not be conclusively determined but was attributed to poor electrical connection on one or more plug-in integrated circuit chips. The IC chips were reseated to restore any degraded connections in the four analyzers as a result of the events.

Several other events involving the toxic gas analyzers have been reported and corrective actions have been implemented to improve the reliability of the Foxboro Miran 981 Analyzers.

LER\91161002.U1