

## (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EV 1.7 DESCRIPTION AND PROBABLE CONSEQUENCES (10)

09		SYSTEM CODE S C		11	CAUSE CODE E		12	CAUSE SUBCODE A		13	COMPONENT CODE X X X X X X X						14	COMP. SUBCODE X		15	VALVE SUBCODE Z		16
7	8	9	10		11	12		12		13						18		19		20			
17		LER/RO REPORT NUMBER		EVENT YEAR 8 3		21	22	SEQUENTIAL REPORT NO. 1 3 6		24	25	26	OCCURRENCE CODE /		27	REPORT TYPE 0 3		28	29	REVISION NO. /		31	
33		ACTION TAKEN A		FUTURE ACTION Z		34	35	EFFECT ON PLANT Z		36	SHUTDOWN METHOD Z		37	HOURS 0 0 0		40	ATTACHMENT SUBMITTED Y		41	NPRD-4 FORM SUR N		42	
38		18		19		20		21		22		23		24		25		26		27		28	
39		40		41		42		43		44		45		46		47		48		49		50	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION

ACTIVITY		CONTENT		AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
1	6	Z	33		
				NA	NA

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION
7		
8		
9		
10		
11		
44		
45		
8		

[illegible]

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	2	0	0	0	NA

8401230201

7	8	9	11	12
LOSS OF OR DAMAGE TO FACILITY				(43)
TYPE DESCRIPTION				

1	9	Z	42	NA	PER
7	8	9	10		

ISSUED DESCRIPTION (45) NA

PHONE: (912) 367-7851

NARRATIVE REPORT  
FOR LER 50-366/1983-136

LICENSEE : GEORGIA POWER COMPANY  
FACILITY NAME : EDWIN I. HATCH  
DOCKET NUMBER : 50-366

Tech. Specs. section(s) which requires report:

This 30-day LER is required by Tech. Specs. section 5.9.1.9.b due to the event's showing that the unit was not meeting the requirements of Tech. Specs. section 3.6.6.1.

Plant conditions at the time of the event(s):

This event occurred on 12/13/83 with the reactor mode switch in the run position and reactor power at 2256 MWt (approximately 93%).

Detailed description of the event(s):

When plant personnel attempted to run the "2B" standby gas treatment fan (2T46-D001B) in order to vent the drywell, the fan tripped and would not restart. Further investigation revealed both the red and green indicating lights to be on when the fan switch was placed to run. Plant personnel attempted to clear the condition by resetting the breaker; however, this did not correct the problem. The "2B" standby gas treatment fan was declared inoperable.

Consequences of the event(s):

Plant operation was not affected by this event. The health and safety of the public were not affected by this event.

Status of redundant or backup subsystems and/or systems:

The "2A" standby gas treatment fan and the Unit 1 "1A" and "1B" standby gas treatment fans were operable.

Justification for continued operation:

Operation continued under a 7-day LCO as permitted by Tech. Specs. section 3.6.6.1, ACTION a.

If repetitive, number of previous LER:

This event is non-repetitive.

Narrative Report for LER 50-366/1583-136  
Page Two

Impact to other systems and/or Unit:

This event had no impact on any other Unit 2 system or on Unit 1.

Cause(s) of the event(s):

The cause of this event is component failure. The "2B" standby gas treatment fan (2T46-D001B) was inoperable due to a failed motor starter assembly.

Immediate Corrective Action:

The "2B" standby gas treatment fan motor starter was replaced with a new starter assembly. The "2B" standby gas treatment fan was then satisfactorily functionally tested per the "STANDBY GAS TREATMENT SYSTEM VENTILATION AND VALVE OPERABILITY" procedure (HNP-2-3655) and was returned to operable status on 12/16/83.

Supplemental Corrective Action:

There is no supplemental corrective action required.

Scheduled (future) corrective action:

There is no scheduled (future) corrective action required.

Action to prevent recurrence (if different from corrective actions):

N/A

Georgia Power Company  
Post Office Box 439  
Baxley, Georgia 31513  
Telephone 912 367-7781  
912 537-9444



Edwin I. Hatch Nuclear Plant


January 12, 1984  
GM-84-17

PLANT E. I. HATCH  
Licensee Event Report  
Docket No. 50-366

United States Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II  
Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303

ATTENTION: Mr. James P. O'Reilly

Attached is Licensee Event Report No. 50-366/1983-136. This report is required by Hatch Unit 2 Technical Specifications Section 6.9.1.9.b.

  
H. C. Nix  
General Manager

*TKS*  
HCN/SBT/djs

xc: R. J. Kelly  
G. F. Head  
J. T. Beckham, Jr.  
P. D. Rice  
K. M. Gillespie  
S. B. Tipps  
R. D. Baker  
Control Room  
Document Control

OFFICIAL COPY

IE 22  
1/1