

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 1 1 1 1 1 1 1
1 6

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[illegible]

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

VENT DESCRIPTION AND PROBABLE CONSEQUENCES TO
On 10/01/82, while in Mode 6, the emergency feedwater pump (EFP) turbine steam supply check valve (2MS-39B)
was disassembled for inspection. This inspection revealed internal damage. The disc stud was broken from
the disc and missing. The disc stud nut, washer, and locking pin were also missing. The counterpart valve
(2MS-39A) in the redundant steam supply line was inspected and revealed no damage. Isolation valve 2CV-1050
which is upstream of 2MS-39B was operable. This occurrence is reportable per Technical Specification (T.S.)
16.9.1.8.e and is similar to LER (50-358) 81-034.

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP SUBCODE		VALVE SUBCODE		REVISION			
0 9		H H 11		B 12		A 13 V A L V E X 14				C 15		A 16		NO			
7 8		9 10		11		12 13 18				19		20		21			
LER/RO 17 REPORT NUMBER	EVENT YEAR 8 2	---		SEQUENTIAL REPORT NO. 0 3 1				OCCURRENCE CODE /				REPORT TYPE X		REVISION NO 1			
	21 22	23		24 3 26				27 / 29				30		31 32			
ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS				ATTACHMENT SUBMITTED				NPRD-4 FORM SUB		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
C 18	Z 19	Z 20	Z 21	0 0 0 22				N 23				Y 24		A 25		A 3 9 5 26	
33	34	35	36	37 40				41				42		43		44 47	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

CHASE DESCRIPTION AND CORRECTIVE ACTIONS 27	
1	0
1	1
1	2
1	3
1	4

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	1	128	0	0	0	129	1	NA
7	8	9	10	11	12	13	14	15	16
ACTIVITY		CONTENT						Inservice Test Program	
								132	

ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
1	6	2	34	1	NA	1	NA
7	8	9	10	11		135	136
						44	45
							80

PERSONNEL EXPOSURES										44	45	80
NUMBER				TYPE		DESCRIPTION						
1	0	7		0	137	2	138	NA				
7	7	8		9	11	12	13				139	

PERSONNEL INJURIES										80	
NUMBER					DESCRIPTION						
1	8	0	0	0	140	NA					
7	8	9	11	12							141


LOSS OF OR DAMAGE TO FACILITY		80
TYPE	DESCRIPTION	
1 1 9	1 Z 142 NA	43

PUBLICITY									
ISSUED		DESCRIPTION							
1	2	0	1	1	N	144	1	NA	
7			8	9			10		
							145	NRC USE ONLY	
							68	69	80

NAME OF PREPARER: Phillip B. Wade

PHONE: (501) 964-3100

8401230254 840109
PDR ADCK 05000368
S PDR



ARKANSAS POWER & LIGHT COMPANY

POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

January 9, 1984


2CANØ184Ø5

Mr. J. E. Gagliardo, Director
Division of Resident Reactor Projects
and Engineering Programs
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76011

Subject: Arkansas Nuclear One - Unit 2
Docket No. 50-368
License No. NPF-6
Licensee Event Report
No. 82-031/01X-1

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specification 6.9.1.8.e, attached is the subject report concerning the emergency feedwater pump turbine steam supply check valve, 2MS-39B. This is a revision to a previous submittal dated October 13, 1982.

Very truly yours,

John R. Marshall
Manager, Licensing

JRM:RJS:s1

Attachment

cc: Mr. Richard C. DeYoung
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. Norman M. Haller, Director
Office of Management & Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

IE-29
111