

LICENSEE EVENT REPORT

CONTROL BLOCK: (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	C	B	E	P	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4		5																
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35																
LICENSEE CODE															LICENSE NUMBER										LICENSE TYPE										CAT 58									

0	1	L	6	0	5	0	-	0	3	2	5	7	1	2	1	2	8	3	8	0	1	1	1	8	4	9																		
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35																
REPORT SOURCE															DOCKET NUMBER										EVENT DATE										REPORT DATE									

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During unit power operation, while performing the loop calibration of RHR system flow

0 3 | monitoring instrumentation located on the remote shutdown panel, PT-55.8PC, it was dis-

0 4 | covered that RHR system flow indication signal converter I-E11-FY-3338 could not be

0 5 | calibrated due to a fluctuating instrument output signal. This event did not affect

0 6 | the health and safety of the public.

0 7 |

0 8 | Technical Specifications 3.3.5.2, 6.9.1.9b

0	9	I	C	11	E	12	E	13	I	N	S	T	R	U	14	Y	15	Z	16	8	3	0	5	0	0	3	L	0	0	0	0	N	Y	N	M	4	2	3							
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47					
LER/RO REPORT NUMBER		EVENT YEAR		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE								COMP. SUBCODE		VALVE SUBCODE		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.		ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | A cold solder joint, occurring where IC chip No. 5 connects to the FY-3338 integrated

1 1 | circuit board, caused the event. No other solder joint problems were found. The

1 2 | subject solder joint was repaired, the PT was satisfactorily completed, and FY-3338,

1 3 | Model No. SRT/4-20MA/1-5VDC/24VDC, was returned to service. No further action re-

1 4 | garding this event is planned.

1	5	E	28	0	9	6	29	NA	B	31	Periodic Test	32																																							
7	8	9	10	11	12	13	14	15	16	17	18	19																																							
FACILITY STATUS													OTHER STATUS													METHOD OF DISCOVERY													DISCOVERY DESCRIPTION												

1	6	Z	33	Z	34	NA	NA	NA	NA	35	36																								
7	8	9	10	11	12	13	14	15	16	17	18																								
ACTIVITY CONTENT												AMOUNT OF ACTIVITY												LOCATION OF RELEASE											

1	7	0	0	0	37	Z	38	NA	39										
7	8	9	10	11	12	13	14	15	16										
PERSONNEL EXPOSURES										DESCRIPTION									

1	8	0	0	0	40	NA	41												
7	8	9	10	11	12	13	14												
PERSONNEL INJURIES										DESCRIPTION									

1	9	Z	42	NA	43	NA	44												
7	8	9	10	11	12	13	14												
LOSS OF OR DAMAGE TO FACILITY										DESCRIPTION									

2	0	N	44	NA	45	NA	46												
7	8	9	10	11	12	13	14												
PUBLICATION										DESCRIPTION									

8401230283 840111
PDR ADOCK 05000325
S PDR

NRC USE ONLY

NAME OF PREPARER M. J. Pastva, Jr.

PHONE: 919-457-9521



Carolina Power & Light Company

Brunswick Steam Electric Plant
P. O. Box 10429
Southport, NC 28461-0429

January 11, 1984

FILE: B09-13510C
SERIAL: BSEP/84-0033

Mr. James P. O'Reilly, Administrator
U. S. Nuclear Regulatory Commission
Region II, Suite 3100
101 Marietta Street N.W.
Atlanta, GA 30303

BRUNSWICK STEAM ELECTRIC PLANT, UNIT NO. 1
DOCKET NO. 50-325
LICENSE NO. DPR-71
LICENSEE EVENT REPORT 1-83-50

Dear Mr. O'Reilly:

In accordance with Section 6.9.1.9b of the Technical Specifications for Brunswick Steam Electric Plant, Unit No. 1, the enclosed Licensee Event Report is submitted. This report fulfills the requirement for a written report within thirty (30) days of a reportable occurrence and is in accordance with the format set forth in NUREG-0161, July 1977.

Very truly yours,

C. R. Dietz, General Manager
Brunswick Steam Electric Plant

RMP/ag/LETJ03

Enclosure

cc: Mr. R. C. DeYoung
NRC Document Control Desk

OFFICIAL COPY

1022
11