



Consumers  
Power  
Company

James W Cook  
Vice President - Projects, Engineering  
and Construction

General Offices: 1945 West Parnall Road, Jackson, MI 49201 • (517) 788-0453

January 16, 1984

83-15 #1

Mr J G Keppler, Regional Administrator  
US Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, IL 60137

MIDLAND ENERGY CENTER PROJECT  
DOCKET NOS 50-329 AND 50-330  
NON-SEISMICALLY SUPPORTED COMPONENT COOLING WATER PIPING SYSTEM  
FILE: 0.4.9.87 SERIAL: 26665

On December 16, 1983, Consumers Power Company notified your staff of a potential 10CFR50.55(e) condition involving the attachment of non-Q/non-seismic piping to the component cooling water system.

This letter is an interim 10CFR50.55(e) report. The attachments to this letter describe the concern and summarize the investigation and corrective action taking place.

Another report, either interim or final, will be sent on or before April 20, 1984.

*James W. Cook*

JWC/AHB/lr

Attachments: (1) MCAR-1, Report No 79, dated December 19, 1983  
(2) MCAR-79, Interim Report 1, dated January 9, 1984

CC: Document Control Desk, NRC  
Washington, DC

RJCook, NRC Resident Inspector  
Midland Nuclear Plant

DHood, USNRC Office of NRR

INPO Records Center

8401230344 840116  
PDR ADOCK 05000329  
S PDR  
OC0184-0031A-MP01

JAN 18 1984

IE2711

OM/OL SERVICE LIST

Mr Frank J Kelley  
Attorney General of the  
State of Michigan  
Ms Carole Steinberg, Esq  
Assistant Attorney General  
Environmental Protection Division  
720 Law Building  
Lansing, MI 48913

Mr Myron M Cherry, Esq  
Suite 3700  
Three First National Plaza  
Chicago, IL 60602

Mr Wendell H Marshall  
RFD 10  
Midland, MI 48640

Mr Charles Bechhoefer, Esq  
Atomic Safety & Licensing  
Board Panel  
U S Nuclear Regulatory Commission  
Washington, DC 20555

Dr Frederick P Cowan  
6152 N Verde Trail  
Apt B-125  
Boca Raton, FL 33433

Mr Fred C Williams  
Isham, Lincoln & Beale  
1120 Connecticut Ave, NW, Suite 325  
Washington, DC 20036

Mr James E Brunner, Esq  
Consumers Power Company  
212 West Michigan Avenue  
Jackson, MI 49201

Mr D F Judd  
Babcock & Wilcox  
PO Box 1260  
Lynchburg, VA 24505

Mr Steve Gadler, Esq  
2120 Carter Avenue  
St Paul, MN 55108

OC0184-0031A-MP01

Atomic Safety & Licensing  
Appeal Board  
U S Nuclear Regulatory Commission  
Washington, DC 20555

Mr C R Stephens (3)  
Chief, Docketing & Services  
U S Nuclear Regulatory Commission  
Office of the Secretary  
Washington, DC 20555

Ms Mary Sinclair  
5711 Summerset Street  
Midland, MI 48640

Mr William D Paton, Esq  
Counsel for the NRC Staff  
U S Nuclear Regulatory Commission  
Washington, DC 20555

Atomic Safety & Licensing  
Board Panel  
U S Nuclear Regulatory Commission  
Washington, DC 20555

Ms Barbara Stamiris  
5795 North River Road  
Rt 3  
Freeland, MI 48623

Mr Jerry Harbour  
Atomic Safety & Licensing  
Board Panel  
U S Nuclear Regulatory Commission  
Washington, DC 20555

Mr M I Miller, Esq  
Isham, Lincoln & Beale  
Three First National Plaza  
52nd Floor  
Chicago, IL 60602

Mr John DeMeester, Esq  
Dow Chemical Building  
Michigan Division  
Midland, MI 48640

Ms Lynne Bernabei  
Government Accountability Project  
1901 Q Street, NW  
Washington, DC 20009

137660

Attachment  
Serial 26665  
83-15 #1QUALITY ASSURANCE PROGRAM  
**MANAGEMENT CORRECTIVE ACTION REPORT**

MCAR-1

REPORT NO. 79

JOB NO. 7220

Q NO.

DATE 12/19/83

**I\* DESCRIPTION (Including references):**

A potential deficiency has been identified concerning non-Q piping connected to Q-list equipment. Specifically, a condition exists where non-Q/non-seismically supported component cooling water piping is connected to Q-listed letdown coolers in the reactor building, as follows:

(continued)

**\* RECOMMENDED ACTION (Optional)**

- 1) Perform an evaluation to determine what impact this condition would have on the safety of operations at Midland if left uncorrected.
- 2) If, as a result of Item 1) above, the affected hardware is found to be nonconforming, initiate proper controls in accordance with project procedures for nonconforming items.

(continued)

REFERRED TO ☒ ENGINEERING ☐ CONSTRUCTION ☐ QA MANAGEMENT ☐☐ PROCUREMENT

\*\*This condition was reported to the NRC by the client as a potential 10 CFR-50.55(e) on 12/16/83.

ISSUED BY JECrooby 12/19/83  
for Project QA Engineer Date**II REPORTABLE DEFICIENCY**☐ NO☒ YES

NOTIFIED CLIENT

Project Manager

Date

Date

**III CAUSE**

CORRECTIVE ACTION TAKEN

AUTHORIZED BY \_\_\_\_\_

Date

## STANDARD DISTRIBUTION

DIVISION QA MANAGER  
MANAGER OF QA - BPC  
GPD - QA MANAGER  
LAPD QA MANAGER  
SFPD QA MANAGER  
PROJECT MANAGER  
CLIENT

## ADDITIONAL DISTRIBUTION - AS APPROPRIATE

ENGINEERING MANAGER  
PROJECT ENGINEER  
QE SUPERVISOR

CONSTRUCTION MANAGER  
PROJ SUPT/PROJ CONSTR MANAGER  
CHIEF CONSTR QC ENGINEER

DIVISION PROCURENT MGR  
PROJ PROCUREMENT MGR  
PROCUREMENT SUPPLIER QUALITY MGR AND  
DIV SUPPLIER QUALITY MGR

FORMAL REPORT TO CLIENT  
(If Section II Applies)

Date

CORRECTIVE ACTION IMPLEMENTED

VERIFIED BY \_\_\_\_\_

Project QA Engineer

Date

\* Describe in space provided and attach reference document.

137660

Description (continued):

<u>Unit Number</u>	<u>Line Number</u>	<u>Line Class</u>	<u>Equipment Number</u>	<u>Equipment Class</u>	<u>Reference Document</u>
Unit 1	6" 1HBD-448 thru 451	Non-Q	1E-57A&B	Q	H-616SH5(Q)
Unit 2	6" 2HBD-448 thru 451	Non-Q	2E-57A&B	Q	H-617SH1(Q)

Assuming a worst case condition, the possibility exists that the non-seismically supported component cooling lines connected to the letdown coolers could fail during a seismic event. If this piping were to collapse during an earthquake, significant loads would be transferred through the coolers and into the equipment support structure, possibly causing failure of the supports and collapse of the coolers. This occurrence would result in a subsequent failure of the safety related piping connected to the coolers, thereby possibly causing a breach of the reactor coolant pressure boundary.

Recommended Action (continued):

- 3) Perform a review to determine if similar conditions exist where non-Q systems are connected to safety related equipment.
- 4) If deficiencies are identified from Item 3) above, perform an evaluation to determine the impact on safety of operations, initiate proper controls for any hardware nonconformances in accordance with project NCR procedures.
- 5) Determine root cause of the design deficiency and provide corrective action to preclude recurrence.
- 6) Issue initial report, interim or final, by 1/3/83.

139455

## Bechtel Associates Professional Corporation

Attachment 2  
Serial 26665  
83-15 #1

SUBJECT: MCAR 79

139461

## INTERIM REPORT 1

DATE: January 9, 1984

PROJECT: Midland Plant Units 1 and 2  
Consumers Power Company  
Bechtel Job 7220Introduction

This report provides the status and course of corrective action required by Management Corrective Action Report (MCAR) 79.

Description of Deficiency

A condition exists where non-Q/nonseismically supported component cooling water (CCW) piping is connected to Q-listed letdown coolers in the reactor building.

The following lines are involved in this deficiency:

Unit	Line	Line Class	Equipment	Equip- ment Class	Reference Document (7220-)
1	6"-1HBD-448 through 451	Non-Q	1E-57A&B	Q	H-616, Sh 2
2	6"-2HBD-448 through 451	Non-Q	2E-57A&B	Q	H-617, Sh 4

Historical Background

During a design review and site walkdown, it was discovered that the CCW piping connected to the letdown coolers was not seismically supported and could impose unacceptable loading on the coolers.

Analysis of Safety Implications

Assuming the worst case, the cooler supports could fail, causing subsequent failure of the letdown line, a component of the reactor coolant boundary. Based on this assumption, the condition is reportable under 10 CFR 50.55(e).



# Bechtel Associates Professional Corporation

MCAR 79  
INTERIM REPORT 1

139455

139461

Page 1

## Probable Cause

The probable cause was failure to ensure compliance with equipment vendor nozzle load limitations at the interface between the non-Q-listed, noncritical, subcontractor (ITT Grinnell)-analyzed piping system and the Q-listed equipment nozzles.

## Corrective Action

1. If, as a result of the review, the affected hardware is found to be nonconforming, initiate proper controls in accordance with project procedures for nonconforming items. A nonconformance report is being issued to be attached to the affected coolers.
2. Perform a review to determine if similar conditions exist where non-Q-listed systems are connected to safety-related equipment and table corrective actions as required, based on findings.
3. Action(s) to preclude recurrence will be finalized in a later report.

## Reportability

This deficiency was reported to the NRC by Consumers Power Company as a potential violation of 10 CFR 50.55(e) on December 16, 1983.

Submitted by:

*mtb* *W.B./11*

*D. S. Lewis*  
E.B. Poser  
Project Engineering Manager

Approved by:

*BRK.*

*E. H. Smith*  
R.H. Smith  
Engineering Manager

Concurrence by:

*for*

*GE Crosby*  
M.A. Dietrich  
Project Quality Assurance  
Engineer