

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

☐ THE PROJECT HAS BEEN COMPLETED.

PHONE 616-465-5901

SUPPLEMENT TO LER # 83-125/03L-0

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

ONE (1) SAFETY RELATED FIRE DOOR WAS INTENTIONALLY MADE INOPERABLE TO PERFORM CORRECTIVE MAINTENANCE ON THE DOOR FRAME. THE WORK PERFORMED ON THE DOOR FRAME WAS DONE IN ORDER TO MEET CERTAIN REQUIREMENTS OF THE NATIONAL FIRE CODES. THE DOOR'S LATCHING SYSTEM WAS RENDERED INOPERABLE DURING THE CORRECTIVE MAINTENANCE. FIRE WATCHES WERE POSTED IN AFFECTED AREAS AS REQUIRED BY T.S. 3.7.10. SURVEILLANCE TEST PROCEDURE "12MHP4030.STP.027, "MAINTENANCE INSPECTION FOR FIRE DOORS PROTECTING SAFETY RELATED AREAS", WAS PERFORMED FOLLOWING REPAIRS AND PRIOR TO DECLARING THE DOOR OPERABLE. PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED.



INDIANA & MICHIGAN ELECTRIC COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106
(616) 465-5901

DMB

January 17, 1984

Mr. J.G. Keppler, Regional Administrator
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-58
Docket No. 50-315


Dear Mr. Keppler:

Pursuant to the requirements of the Appendix A Technical Specifications, the following report/s are submitted:

RO 83-125/03L-0

The submittal of this Licensee Event Report exceeds the 30 day reporting requirement. This delay was caused by an indepth review of this event in an effort to ensure proper classification and subsequent reportability.

Sincerely,


W.G. Smith, Jr.
Plant Manager

/cbm

Attachment

cc: John E. Dolan
M.P. Alexich
R.F. Kroeger
H. Brugger
E.R. Swanson, RO:III
R.C. Callen, MPSC
G. Charnoff, Esq.
J.M. Hennigan
R.O. Bruggee, EPRI
INPO
PNSRC
J.F. Stietzel
E.L. Townley
Dir., IE (30 copies)
Dir., MIPC (3 copies)

IE 22
11

JAN 19 1984