

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

PHONE: (205) 899-5156

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (Continued)

section of the approved procedure which caused him to misposition the pump inlet and bypass valves. Operations personnel noticed an abnormally low indication on radiation monitor R-11 and checks were made by health physics personnel on both the evening and night shifts. These checks verified proper pump operation but failed to verify inlet and bypass valve position. Upon discovery on day shift, the valve lineup was corrected and radiation monitor R-11 was returned to service at 0830 on 12/15/83. The personnel involved have been counseled.