

LICENSEE EVENT REPORT

CONTROL BLOCK:

1	2	3	4	5	6
---	---	---	---	---	---

 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1
---	---

M	S	G	G	S	1
---	---	---	---	---	---

2	0	0	-	0	0	0	0	0	0	-	0	0
---	---	---	---	---	---	---	---	---	---	---	---	---

3	4	1	1	1	1
---	---	---	---	---	---

4	5
---	---

7 8 9 14 15 25 26 30 57 CAT 58

CON'T

0	1
---	---

 REPORT SOURCE

L	6	0	5	0	0	0	4	1	6
---	---	---	---	---	---	---	---	---	---

7	1	2	0	6	8	2
---	---	---	---	---	---	---

8	0	1	0	5	8	2
---	---	---	---	---	---	---

9

7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | At 1610 on December 6, 1982, the temporary ventilation exhaust system for the

0 3 | suppression pool area was observed operating and discharging to atmosphere while it's

0 4 | CAM (Continuous Air Monitor) was not operating. Earlier on the same day the system

0 5 | had been shutdown by operations. This event is being reported pursuant to

0 6 | T.S.6.9.1.13.c. The event had no effect on the health and safety of the public and

0 7 | did not constitute a threat to plant safety.

0	8
---	---

7	8	0
---	---	---

 80

0	9
---	---

X	X
---	---

 (11)

A

 (12)

C

 (13)

I	N	S	T	R	U
---	---	---	---	---	---

 (14)

S

 (15)

Z

 (16)
7 8 9 10 11 12 13 18 19 20
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
(17) LER RO REPORT NUMBER

8	2
---	---

1	5	5
---	---	---

0	3
---	---

L

0

21 22 23 24 26 27 28 29 30 31 32
EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
H 18 Z 19 Z 20 Z 21 0 0 0 0 Y 23 N 24 L 25 E 0 7 0 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The event occurred due to personnel error. The temporary ventilation exhaust

1 1 | system was started without starting the CAM and without notifying the shift

1 2 | superintendent. The CAM was immediately placed into service upon discovery.

1 3 | Operations personnel have been appropriately instructed to prevent reoccurrence.

1	4
---	---

7	8	9
---	---	---

 80

1	5
---	---

G

 (28)

0	0	0
---	---	---

 (29)

NA

 (30)

A

 (31) Normal Rounds (32)
7 8 9 10 12 13 44 45 46 80

1	6
---	---

Z

 (33)

Z

 (34)

NA

 (35)

NA

 (36)
7 8 9 10 11 44 45 80

1	7
---	---

0	0	0
---	---	---

 (37)

Z

 (38)

NA

 (39)
7 8 9 11 12 13 80

1	8
---	---

0	0	0
---	---	---

 (40)

NA

 (41)
7 8 9 11 12 80

1	9
---	---

Z

 (42)

NA

 (43)

8301100230	830105
------------	--------

PDR	ADOCK	05000416
-----	-------	----------

S	PDR
---	-----

7 8 9 10 11 12 80

2	0
---	---

N

 (44)

NA

 (45)

68	69	80
----	----	----

7 8 9 10 80

NAME OF PREPARER Original signed by Matthew V. Rohrer PHONE

SUPPLEMENTARY INFORMATION TO
LER 82-155/03 L-0

Mississippi Power & Light Company
Grand Gulf Nuclear Station - Unit 1
Docket No. 50-416

Technical Specification Involved: NA
Reported Under Technical Specification: 6.9.1.13.c

Event Narrative:

At 8:30 on December 6, 1982, the continuous air monitor (CAM) for the discharge of the temporary ventilation exhaust system was shut off when the system was secured. At 1610 on the same day the system was observed to be operating yet the CAM unit for the discharge was not. The system takes a suction from the suppression pool area and discharges to the atmosphere. The temporary system was installed to reduce the amount of painting fumes and dust while workers were in the area. Upon discovering that the CAM unit was not operating, it was immediately turned on. No significant activity increase above normal background was observed following the system shutdown. This was expected since there is no activity from fission products or other sources in the pool.

The system is controlled by a simple on/off switch operated locally. It is believed that the switch was turned on by manual labor personnel working in the area unaware of the monitoring requirements. Operations personnel have been instructed to take appropriate measures to prevent reoccurrence of this incident. This is a final report.