

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
---	---

REPORT SOURCE

L	6	0	5	0	0	0	3	2	8	7	0	1	1	8	8	3	8	0	2	1	5	8	3	9
60	61	DOCKET NUMBER								68	69	EVENT DATE					74	75	REPORT DATE					80

0 2 With unit 2 in mode 1 (98% reactor power) at 1100 CST on 01/18/83, during review
0 3 of SI-90.32, it was discovered that pressurizer pressure channel 2-PS-68-334 had
0 4 been found out of tolerance. The calibration was performed on 12/15/82 with the
0 5 unit in mode 5, but the out of tolerance channel could have occurred in mode 1
0 6 prior to entering mode 5. There was no effect upon public health and safety.
0 7 Previous occurrences - none.

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The pressure switch bistable was verified to be in tolerance on 11/09/82. On

1 1 12/15/82 the bistable was found out of tolerance. The cause is unknown and

1 2 considered to be an isolated case, since past records have shown the instruments

1 3 to be very stable. The bistable setpoints were reset and the channel verified

1 4 operable on 12/15/82. The channel will be monitored for bistable drift.

FACILITY STATUS										% POWER										OTHER STATUS										METHOD OF DISCOVERY										DISCOVERY DESCRIPTION									
1	5	E	28	0	9	8	29	NA	B	31	Surveillance test																																						
ACTIVITY CONTENT										RELEASED OF RELEASE										AMOUNT OF ACTIVITY										LOCATION OF RELEASE																			
1	6	Z	33	Z	34	A	35	NA																																									
PERSONNEL EXPOSURES										PERSONNEL INJURIES										LOSS OF OR DAMAGE TO FACILITY										PUBLICITY																			
NUMBER										NUMBER										TYPE										DESCRIPTION																			
1	7	0	0	0	37	Z	38	NA	0	0	0	40	NA	0	0	0	42	NA	2	0	N	44	NA																										
ISSUED										DESCRIPTION										NRC USE ONLY																													
PDR										PDR																																							

Name of Preparer: H. R. Rogers /M. R. Harding

Phone: (615) 751-0349