

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONTROL BLOCK: 1 (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N Y J A F 1 2 0 0 - 0 0 0 0 - 0 0 0 3 4 1 1 1 1 4 5
7 8 9 14 15 25 26 30 57 CAT 58
LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CON'T
0 1 REPORT SOURCE L 6 0 5 0 0 0 3 3 3 7 1 2 2 6 8 2 8 0 2 0 3 8 3 9
7 8 60 61 68 69 74 75 80
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0 2 "Update Report - Previous Report Dated 01-25-83". During normal operation on 09-02-
0 3 82, Main Steam Isolation Valve "D" Inboard ten (10) percent switch would not reset
0 4 when tested to satisfy T.S. 3.1-1(Note 1). The "D" valve was then recycled and re-
0 5 reset with satisfactory results. The event did not represent a hazard to the public
0 6 health and safety. See attachment for additional details. LER-82-038 is a related
0 7 event.
0 8
7 8 9

0 9 SYSTEM CODE I A 11 CAUSE CODE E 12 CAUSE SUBCODE E 13 COMPONENT CODE I N S T R U 14 COMP. SUBCODE S 15 VALVE SUBCODE Z 16
7 8 9 10 11 12 13 18 19 20
17 LER/RO REPORT NUMBER 8 2 21 22 0 4 3 24 26 27 0 3 28 29 X 30 31 2 32
EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.

ACTION TAKEN X 18 FUTURE ACTION F 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED Y 23 NPRD-4 FORM SUB. Y 24 PRIME COMP. SUPPLIER A 25 COMPONENT MANUFACTURER Z 9 9 9 9 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
1 0 See attachment for details.
1 1
1 2
1 3
1 4
7 8 9

FACILITY STATUS Z 28 % POWER 1 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Surveillance 32
7 8 9 10 12 13 44 45 46 80

ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36
7 8 9 10 11 44 45 80

PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39
7 8 9 11 12 13 80

PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41
7 8 9 11 12 80

LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43
7 8 9 10 80

PUBLICITY ISSUED N 44 DESCRIPTION NA 45
7 8 9 10 80

8302230691 830203
PDR ADOCK 05000333
S PDR
NRC USE ONLY
2 0
7 8 9 10 68 69 80
NAME OF PREPARER Hartford Keith PHONE 315-342-3840

POWER AUTHORITY OF THE STATE OF NEW YORK
JAMES A. FITZPATRICK NUCLEAR POWER PLANT

DOCKET NO. 50-333

ATTACHMENT TO LER 82-043/03X-2

PAGE 1 of 1

During normal operation on December 26, 1982, Main Steam Valve "D" Inboard ten (10) percent switch would not reset when tested to satisfy Technical Specification 3.1-1 (Note 1). The "D" valve was then recycled and reset with satisfactory results.

The event did not represent a hazard to the public health and safety.

During the January 9, 1983 plant shutdown, an investigation was performed to ascertain the cause of reset problems. The cause was found to be, when the ten (10) percent switch is set at a very conservative trip point, the inherent dead band is outside the reset point; unless the value stroke is far beyond the trip setpoint. Corrective action was to adjust the switch activation point further down on the valve travel, allowing a positive reset on return to full open position.

No further corrective action is required.

It should be noted that Revision 1 of this LER reported a failure of "B" outboard MSIV in addition to the "D" inboard. It has since been determined that this should have been two separate LER's.