

CONTROL BLOCK:

--	--	--	--	--	--	--

 ① (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

00001-917-076

ATTACHMENT TO:

LER NO. 83-007/03L-0

February 25, 1983

Page 2 of 2

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (CONTINUED)

Mode 5 (cold shutdown at 0914 on 1/16/83, approximately five hours into the extended time frame. Health/safety of the public was not affected.

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (CONTINUED)

The satisfactory performance of the local leak rate test following repairs during the previous refueling outage is attributed to the fact that the seal had not experienced any thermal or pressure cycles since reassembly.

The O-rings were replaced and following the satisfactory performance of FNP-1-STP-627 (Local Leak Rate Testing of Containment Penetrations), the penetration was declared operable at 1030 on 2/8/83. The personnel involved have been reinstructed on exercising caution while performing safety-related maintenance.