

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

| | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---------------|---|----------------|----|---|---|---|---|--------------|----|----|---|-----|---|----|---|----|----|---|---|---|----|----|---|---|---|---|
| 0 | 1 | M | S | G | G | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5 |
| 7 | 8 | 9 | 14 | | | | | | 15 | 25 | | | | | | 26 | 30 | | | | 57 | 58 | | | | |
| LICENSEE CODE | | LICENSE NUMBER | | | | | | LICENSE TYPE | | | | CAT | | 58 | | | | | | | | | | | | |

| | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---------------|---|---------------|---|---|---|---|---|------------|----|---|---|-------------|----|----|---|---|---|----|----|---|---|---|---|---|---|---|
| 0 | 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 4 | 1 | 6 | 7 | 0 | 1 | 2 | 9 | 8 | 3 | 8 | 0 | 2 | 2 | 5 | 8 | 3 | 9 |
| 7 | 8 | 60 | | | | | | 61 | 68 | | | | 69 | 74 | | | | 75 | 80 | | | | | | | |
| REPORT SOURCE | | DOCKET NUMBER | | | | | | EVENT DATE | | | | REPORT DATE | | | | | | | | | | | | | | |

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

On January 29, 1983, fire door 1A106 (Auxiliary Building stairwell, elevation 93 feet) alarmed on the supervision system and would not reset. Similarly, on January 31, 1983, fire door OC505 (Control Room) alarmed and would not reset. This required entering the action statement of T.S.3.7.7 and is being reported pursuant to T.S. 6.9.1.13.b. The event had no effect on the health and safety of the public and did not constitute a threat to plant safety.

| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|-------------|---|------------|----|---------------|----|--------------|----|---------------|----|------------|----|-----------------------|----|-----------------|----|-------------|----|--------------|----|--------------|----|---------------|----|-----------------|----|-----------------|----|-------|----|----------------------|----|------------------|--|----------------------|--|------------------------|--|
| 0 | 9 | A | B | 11 | E | 12 | B | 13 | X | X | X | X | 14 | Z | 15 | Z | 16 | 8 | 3 | 0 | 3 | 4 | 0 | 3 | L | 0 | X | 9 | 9 | 9 | 26 | | | | | | |
| 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32 | 33 | 34 | 35 | 36 | 37 | 38 | | | | | | |
| SYSTEM CODE | | CAUSE CODE | | CAUSE SUBCODE | | COMP SUBCODE | | VALVE SUBCODE | | EVENT YEAR | | SEQUENTIAL REPORT NO. | | OCCURRENCE CODE | | REPORT TYPE | | REVISION NO. | | ACTION TAKEN | | FUTURE ACTION | | EFFECT ON PLANT | | SHUTDOWN METHOD | | HOURS | | ATTACHMENT SUBMITTED | | NPRD-4 FORM SUB. | | PRIME COMP. SUPPLIER | | COMPONENT MANUFACTURER | |

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

The cause was found to be failure of the lock/latch mechanisms. While operating under the action statement of T.S.3.7.7, hourly fire watches were established. The lock/latch mechanisms were replaced and the doors were returned to normal service, with the alarm circuits activated, within the required 7 day time limit of the action statement. This is a final report.

| | | | | | | | | | | | | | |
|-----------------|---|---------|----|--------------|----|---------------------|----|-----------------------|----|----|----|-------------------|----|
| 1 | 5 | G | 28 | 0 | 0 | 0 | 29 | NA | 30 | A | 31 | Alarmed Condition | 32 |
| 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 |
| FACILITY STATUS | | % POWER | | OTHER STATUS | | METHOD OF DISCOVERY | | DISCOVERY DESCRIPTION | | | | | |

| | | | | | | | | | |
|-------------------|---|--------------------|----|--------------------|----|---------------------|----|----|----|
| 1 | 6 | Z | 33 | Z | 34 | AN | 35 | NA | 36 |
| 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 |
| ACTIVITY RELEASED | | CONTENT OF RELEASE | | AMOUNT OF ACTIVITY | | LOCATION OF RELEASE | | | |

| | | | | | | | | | |
|---------------------|---|--------|----|------|----|-------------|----|----|----|
| 1 | 7 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39 |
| 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 |
| PERSONNEL EXPOSURES | | NUMBER | | TYPE | | DESCRIPTION | | | |

| | | | | | | | |
|--------------------|---|--------|----|-------------|----|----|----|
| 1 | 8 | 0 | 0 | 0 | 40 | NA | 41 |
| 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 |
| PERSONNEL INJURIES | | NUMBER | | DESCRIPTION | | | |

| | | | | | |
|-------------------------------|---|------|----|-------------|----|
| 1 | 9 | Z | 42 | NA | 43 |
| 7 | 8 | 9 | 10 | 11 | 12 |
| LOSS OF OR DAMAGE TO FACILITY | | TYPE | | DESCRIPTION | |

| | | | | | |
|------------------|---|-------------|----|----|----|
| 2 | 0 | N | 44 | NA | 45 |
| 7 | 8 | 9 | 10 | 11 | 12 |
| PUBLICITY ISSUED | | DESCRIPTION | | | |

8303040425 830225
PDR ADOCK 05000416
S PDR

NRC USE ONLY

NAME OF PREPARER Matthew V. Rohrer and Boyd Shingleton

PHONE