

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 NJCIP 12 000-0000000-000 3411111 4 5  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

CON'T  
01 REPORT SOURCE L 0 0 1 5 1 0 0 1 0 2 1 1 9 7 1 2 2 3 8 3 8 0 2 0 7 8 4 9  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 The addition of lead for radiation shielding on two of three spent fuel  
03 pool heat exchangers would overstress the heat exchanger's foundation  
04 bolts during a seismic event. Based upon the potential consequences of a  
05 failure of this type and the likelihood of occurrence, the safety signi-  
06 ficance is considered minimal. The discovery of this condition is con-  
07 sidered a reportable occurrence in accordance with Technical Specifica-  
08 tions, paragraph 6.9.2.a.9.  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

09 SYSTEM CODE F C 11 CAUSE CODE D 12 CAUSE SUBCODE Z 13 COMPONENT CODE Z Z Z Z Z Z Z 14 COMP SUBCODE Z 15 VALVE SUBCODE Z 16  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

17 LER/RO REPORT NUMBER 8 3 EVENT YEAR 21 22  
ACTION TAKEN X 18 FUTURE ACTION F 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21  
23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

101 SEQUENTIAL REPORT NO. 0 1 2 6 OCCURRENCE CODE 0 1 REPORT TYPE T REVISION NO. 0  
23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

ATTACHMENT SUBMITTED Y 23 HOURS 0 0 0 0 22 NPD-4 FORM SUB N 24 PRIME COMP. SUPPLIER Z 25 COMPONENT MANUFACTURER Z 9 9 9 9 47  
41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Cause was attributed to lack of procedural controls in the past when  
11 applying lead shielding to piping systems. A decontamination effort  
12 will attempt to reduce the radiation levels in the vicinity of the heat  
13 exchangers. Plant walkdown will identify similar situations affecting  
14 safety-related systems. Safety evaluation prior to lead reapplication.  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

15 FACILITY STATUS H 28 % POWER 0 0 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY C 31 DISCOVERY DESCRIPTION engineering evaluation 32  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

16 ACTIVITY CONTENT Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE 36  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

17 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

18 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60


20 PUBLICITY ISSUED N 44 DESCRIPTION NA 45  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

NAME OF PREPARER Paul F. Czaya

PHONE (609) 971-4893

8402150225 840207  
PDR ADOCK 05000219  
S PDR

IE22  
1/1



**GPU Nuclear Corporation**

Post Office Box 388  
Route 9 South  
Forked River, New Jersey 08731-0388  
609 971-4000  
Writer's Direct Dial Number:

February 7, 1984

Dr. Thomas E. Murley, Administrator  
Region I  
U.S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406

Dear Dr. Murley:

Subject: Oyster Creek Nuclear Generating Station  
Docket No. 50-219  
Licensee Event Report  
Reportable Occurrence No. 50-219/83-26/01T

This letter forwards three copies of a Licensee Event Report (LER) to report Reportable Occurrence No. 50-219/83-26/01T in compliance with paragraph 6.9.2.a.9. of the Technical Specifications. As indicated in my letter to you dated January 16, 1984, further review necessitated a delay in submitting this LER.

Very truly yours,

Peter B. Fiedler  
Vice President and Director  
Oyster Creek

PBF:dam  
Enclosures

cc: Director (40 copies)  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Director (3 copies)  
Office of Management Information and  
Program Control  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

NRC Resident Inspector  
Oyster Creek Nuclear Generating Station  
Forked River, NJ 08731

OYSTER CREEK NUCLEAR GENERATING STATION  
Forked River, New Jersey 08731

Licensee Event Report  
Reportable Occurrence No. 50-219/83-26/01T

Report Date

February 7, 1984

Preliminary Report Date

December 23, 1983

Discovery Date

December 23, 1983

Identification of Occurrence

Over the past several years the addition of lead, for the purpose of radiation shielding, on two of three fuel pool cooling heat exchangers has created a situation where the heat exchangers' foundation bolts would be overstressed during a seismic event. In addition, while investigating this situation, it was discovered that the original portions of the fuel pool cooling piping system are supported only by dead weight supports and therefore may not be a seismic Class I System as stated in the station's "Facility Description and Safety Analysis Report" (FDSAR). This is considered to be a reportable occurrence in accordance with paragraph 6.9.2.a.(9) of the Technical Specifications.

Conditions Prior to Occurrence

The plant was in various operating and shutdown modes.

Description of Occurrence

In response to an ALARA concern in the area of the fuel pool cooling heat exchangers, the Technical Functions Division (Engineering) was requested to evaluate the addition of lead shielding to the heat exchangers. During the evaluation it was noted that an estimated total of 4320 lbs. of lead (1320 lbs. - upper HXGR; 3000 lbs - lower HXGR) is on the original fuel pool cooling heat exchangers. This condition was analyzed utilizing the seismic floor response spectrum developed during the NRC's Systematic Evaluation Program (SEP) for Oyster Creek. The analysis indicates that the foundation

bolts for the heat exchangers would be overstressed. During the course of this investigation, it was also discovered that there exists a discrepancy between the station FDSAR and the amended installation specification for the system. The FDSAR indicates that the fuel pool cooling system is a seismic Class I system while addendum No. 6 to Burns and Roe Specification S-2299-60A removed fuel pool cooling from the list of Class I seismic systems.

#### Apparent Cause of Occurrence

The cause of the occurrence was attributed to lack of procedural controls in the past when applying lead shielding to piping systems.

The exact cause of the discrepancy between the FDSAR and the installation specification could not be determined but is believed to be due to lack of control of changes during the construction phase of the plant.

#### Analysis of Occurrence

The spent fuel pool cooling system provides the means for heat removal from the spent fuel storage pool. The fuel pool cooling heat exchangers, in turn, are cooled by reactor building closed cooling water (RBCCW) which is in turn cooled by service water (SW). RBCCW and SW are not seismic Class I systems. The failure of any of these systems would cause the fuel pool to heat up. This heat-up might lead to structural damage of the fuel pool. The Technical Specification basis for the fuel pool indicates that there would be no damage to fuel pool structural integrity for approximately ten (10) hours, if heat-up commenced from the Technical Specification limit of 125 degrees F. This would provide time to restore cooling, if it were lost. An alarm annunciates in the control room when the fuel pool temperature reaches 120 degrees F.

Analyses performed to establish the Technical Specification bases conservatively assumed the heat load to the spent fuel pool resulting from a complete core offload within ten days following shutdown and all licensed storage locations (1800) filled from prior refuelings. There are 1375 irradiated fuel assemblies currently stored in the fuel pool. In addition, the full core offload to support the current outage has been in storage for approximately eleven months. Therefore, the present heat addition due to fission product decay is significantly reduced. The heat load will be reduced further when refueling is completed.

Also, rupture of the fuel pool piping will not cause the fuel pool to drain due to the arrangement of return lines and skimmer surge tanks.

Based upon the potential consequences of a failure of this type and the likelihood of occurrence, the safety significance of this occurrence is considered to be minimal.

### Corrective Actions

The following corrective actions have been initiated:

1. A decontamination effort has been completed which reduced the levels of radiation in the vicinity of the heat exchangers. All lead will be removed prior to startup. If, for ALARA reasons, lead shielding is still required, a safety evaluation will be performed before adding any shielding.
2. A walk-down of the plant will be conducted to insure that similar situations do not exist which might interfere with the functioning of safety-related equipment. This will be completed prior to plant startup.
3. A seismic analysis has been conducted for the fuel pool cooling piping system in its present configuration and it was found that the original fuel pool cooling system is not seismic Class 1, however, the augmented cooling system which was added as part of the fuel pool expansion described in Amendment 78 to the FDSAR is a seismic Class 1 system. To satisfy original licensing criteria, changes will be made to the return piping system to ensure a seismically qualified flow path can be established between the fuel pool and the seismically qualified portion of the cooling system. This will be accomplished prior to the next core offload. Seismic qualification will be based upon operational criteria consistent with ASME Section III, Division I, Appendix F. An assessment of the entire system will then be made to determine if further system upgrading is appropriate.