



New York Power Authority

February 7, 1984
JPN-84-08

J. Phillip Bayne
Executive Vice President
Nuclear Generation

Director of Nuclear Reactor Regulations
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Attention: Mr. Domenic B. Vassallo, Chief
Operating Reactors Branch No. 2
Division of Licensing

Subject: James A. FitzPatrick Nuclear Power Plant
Docket No. 50-333
Inservice Inspection Summary Report - Summer
1983 Outage

- References:
1. NYPA letter, J. P. Bayne to D. B. Vassallo, dated July 7, 1983 (JPN-83-64).
 2. NYPA letter, C. A. McNeill, Jr. to T. E. Murley, dated August 24, 1983 (JAEP-83-0880).
 3. NRC letter, D. B. Vassallo to J. P. Bayne, dated September 1, 1983.

Dear Sir:

Attached are two (2) copies of the James A. FitzPatrick Inservice Summary Report for the Summer, 1983 outage. This report covers inspections performed in three general areas: 1) pipe supports, pipe weld and other pressure retaining component examinations performed in accordance with the FitzPatrick Inservice Inspection program; 2) the examination of susceptible stainless steel piping for evidence of intergranular stress corrosion cracking in accordance with NUREG 0313, Rev. 1 and IE Bulletin, 83-02; 3) examination of the jet pump beams and core spray spargers in accordance with IE Bulletin Nos. 80-07 and 81-13, as well as other in-vessel components.

The results of these inspections were acceptable. Intergranular stress corrosion cracking was discovered in the control rod drive hydraulic return line, and in the Reactor Recirculation System in one of the end cap welds on the 'A' distribution manifold.

8402160336 840207
PDR ADOCK 000033C
Q PDR

Handwritten:
A047
1/2

Handwritten:
Enclosure: ORB# 2-BC
To Reg File
LPOR
PDR
NTIS
NSIC

The control rod drive hydraulic return line was cut and capped as reported in Reference 1. The cracking in the recirculation system distribution manifold cap was analyzed for effect on piping structural margin and found to be of acceptable size for operation for at least one cycle. This analysis was reported in Reference 2, and found acceptable in your safety evaluation dated September 1, 1983 (Reference 3).

This report has been reviewed by the Authority and by the Hartford Steam Boiler Inspection and Insurance Company authorized inservice inspector. The approval of the authorized inspector is shown on data form NIS-1.

Enclosure 1 to this letter is an acknowledgement of receipt. Please sign and return to Mr. J. A. Gray, Jr. of my staff at the address shown above. If you have any questions, please contact Mr. Gray.

Very truly yours,

for *C. M. Wilverding*
J. P. Bayne
Executive Vice-President
Nuclear Generation

cc: Resident Inspector
U.S. Nuclear Regulatory Commission
P. O. Box 136
Lycoming, NY 13093

R. W. Barton
United Engineers & Constructors, Inc.
30 South 17th Street
Post Office Box 8223
Philadelphia, PA 19101