

LICENSEE EVENT REPORT

UPDATE REPORT:

PREVIOUS REPORT DATE: 6-24-83

CONTROL BLOCK: | | | | | | | ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	C	B	E	P	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	1	1	1	1	4	5							
7	8	9						14						15	25										26	30										57	58	
		LICENSEE CODE							LICENSE NUMBER											LICENSE TYPE																		

CON'T

REPORT SOURCE L 6 0 5 0 - 0 3 2 4 7 0 5 2 6 8 3 8 0 2 1 0 8 4 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While performing Remote Shutdown Panel RHR System Flow Indication Calibration,
0 3 PT-55.8PC, alligator clip test leads connected across the instrument test terminals
0 4 of RHR System flow transmitter 2-E11-FT-3338 were accidentally bumped and detached by
0 5 the involved technician. The leads shorted to ground and rendered the transmitter's
0 6 respective signal converter, FY-3338, inoperable due to resulting component damage.
0 7 This event did not affect the health and safety of the public.

08 Technical Specifications 3.3.5.2, 6.9.1.9b 8

SYSTEM CODE I C 11		CAUSE CODE A 12		CAUSE SUBCODE C 13		COMPONENT CODE I N S T R U 14				COMP. SUBCODE Y 15		VALVE SUBCODE Z 16					
EVENT YEAR 8 3 21 22		SEQUENTIAL REPORT NO. 0 5 23 24 25 26		OCCURRENCE CODE 0 3 27 28 29		REPORT TYPE L 30 31		REVISION NO. 1 32									
ACTION TAKEN D 18 19		FUTURE ACTION Z 18 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22 23 24 25 26		ATTACHMENT SUBMITTED N 23 24		NPRD-4 FORM SUB. Y 24 25		PRIME COMP. SUPPLIER N 25 26		COMPONENT MANUFACTURER M 4 2 2 26 27 28 29	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | This event resulted from the involved technician being somewhat encumbered due to
1 1 | dress in full anticontaminate clothing and rubber gloves. FY-3338, Part No.
1 2 | SRT/4-20 mA/1-5V/24 DC STD was repaired and returned to service. This event was
1 3 | reviewed by appropriate I&C personnel to ensure their awareness of the importance
1 4 | to exercise caution when performing functions requiring dexterity while in
7 8 9 anticontaminate dress.

FACILITY STATUS (1) 5 (2) E (28) % POWER (3) 0 (4) 9 (5) 7 (29) OTHER STATUS (30) NA METHOD OF DISCOVERY (31) B DISCOVERY DESCRIPTION (32) Periodic Test

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 2 33 34

AMOUNT OF ACTIVITY (35)

NA

LOCATION OF RELEASE (36)

NA

PERSONNEL EXPOSURES										
NUMBER			TYPE	DESCRIPTION						
1	7	0	0	0	(37)	z	(38)	NA		

PERSONNEL INJURIES			
NUMBER	DESCRIPTION		
00040	NA		

7 8 9 11 12
LOSS OF OR DAMAGE TO FACILITY (43)
TYPE DESCRIPTION
1 9 7 (42)
8402220553 840210
PDR ADOCK 05000324
S PDR
TE22 111

[illegible]

NAME OF PREPARER M. J. Pastva, Jr. PHONE: 919-457-9521

NAME OF PREPARER M. J. Pastva, Jr.

PHONE: 919-457-9521

100



Carolina Power & Light Company

~~84 FEB 16 10:31~~

Brunswick Steam Electric Plant
P. O. Box 10429
Southport, NC 28461-0429

February 10, 1984

FILE: B09-13510C
SERIAL: BSEP/84-0268

Mr. James P. O'Reilly, Administrator
U. S. Nuclear Regulatory Commission
Region II, Suite 3100
101 Marietta Street N.W.
Atlanta, GA 30303

BRUNSWICK STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-324
LICENSE NO. DPR-62
SUPPLEMENT TO LICENSEE EVENT REPORT 2-83-52

Dear Mr. O'Reilly:

In accordance with Section 6.9.1.9b of the Technical Specifications for Brunswick Steam Electric Plant, Unit No. 2, the enclosed supplemental Licensee Event Report is submitted. The original report fulfilled the requirement for a written report within thirty (30) days of a reportable occurrence and both are in accordance with the format set forth in NUREG-0161, July 1977.

Very truly yours,

C. R. Dietz, General Manager
Brunswick Steam Electric Plant

MJP/dgr/MSCGC1

Enclosure

cc: Mr. R. C. DeYoung
NRC Document Control Desk

OFFICIAL COPY

1622

11