



INDIANA & MICHIGAN ELECTRIC COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106
(616) 465-5901

October 3, 1983

Mr. J.G. Keppler, Regional Administrator
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-58
Docket No. 50-315


Dear Mr. Keppler:

This is to confirm a notification made by our Mr. B.A. Svensson to Mr. Steven Long, NRC Operations Center, at 2021 hours on September 30, 1983. At that time we reported that while making pre-startup valve lineups on Unit 1, it was discovered that the component cooling water supply and return piping for the containment hydrogen sampling system sample pumps and sample cooling coil are reversed. This situation has existed since the original installation. A review is being performed to determine if the system would have functioned as installed during accident conditions.

The Unit 2 installation was verified to be correct.

As required by Technical Specification 6.9.1.12, a followup report will be submitted within 14 days.

Sincerely,


W.G. Smith, Jr.
Plant Manager

/bab

cc: John E. Dolan
M.P. Alexich
R.F. Kroeger
H. Brugger
E. Swanson/N. DuBry, RO:III
R.C. Callen, MPSC
G. Charnoff, Esq.
J.M. Hennigan
R.L. Bruggee

INPO
PNSRC
J.F. Stietzel
E.L. Townley
Dir., IE (40 copies)
Dir., MIPC (4 copies)

8310120197 831003
PDR ADOCK 05000315
S PDR

OCT 6 1983

IE22
10