

**LICENSEE EVENT REPORT**

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONTROL BLOCK: 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100 101 102 103 104 105 106 107 108 109 110 111 112 113 114 115 116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131 132 133 134 135 136 137 138 139 140 141 142 143 144 145 146 147 148 149 150 151 152 153 154 155 156 157 158 159 160 161 162 163 164 165 166 167 168 169 170 171 172 173 174 175 176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194 195 196 197 198 199 200 201 202 203 204 205 206 207 208 209 210 211 212 213 214 215 216 217 218 219 220 221 222 223 224 225 226 227 228 229 230 231 232 233 234 235 236 237 238 239 240 241 242 243 244 245 246 247 248 249 250 251 252 253 254 255 256 257 258 259 260 261 262 263 264 265 266 267 268 269 270 271 272 273 274 275 276 277 278 279 280 281 282 283 284 285 286 287 288 289 290 291 292 293 294 295 296 297 298 299 300 301 302 303 304 305 306 307 308 309 310 311 312 313 314 315 316 317 318 319 320 321 322 323 324 325 326 327 328 329 330 331 332 333 334 335 336 337 338 339 340 341 342 343 344 345 346 347 348 349 350 351 352 353 354 355 356 357 358 359 360 361 362 363 364 365 366 367 368 369 370 371 372 373 374 375 376 377 378 379 380 381 382 383 384 385 386 387 388 389 390 391 392 393 394 395 396 397 398 399 400 401 402 403 404 405 406 407 408 409 410 411 412 413 414 415 416 417 418 419 420 421 422 423 424 425 426 427 428 429 430 431 432 433 434 435 436 437 438 439 440 441 442 443 444 445 446 447 448 449 450 451 452 453 454 455 456 457 458 459 460 461 462 463 464 465 466 46

REPORT SOURCE 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

0 0 5 0 0 2 4 7 7 1 0 1 1 8 3 8 1 1 1 0 8 3 9

DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 7 While the plant was being cooled down for a planned maintenance outage a 1/2" nipple failed on the impulse line associated with Auxiliary Boiler Feedpump #23 flow transmitter. Technical Specification 3.4. Health and safety of the public were not affected. No previous similar event.

7 8 9		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE	
0 9		C H		X		B		P I P E X X				A		Z	
7 8		9 10		11 12		13 14		15 16 17 18				19 20		21 22	
17 LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.					
8 3		21 22		23 24		25 26		27 28		29 30		31 32		33 34	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB		PRIME COMP. SUPPLIER	
X		X		Z		Z		0 0 0		N		N		Z	
33 34		35 36		37 38		39 40		41 42		43 44		45 46		47 48	
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS															

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Failed nipple was repaired within the time permitted by the Technical Specifications.

1 1 | The cause for this failure is being investigated.

1 2 |

1 3 |

1 4 |

8 9  
FACILITY STATUS (28) 0 0 0 (29) NA (30) METHOD OF DISCOVERY (31) Routine Inspection (32) DISCOVERY DESCRIPTION  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60  
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) (36) LOCATION OF RELEASE  
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60  
1 5 G (28) 0 0 0 (29) NA (30) METHOD OF DISCOVERY (31) Routine Inspection (32) DISCOVERY DESCRIPTION  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60  
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) (36) LOCATION OF RELEASE  
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60  
1 6 Z (33) Z (34) NA (35) (36) LOCATION OF RELEASE

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	Z	(38)	NA	(39)

		PERSONNEL INJURIES					
		NUMBER			DESCRIPTION		
7	8	9	10	11	12	13	14
1	8	0	0	0	(40)	NA	(41)

7		8		9		10	
TYPE				DESCRIPTION			
1	9	Z	42	NA			

IE 20

PUBLICITY		ISSUED		DESCRIPTION		NRC USE ONLY	
2	0	N	14	NA			

8312050404 831110  
PDR ADOCK 05000247  
S PDR

NAME OF PREPARER

Srivatsan Nadipuram

PHONE: 014-526-5340

John D. O'Toole  
Vice President

Consolidated Edison Company of New York, Inc.  
4 Irving Place, New York, NY 10003  
Telephone (212) 460-2533

November 10, 1983


Re: Indian Point Unit No. 2  
Docket No. 50-247  
LER-83-037/03L-0

Dr. Thomas E. Murley,  
Regional Administrator-Region I  
U. S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, Pa. 19406

Dear Dr. Murley:

The attached Licensee Event Report LER-83-037/03L-0 is hereby submitted in accordance with the requirements of Technical Specification 6.9.1.7. This event is of the type described in Technical Specification 6.9.1.7.2.b.

Very truly yours,



attach.

cc: Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. Thomas Foley, Senior Resident Inspector  
U. S. Nuclear Regulatory Commission  
P. O. Box 38  
Buchanan, New York 10511

IE22  
1/1