

CONTROL BLOCK: ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 M A P P S 1 2 0 0 - 0 0 0 0 0 0 - 0 0 0 3 4 1 1 1 1 4 5
7 8 9 LICENSE CODE 14 15 LICENSE NUMBER 18 24 LICENSE TYPE 30 37 CAT 38

CUNT

01 REPORT SOURCE L 6 0 5 0 - 0 2 9 3 7 1 0 2 1 8 3 8 1 1 1 8 8 3 9
7 8 DOCKET NUMBER 60 61 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During steady state operation, on October 21, 1983, it was found that a sliding
03 fire door did not have the proper number (1 as-built vs. 2 required) of binders
04 as required by NFPA Standard #80. A fire patrol has been established in accord-
05 ance with T.S. 3.12.F. This event does not affect the health and safety of the
06 public.
07
08

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
A B 11 B 12 A 13 X X X X X 14 Z 15 Z 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20
17 LER/RO REPORT NUMBER 8 3 21 22 23 24 25 26 27 28 29 30 31 32
18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS 22 ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER 26
X 18 F 19 Z 20 Z 21 0 0 0 0 N 23 N 24 A 25 R 2 5 5 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Cause was determined to be an installation oversight. Engineering has ordered
11 a second binder which will be installed to bring the door into conformance with
12 NFPA Standard #80. The sliding fire door is the only one of this design within
13 the Station. This event was an isolated incident.
14

15 FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DISCOVERY DESCRIPTION 32
E 28 0 9 2 29 N/A B 31 QA Fire Protection Audit
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
16 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
Z 33 Z 34 N/A N/A
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39
0 0 0 37 Z 38 N/A
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
18 PERSONNEL INJURIES NUMBER DESCRIPTION 41
0 0 0 40 N/A
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43
Z 42 N/A
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
20 PUBLICITY ISSUED DESCRIPTION 45
N 44 N/A
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

NAME OF DEBADER

P. J. Hamilton

PHONE

617-746-7905

BOSTON EDISON COMPANY
800 BOYLSTON STREET
BOSTON, MASSACHUSETTS 02199

WILLIAM D. HARRINGTON
SENIOR VICE PRESIDENT
NUCLEAR

November 18, 1983

BECO Ltr. #83-284

Regional Administrator, Region 1
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406


Docket Number 50-293
License DPR-35

Dear Sir:

The attached Licensee Event Report #83-056/03L-0, "Sliding Fire Door", is hereby submitted in accordance with the requirements of Pilgrim Nuclear Power Station Technical Specification 6.9.E.2.b.

If there are any questions on this subject, please do not hesitate to contact the undersigned.

Respectfully submitted,



William D. Harrington

WDH:em

Enclosure: LER 83-056/03L-0

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Standard BECO LER Distribution

IE22
1/1