

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

| | |
|---|---|
| 0 | 1 |
| 7 | 8 |

REPORT SOURCE

| | | | | | | | | | | | | | | | | | | | | | | | | |
|---------------|----|---|---|---|---|---|---|---|---|----|------------|---|---|---|---|----|---|-------------|---|---|---|---|---|----|
| L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 5 | 4 | 7 | 1 | 0 | 2 | 4 | 8 | 3 | 3 | 1 | 1 | 0 | 7 | 8 | 3 | 9 |
| 60 | 61 | | | | | | | | | 68 | 69 | | | | | 74 | | 75 | | | | | | 80 |
| DOCKET NUMBER | | | | | | | | | | | EVENT DATE | | | | | | | REPORT DATE | | | | | | |

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | At 0735 hours, on October 24, 1983, while performing the Suppression Chamber to
0 3 | Drywell Vacuum Breaker Monthly Exercise, QOS 1600-1, vacuum breaker 1-1601-32C
0 4 | showed a dual indication on Division I while closing. As required by Technical
0 5 | Specification 3.7.A.4.b, the Suppression Chamber to Drywell pressure separation was
0 6 | performed immediately; and the vacuum breaker was verified to be closed. Since the
0 7 | only apparent problem was a limit switch on Division I, the vacuum breaker was
0 8 | capable of performing its design function. The safety implications of this
0 9 | occurrence were minimal.

| | | | | | | | | | | | | | | | | | | | | | | | | | | |
|-------------------|----|----------------------|--------------------|-------------------|-----------------|----------------------|----|----------------------|----------------------|----|-------------------------------|------------------|----|----|---------------------------|----|----|----------------------|------------------|----|---------------------------|----|------------------|-----------------------------------|----|----|
| 09 | | SYSTEM CODE S A | | 11 | CAUSE CODE X | | 12 | CAUSE SUBCODE X | | 13 | COMPONENT CODE I N S T R U | | | | | | 14 | COMP SUBCODE S | | 15 | VALVE SUBCODE Z | | 16 | | | |
| 7 | 8 | 9 | 10 | | 11 | | 12 | | 13 | | | | | | 18 | | 19 | | | 20 | | | | | | |
| 17 | | LER/RO REPORT NUMBER | | EVENT YEAR 8 3 | | 21 | 22 | SHUTDOWN METHOD Z | | 21 | SEQUENTIAL REPORT NO 0 43 | | 24 | 26 | OCCURRENCE CODE 0 3 | | 28 | 29 | REPORT TYPE L | | 30 | 31 | REVISION NO 0 | | 32 | |
| ACTION TAKEN X | | 18 | FUTURE ACTION X | | 19 | EFFECT ON PLANT Z | | 20 | SHUTDOWN METHOD Z | | 21 | HOURS 0 0 0 0 | | 22 | ATTACHMENT SUBMITTED N | | 23 | NPRD-4 FORM SUB N | | 24 | PRIME COMP. SUPPLIER A | | 25 | COMPONENT MANUFACTURER M 3 0 2 | | 26 |
| 33 | 34 | 35 | 36 | 37 | 38 | 39 | 40 | 41 | 42 | 43 | 44 | 45 | 46 | 47 | 48 | 49 | 50 | 51 | 52 | 53 | 54 | 55 | 56 | 57 | 58 | |

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The cause of this occurrence is suspected as being the Division 1 open limit switch
1 1 | out of adjustment. The root cause will be determined at the next outage of
1 2 | sufficient duration. A supplemental report will be issued following repairs.
1 3 | Until that time, the Suppression Chamber to Drywell pressure separation test will be
1 4 | performed every 15 days as required by Technical Specification 3.7.A.4.d.

FACILITY STATUS (1) 5 (E) (28) % POWER (0) 8 9 (29) OTHER STATUS (30) NA
 METHOD OF DISCOVERY (B) (31) Vacuum Breaker Inop Surveillance DISCOVERY DESCRIPTION (32)
 ACTIVITY CONTENT RELEASED OF RELEASE (1) 6 (Z) (33) (Z) (34) AMOUNT OF ACTIVITY (35) NA
 LOCATION OF RELEASE (36) NA

| PERSONNEL EXPOSURES | | | | | | | | | |
|---------------------|---|---|------|-------------|----------------|--|--|--|--|
| NUMBER | | | TYPE | DESCRIPTION | | | | | |
| 1 | 7 | 0 | 0 | 0 | (37) Z (38) NA | | | | |

| PERSONNEL INJURIES | | NUMBER | | DESCRIPTION | |
|--------------------|---|--------|---|-------------|-------|
| 1 | 2 | 0 | 0 | 0 | 40 NA |

| | | | | | | |
|------------------------------------|---|---|------|----|--------------------|------|
| 7 | 8 | 9 | 11 | 12 | 8312070110 831107 | 80 |
| LOSS OF OR DAMAGE TO FACILITY (43) | | | | | PDR ADOCK 05000254 | IE22 |
| TYPE DESCRIPTION | | | | | S PDR | |
| 1 | 9 | Z | (42) | NA | | |

| | | | | | | | | | | | | | | | | |
|--------|---|-------------|-----------|----|--|--|--|--|--|--|--|--|--|----|--------------|--|
| 7 | 8 | 9 | 10 | | | | | | | | | | | 80 | | |
| | | | PUBLICITY | | | | | | | | | | | | NRC USE ONLY | |
| ISSUED | | DESCRIPTION | | | | | | | | | | | | | | |
| 2 | 0 | N | 44 | NA | | | | | | | | | | | | |

NAME OF PREPARER S Reynolds

PHONE 309-654-2241, ext 177



Commonwealth Edison

Quad Cities Nuclear Power Station
22710 206 Avenue North
Cordova, Illinois 61242
Telephone 309/654-2241

DMB

NJK-83-410

November 7, 1983

J. Keppier, Regional Administrator
Office of Inspection and Enforcement
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137


Reference: Quad-Cities Nuclear Power Station
Docket Number 50-254, DPR-29, Unit One
Appendix A, Section 3.7.A.4.b

Enclosed please find Reportable Occurrence Report Number R0 83-43/03L-0
for Quad-Cities Nuclear Power Station.

This report is submitted to you in accordance with the requirements of
Technical Specification 6.6.B.2.b, operation in a degraded mode permitted
by a limiting condition for operation.

Respectfully,

COMMONWEALTH EDISON COMPANY
QUAD-CITIES NUCLEAR POWER STATION


N. J. Kalivianakis
Station Superintendent

NJK:DGC/bb

Enclosure

cc B. Rybak
A. Morrongiello
INPO Records Center

NOV 25 1983

IE2211