

LICENSEE EVENT REPORT

CONTROL BLOCK: [] - [] [] [] [] [] [] []

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	T	N	S	N	P	L	(?)	0	0	-	0	0	0	0	0	-	0	0	(3)	4	1	1	1	1	(4)						
7	8	9	LICENSEE CODE						14	LICENSE NUMBER												25	LICENSE TYPE					30	CAT AL.			

CON'T

REPORT SOURCE L 6 0 5 1 0 1 0 0 3 2 7 7 1 1 0 1 8 3 8 1 1 3 0 8 3 9
60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

012 With unit 1 in mode 1 (100% Rx power) at 1238 CST on 11/01/83, one UHI level switch
013 (1-LS-87-23) was declared inoperable due to failure to meet surveillance requirements.
014 This event required entry into action statement (a) of LCO 3.5.1.2. There was no
015 effect upon public health and safety. Previous occurrences - twelve (SQRO-50-327/
016 82135, 83002, 83022, 83041, 83052, 83066, 83084; SQRO-50-328/82137, 83013, 83023,
017 83044, 83062).

0 8 7 8 9

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

0 9 7 8 9 S F 11 E 12 E 13 I N S T R U 14 S 15 Z 16

[illegible]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | During performance of SI-196.1, 1-LS-87-23 was found out of calibration due to a
1 1 | loose setpoint lockdown screw. The Barton Model 288 level switch lockdown screw
1 2 | was retightened and the switch recalibrated and returned to service at 1440 CST
1 3 | on 11/01/83. A study is being conducted to determine if a more reliable switch is
1 4 | available.

FACILITY STATUS (E) (28) POWER (1) (0) (0) (29) OTHER STATUS (30) NA METHOD OF DISCOVERY (B) (31) DISCOVERY DESCRIPTION (32) Surveillance testing

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 2 33 3 34 NA NA

PERSONNEL EXPOSURES									
NUMBER			TYPE		DESCRIPTION				
1	7	0	0	0	37	Z	38	NA	

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1	1	0	0
2	0	0	0
3	0	0	0
4	0	0	0
5	0	0	0
6	0	0	0
7	0	0	0
8	0	0	0
9	0	0	0
10	0	0	0
11	0	0	0
12	0	0	0
13	0	0	0
14	0	0	0
15	0	0	0
16	0	0	0
17	0	0	0
18	0	0	0
19	0	0	0
20	0	0	0
21	0	0	0
22	0	0	0
23	0	0	0
24	0	0	0
25	0	0	0
26	0	0	0
27	0	0	0
28	0	0	0
29	0	0	0
30	0	0	0
31	0	0	0
32	0	0	0
33	0	0	0
34	0	0	0
35	0	0	0
36	0	0	0
37	0	0	0
38	0	0	0
39	0	0	0
40	0	0	0
41	0	0	0
42	0	0	0
43	0	0	0
44	0	0	0
45	0	0	0
46	0	0	0
47	0	0	0
48	0	0	0
49	0	0	0
50	0	0	0
51	0	0	0
52	0	0	0
53	0	0	0
54	0	0	0
55	0	0	0
56	0	0	0
57	0	0	0
58	0	0	0
59	0	0	0
60	0	0	0
61	0	0	0
62	0	0	0
63	0	0	0
64	0	0	0
65	0	0	0
66	0	0	0
67	0	0	0
68	0	0	0
69	0	0	0
70	0	0	0
71	0	0	0
72	0	0	0
73	0	0	0
74	0	0	0
75	0	0	0
76	0	0	0
77	0	0	0
78	0	0	0
79	0	0	0
80	0	0	0
81	0	0	0
82	0	0	0
83	0	0	0
84	0	0	0
85	0	0	0
86	0	0	0
87	0	0	0
88	0	0	0
89	0	0	0
90	0	0	0
91	0	0	0
92	0	0	0
93	0	0	0
94	0	0	0
95	0	0	0
96	0	0	0
97	0	0	0
98	0	0	0
99	0	0	0
100	0	0	0

7		8		9		10		11		12	
TYPE		DESCRIPTION		CIRCUIT		EQUIPMENT		LOCATION		REMARKS	
1	9	2	42	NA							

7 8 9 10
PUBLICITY
ISSUED DESCRIPTION (45)
2 0 N (44) NA
8312080052 831130
PDR ADOCK 05000327
S PDR
NAC USE ONLY

Name of Preparer: H. R. Rogers /M. R. Harding

Phena: (615) 870-6422

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Tower II

22 DEC 5 9:38

November 30, 1983

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Suite 2900
101 Marietta Street, NW.
Atlanta, Georgia 30303


Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 1 - DOCKET
NO. 50-327 - FACILITY OPERATING LICENSE DPR-77 - REPORTABLE OCCURRENCE
REPORT SQRO-50-327/83156

The enclosed report provides details concerning the inoperability of one
UHI level channel. This report is submitted in accordance with Sequoyah
unit 1 Technical Specification 6.9.1.13.b.

Very truly yours,

TENNESSEE VALLEY AUTHORITY



H. J. Green
Director of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

NRC Inspector, NUC PR, Sequoyah

OFFICIAL COPY

LE 22
1/1