

LICENSEE EVENT REPORT

CONTROL BLOCK / / / / / / (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

/0/1/ /V/A/N/A/S/1/ (2) /0/0/-/0/0/0/0/0/-/0/0/ (3) /4/1/1/1/1/ (4) / / / (5)
 /0/1/ LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT
 REPORT /L/ (6) /0/5/0/0/0/3/3/8/ (7) /1/1/0/1/8/3/ (8) /1/1/2/3/8/3/ (9)
 SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

/0/2/ / Individual Rod Position Indication (IRPI) for channel N-09 deviated from the /
 /0/3/ / group demand position by greater than 12 steps on November 1, 1983 at 2246. The /
 /0/4/ / IRPI channel was satisfactorily recalibrated within 8 hours as required by the /
 /0/5/ / Action Statement of T.S. 3.1.3.2; therefore the health and safety of the general /
 /0/6/ / public were not affected. This event is reportable as per T.S. 6.9.1.9.b. /
 /0/7/ / /
 /0/8/ / /

SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
-------------	------------	---------------	----------------	---------------	---------------

/0/9/	/I/D/ (11)	/E/ (12)	/E/ (13)	/I/N/S/T/R/U/ (14)	/I/ (15)	/Z/ (16)
	LER/RO	PERCENT YEAR	SEQUENTIAL REPORT NO.	OCCURRENCE CODE	REPORT TYPE	REVISION NO.
(17)	REPORT NUMBER	/8/3/	/-/ /0/7/6/	/0/3/	/L/	/-/ /0/

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
--------------	---------------	-----------------	-----------------	-------	----------------------	------------------	----------------------	------------------------

/E/ (18)	/Z/ (19)	/Z/ (20)	/Z/ (21)	/0/0/0/0/ (22)	/N/ (23)	/Y/ (24)	/N/ (25)	/W/1/2/0/ (26)
----------	----------	----------	----------	----------------	----------	----------	----------	----------------

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

/1/0/ / The cause of the indicator disagreement was instrument drift. This is a recurr- /
 /1/1/ / ing problem and is generic to Westinghouse Analog Position Indicating Systems. /
 /1/2/ / The Rod Position Indicator Channel for N-09 was properly recalibrated and return- /
 /1/3/ / ed to service. /
 /1/4/ / /

FACILITY STATUS	%POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
-----------------	--------	--------------	---------------------	----------------------------

/1/5/	/C/ (28)	/0/6/9/ (29)	/ NA / (30)	/A/ (31) / Operator Observation /
-------	----------	--------------	-------------	-----------------------------------

ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
-------------------	--------------------	-------------------------	--------------------------

/1/6/	/Z/ (33)	/Z/ (34)	/ NA /
-------	----------	----------	--------

PERSONNEL EXPOSURES NUMBER	TYPE	DESCRIPTION (39)
----------------------------	------	------------------

/1/7/	/0/0/0/ (37)	/Z/ (38)	/ NA /
-------	--------------	----------	--------

PERSONNEL INJURIES NUMBER	DESCRIPTION (41)
---------------------------	------------------

/1/8/	/0/0/0/ (40)	/ NA /
-------	--------------	--------

LOSS OF OR DAMAGE TO FACILITY TYPE	DESCRIPTION (43)
------------------------------------	------------------

/1/9/	/Z/ (42)	/ NA /
-------	----------	--------

PUBLICITY

ISSUED	DESCRIPTION (45)
--------	------------------

/2/0/	/N/ (44)	/ NA /
-------	----------	--------

NAME OF PREPARER E. Wayne Harrell

PHONE (703) 894-5151

NRC USE ONLY

/ / / / / / / / / / / / / / / /

Vepco

Rec'd
53 NOV 30 11:05
VIRGINIA ELECTRIC AND POWER COMPANY
NORTH ANNA POWER STATION
P. O. BOX 402
MINERAL, VIRGINIA 23117

November 23, 1983

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 2900
Atlanta, Georgia 30303

Serial No. N-83-162
NO/RST: dus
Docket No. 50-338
License No. NPF-4


Dear Mr. O'Reilly:

Pursuant to North Anna Power Station Technical Specifications, the Virginia Electric and Power Company hereby submits the following License Event Report applicable to North Anna Unit No. 1.

Report No.	Applicable Technical Specifications
LER 83-076/03L-0	T.S. 6.9.1.9.b

This report has been reviewed by the Station Nuclear Safety and Operating Committee and will be forwarded to Safety Evaluation and Control for their review.

Very Truly Yours,


E. Wayne Barrell
Station Manager

Enclosures (3 copies)

cc: Document Control Desk (1 copy)
016 Phillips Bldg.
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555

OFFICIAL COPY

TE 22

1/1