

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONT

0	1
---	---

REPORT SOURCE

L	6	0	5	0	0	0	3	2	8	7	1	0	3	1	8	3	8	1	1	2	9	8	3	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

DICTIONARY NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

0 2 | Unit 2 in mode 1 at 100% RTP. At approximately 1000 (C) on 10/31/83, personnel

03 | attempting to perform an air leakage test on the upper containment airlock discovered

0 4 the outer door not fully closed. This event required entry into LCO 3.6.1.3. There

0 5 | was no effect upon public health or safety. Previous occurrences - none.

06

0	7
---	---

08 _____

SYSTEM CODE S A 9 10		CAUSE CODE A 11		CAUSE SUBCODE X 12		COMPONENT CODE P E N E T R 13 14 15 16 17 18		COMP. SUBCODE A 19		VALVE SUBCODE Z 20	
LER/RO REPORT NUMBER 17		EVENT YEAR 8 3 21 22		SEQUENTIAL REPORT NO. 1 5 3 23 24 25 26		OCCURRENCE CODE 0 3 27 28 29		REPORT TYPE L 30		REVISION NO. 0 31 32	
ACTION TAKEN X 33		FUTURE ACTION Z 34		EFFECT ON PLANT Z 35		SHUTDOWN METHOD Z 36		HOURS 0 0 0 0 37 38 39 40		ATTACHMENT SUBMITTED N 41	
CAUSE DESCRIPTION 1		PRIME COMP. SUPPLIER L 43		NPRD 4 FORM SUB. N 42		COMPONENT MANUFACTURER C 3 1 44					

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The door was closed upon discovery. Security personnel conducted a search of upper

11 [] containment and concluded no security compromise had taken place. The most probable

1 2 cause of the door being not fully closed has been attributed to Public Safety

13 | personnel not getting the door fully seated following an alarm check at 0403 (C)

1 4 | on 10/31/83.

FACILITY STATUS (1) 5 (2) E (28) 1 0 0 (29) NA (30) OTHER STATUS
 7 8 9 10 11 12 13 44
 ACTIVITY CONTENT (31) B (32) Surveillance test (33) DISCOVERY DESCRIPTION
 45 46
 RELEASED OF RELEASE (34) Z (35) NA (36) LOCATION OF RELEASE
 7 8 9 10 11 12 13 44
 AMOUNT OF ACTIVITY
 PERSONNEL EXPOSURES (37) Z (38) NA (39) DESCRIPTION
 7 8 9 10 11 12 13 44
 NUMBER TYPE
 PERSONNEL INJURIES (40) NA (41) DESCRIPTION
 7 8 9 10 11 12 13 44
 NUMBER
 LOSS OF OR DAMAGE TO FACILITY (42) Z (43) NA (44) DESCRIPTION
 7 8 9 10 11 12 13 44
 TYPE
 PUBLICITY (45) N (46) NA (47) DESCRIPTION
 7 8 9 10 11 12 13 44
 ISSUED
 8312080127 831129
 PDR ADOCK 05000328
 S PDR
 I E 22
 VI
 NRC USE ONLY

Name of Preparer: G. B. Kirk /M. R. Harding

Phone: (615) 870-6422

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Tower II

83 NOV 31 11:06
November 29, 1983

83 DEC 5 9:38

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Suite 2900
101 Marietta Street, NW.
Atlanta, Georgia 30303


Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 2 - DOCKET
NO. 50-328 - FACILITY OPERATING LICENSE DPR-79 - REPORTABLE OCCURRENCE
REPORT SQRO-50-328/83153

The enclosed report provides details concerning one containment airlock door
discovered not fully closed. This report is submitted in accordance with
Sequoyah unit 2 Technical Specification 6.9.1.13.b.

Very truly yours,

TENNESSEE VALLEY AUTHORITY


H. J. Green
Director of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

NRC Inspector, Sequoyah