

CONTROL BLOCK: ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)01 ALJMF 2 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

CONT

01 REPORT SOURCE L 6 0 5 0 0 0 3 6 4 7 1 1 0 1 8 3 8 1 1 2 8 8 3 9  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 At approximately 0700 on 11/1/83, it was determined that the Reactor Coolant System

03 cooldown rate had exceeded 100 degrees per hour between 0500 and 0600. Tech. Spec.

04 3.4.10, in part, limits the maximum RCS (except the pressurizer) cooldown to

05 100 degrees Fahrenheit in any one hour period. Tech. Spec. 3.4.10 action state-

06 ment requirements were met. Health/safety of the public was not affected.

07

08

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
Z Z 11 A 12 A 13 Z Z Z Z Z Z 14 Z 15 Z 16

17 LER/RO REPORT NUMBER 8 3 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

10 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

11 This event was caused by personnel error. The operators were plotting the cool-

12 down once per hour (in accordance with Tech. Specs. but in violation of the con-

13 trolling procedure which requires the temperature to be plotted every 30 minutes)

14 on the quarter hour. Between 0515 and 0615, the cooldown was plotted to be 97

15 degrees Fahrenheit. However, subsequent review of the strip (see attached)

16 FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)

17 D 28 0 0 0 29 NA B 31 Surveillance Test

18 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

19 Z 33 Z 34 NA NA

20 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)

21 0 0 0 37 Z 38 NA

22 PERSONNEL INJURIES NUMBER DESCRIPTION (41)

23 0 0 0 40 NA

24 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)

25 Z 42 NA

26 PUBLICITY ISSUED DESCRIPTION (45)

27 N 44 NA

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45

46

47

48

49

50

51

52

53

54

55

56

57

58

59

60

NAME OF PREPARER W. G. Hairston, III

PHONE (205) 899-5156

Licensee Event Report  
LER 83-056/03L-0  
Page 2 of 2

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (continued)

charts and plant computer logs indicated that between 0500 and 0600 the cooldown had been 114 degrees Fahrenheit. An engineering evaluation performed by Westinghouse determined that no Appendix G limits were violated and that reactor vessel integrity was not impaired. The personnel involved have been counseled. This incident will be discussed with all licensed personnel.