

LICENSEE EVENT REPORT

CONTROL BLOCK: | | | | | (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | M | I | D | C | C | 2 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | | 5 |
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100
LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31 CAT 58

CONT

011 | REPORT SOURCE | L | 5 | 0 | 5 | 0 | 0 | 0 | 3 | 1 | 6 | 7 | 1 | 1 | 0 | 5 | 8 | 3 | 3 | 1 | 2 | 0 | 1 | 8 | 3 | 9 |
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100
DOCKET NUMBER 55 56 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

012 | DURING NORMAL START-UP OPERATION, CD EMERGENCY DIESEL GENERATOR WAS REMOVED FROM |
013 | SERVICE TO REPAIR MINOR OIL LEAKS. THIS CONDITION WAS NONCONSERVATIVE WITH RESPECT |
014 | TO T.S. 3.8.1.1. THE ACTION STATEMENTS WERE MET AND PUBLIC HEALTH AND SAFETY WERE |
015 | NOT AFFECTED. NO PREVIOUS OCCURRENCES. |
016 | |
017 | |
018 | |013 | SYSTEM CODE | E | E | E | 11 | CAUSE CODE | E | 12 | CAUSE SUBCODE | B | 13 | COMPONENT CODE | E | N | G | I | N | E | 14 | COMP. SUBCODE | Z | 15 | VALVE SUBCODE | Z | 16 |
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100
EVENT YEAR 21 22 SEQUENTIAL REPORT NO. 24 25 OCCURRENCE CODE 27 28 REPORT TYPE 30 31 REVISION NO. 32
013 | LER-FO REPORT NUMBER | 8 | 3 | 21 | 22 | 1 | 0 | 7 | 24 | 25 | 0 | 1 | 3 | 27 | 28 | L | 30 | 31 | 0 | 32 |
ACTION TAKEN 33 34 FUTURE ACTION 35 36 EFFECT ON PLANT 37 38 SHUTDOWN METHOD 39 40 HOURS 41 42 ATTACHMENT SUBMITTED 43 44 NPD-4 FORM SUB. 45 46 PRIME COMP. SUPPLIER 47 48 COMPONENT MANUFACTURER 49 50
E | 33 | Z | 34 | Z | 35 | Z | 36 | 0 | 0 | 0 | 0 | 41 | N | 42 | N | 43 | A | 44 | W | 3 | 1 | 1 | 5 | 50 |

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

113 | A COMPRESSION FITTING ON THE NUMBER 6 CYLINDER, LIFTER LUBE OIL SUPPLY LINE, AND A |
111 | PLUG ON THE SHAFT DRIVEN FUEL OIL PUMP WERE FOUND TO BE LEAKING. THE MINOR LEAKAGE |
112 | APPEARED TO BE A RESULT OF THE COMPONENTS BEING LOOSEMED SLIGHTLY DUE TO VIBRATION. |
112 | THE COPPER GASKET ON THE PLUG WAS REPLACED AS A PRECAUTION. THE PLUG AND COMPRESSION |
114 | FITTING WERE TIGHTENED. THE ENGINE TESTED SATISFACTORILY AND WAS RETURNED TO SERVICE. |115 | FACILITY STATUS | C | 28 | N POWER | 0 | 0 | 0 | 0 | 29 | OTHER STATUS | NA | 30 | METHOD OF DISCOVERY | B | 31 | DISCOVERY DESCRIPTION | OPERATOR OBSERVATION | 32 |
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100
ACTIVITY CONTENT 33 34 RELEASED OF RELEASE 35 36 AMOUNT OF ACTIVITY 37 38 LOCATION OF RELEASE 39 40
115 | Z | 33 | Z | 34 | NA | 35 | NA | 36 |
PERSONNEL EXPOSURES 37 38 TYPE 39 40 DESCRIPTION 41 42 NA
117 | 0 | 0 | 0 | 0 | 37 | Z | 38 |
PERSONNEL INJURIES 39 40 NUMBER 41 42 DESCRIPTION 43 44 NA
115 | 0 | 0 | 0 | 0 | 40 | NA | 41 |
LOSS OF OR DAMAGE TO FACILITY 42 43 TYPE 44 45 DESCRIPTION 46 47 NA
113 | Z | 42 |
PUBLICITY 43 44 ISSUED DESCRIPTION 45 46 NA
2 | 0 | 43 |

NAME OF PREPARER W. J. FLAGA

PHONE: 616-465-5901

NRC USE ONLY