

CONTROL BLOCK:

--	--	--	--	--	--	--

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1	A	L	B	R	F	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5			
8	9	LICENSEE CODE					14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT	58

DON'T

REPORT SOURCE 1 6 0 5 0 0 0 2 5 9 7 1 1 0 7 8 3 6 1 2 0 5 8 3 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

2 During a refueling outage it was discovered that SI 4.1.A-8, High Water Level in
3 Scram Discharge Tank, had not been performed in compliance with T.S. Table 3.1.A.
4 The maximum allowable time period for performance had been exceeded by one day.
5 There was no effect on public health and safety.
6
7
8

SYSTEM CODE I A (11)		CAUSE CODE D (12)		CAUSE SUBCODE Z (13)		COMPONENT CODE Z Z Z Z Z Z (14)				COMP SUBCODE Z (15)		VALVE SUBCODE Z (16)	
LER/RO REPORT NUMBER 8		EVENT YEAR 8 3 (17)		SEQUENTIAL REPORT NO. 0 6 5 (18)		OCCURRENCE CODE 0 3 (19)		REPORT TYPE L (20)		REVISION NO. 0 (21)			
ACTION TAKEN G (18)		FUTURE ACTION Z (19)		EFFECT ON PLANT Z (20)		SHUTDOWN METHOD Z (21)		HOURS 0 0 0 0 (22)		ATTACHMENT SUBMITTED Y (23)		NPRD-4 FORM SUB N (24)	
PRIME COMP. SUPPLIER Z (25)		COMPONENT MANUFACTURER Z 9 9 9 (26)											

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The master surveillance schedule did not require SI 4.1.A-8 be performed with
11 fuel in the Rx vessel during refuel mode. SI 4.1.A-8 was performed and personnel
12 instructed to schedule performance. The master schedule will be revised by
13 12/30/83. This event is considered isolated, and no further recurrence control is
14 required.

FACILITY STATUS								% POWER								OTHER STATUS								METHOD OF DISCOVERY								DISCOVERY DESCRIPTION								80
[5]	[H]	(28)	[0]	[0]	[0]	(29)	NA						[B]	(31)	Surveillance schedule review												80													
ACTIVITY CONTENT								RELEASED OF RELEASE								AMOUNT OF ACTIVITY								LOCATION OF RELEASE								80								
[6]	[Z]	(33)	[Z]	(34)	NA														NA								80													
PERSONNEL EXPOSURES								NUMBER TYPE DESCRIPTION																																
[7]	[0]	[0]	[0]	(37)	[Z]	(38)	NA														80																			
PERSONNEL INJURIES								NUMBER DESCRIPTION																																
[2]	[0]	[0]	[0]	(40)															80																					
LOSS OF OR DAMAGE TO FACILITY								TYPE DESCRIPTION																																
[9]	[Z]	(42)															80																							
PUBLICITY								ISSUED DESCRIPTION																																
[0]	[N]	(44)															NRC USE ONLY								80															

NAME OF PREPARED G.D.R. Campbell

(205) 729-0815

LER SUPPLEMENTAL INFORMATION

BFRO-50-259 / 83065 Technical Specification Involved Table 3.1.A

Reported Under Technical Specification 6.7.2.b.(3) * Date Due NRC 12/7/83

Event Narrative:

Units 1 and 3 were in refueling outages. Unit 2 was operating normally at 99.6 percent power. After fuel had been reloaded into unit 1 reactor vessel, engineering and surveillance scheduling personnel began developing a list of surveillance tests required to be performed prior to startup. It was discovered that the master schedule did not require Surveillance Instruction (SI) 4.1.A-8, High Water Level in Scram Discharge Tank, to be performed while fuel is in the vessel during refueling. SI 4.1.A-8 was performed on September 30, 1983 and on November 9, 1983 (one day past the maximum allowable date). This requirement was not specified in the original development of SI 1, Appendix K.

The master surveillance schedule will be revised by December 30, 1983, to clarify scheduling of this instruction during refueling. There was no effect on public health and safety. This event is considered isolated, and no further recurrence control is required.

* Previous Similar Events:

None

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision: JRP

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Tower II

02 DEC 7 P2:25

December 5, 1983

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Suite 2900
101 Marietta Street, NW.
Atlanta, Georgia 30303


Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 1 - DOCKET
NO. 50-259 - FACILITY OPERATING LICENSE DPR-33 - REPORTABLE OCCURRENCE
REPORT BFRO-50-259/83065

The enclosed report provides details concerning the failure to perform
a surveillance instruction. This report is submitted in accordance with
Browns Ferry unit 1 Technical Specification 6.7.2.b(3).

Very truly yours,

TENNESSEE VALLEY AUTHORITY


H. J. Green
Director of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

NRC Inspector, Browns Ferry

OFFICIAL COPY

IE 22

1/1