

## LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N Y J A F 1 2 0 0 - 0 0 0 0 - 0 0 0 3 4 1 1 1 1 4 5  
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100CON'T  
0 1 REPORT SOURCE L 6 0 5 0 0 0 3 3 3 7 1 1 0 4 8 3 8 1 1 2 8 8 3 9  
7 8 9 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 During normal operation, while conducting surveillance testing of the High  
0 3 Presssure Coolant Injection (HPCI) Turbine Steam High Flow Containment Isolation  
0 4 Switch 23-DPIS-76 setpoint was found less conservative than the T.S. Table 3.2-2  
0 5 required setting of  $\leq 106$  inches of water. The as found value was 122 inches of  
0 6 water. Other trip channels monitoring the same parameter were available and had  
0 7 setpoints  $\leq 106$  inches of water. The event did not represent a significant hazard  
0 8 to the public health and safety.

0 9 SYSTEM CODE S F 11 CAUSE CODE X 12 CAUSE SUBCODE B 13 COMPONENT CODE I N S T R U 14 COMP SUBCODE S 15 VALVE SUBCODE B 16  
17 LER NO REPORT NUMBER 8 3 21 22 SEQUENTIAL REPORT NO. 0 5 5 24 25 OCCURRENCE CODE 0 3 28 29 REPORT TYPE L 30 REVISION NO. 0 31  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS 22 ATTACHMENT SUBMITTED N 23 NPD-4 FORM SUB N 24 PRIME COMP SUPPLIER N 25 COMPONENT MANUFACTURER B 0 8 0 0 26  
18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 Instrument drift was the cause. Corrective action consisted of immediate adjustment  
1 1 of the setpoint to within the required value and increasing the test frequency for  
1 2 trend observations.  
1 3 No further corrective action is required.

1 4  
1 5 FACILITY STATUS E 28 % POWER 1 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Surveillance 32  
1 6 ACTIVITY CONTENT Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36  
1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39  
1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41  
1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43  
2 0 PUBLICITY N 44 DESCRIPTION NA 45

8312130396 831128  
PDR ADDCK 05000333  
S PDR

NRC USE ONLY

NAME OF PREPARER Hartford N. Keith

PHONE 342-3840 ext. 230

James A. FitzPatrick  
Nuclear Power Plant  
P.O. Box 41  
Lycoming, New York 13093  
315 342.3840



Corbin McNeill  
Resident Manager

November 28, 1983  
JAFP 83-1186

Thomas E. Murley Regional Administrator  
United States Nuclear Regulatory Commission  
Region I  
631 Park Avenue  
King of Prussia, Pa. 19406


REFERENCE: DOCKET NO. 50-333 Licensee Event Report: 83-055/03 L

Dear Mr. Murley:

We have enclosed the referenced Licensee Event Report in accordance with Section 6.0 of Technical Specifications and USNRC Regulatory Guide 1.16.

If there are any questions concerning this report, please contact Mr. Hartford N. Keith at (315) 342-3840, Extension 230.

Very truly yours,

  
CORBIN A. McNEILL, JR.  
RESIDENT MANAGER

CAM/HNK/cm  
Enclosure

CC: USNRC Document Control Desk (1)  
Asst. Director of Operating Reactors,  
USNRC Directorate of Licensing (1)  
INPO Records Center, Atlanta, Georgia (1)  
Internal Power Authority Distribution  
NRC Resident Inspector  
Document Control Center  
LER/OR File

IE 22  
11