

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 7 8
C
0 1 2 3 4 5 6 7 8 9
REPORT SOURCE 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

On Nov. 9, 1983, with Unit-1 shutdown for a planned outage, Local Leak Rate Tests were performed on the inboard feedwater check valves (1B21-F010A/B). It was determined that the Tech. Spec. 3.6.1.2. limit of .6 La (231.4 SCFH) was exceeded. The feedwater lines still have two isolation valves in each line which meet the requirements of Appendix J to 10CFR50 criteria as containment isolation valves. The feedwater lines and check valves are designed and constructed in accordance with standard review plan 3.6.2-10 so as to preclude the possibility of a credible line break.

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE					
C	H	E	B	V	A	L	V	E	X	C	A						
9 10		11 12		13 14		15 16				17 18		19 20					
EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.									
8	3	1	4	6	0	3	L	0									
21 22		23 24		25 26		27 28		29 30		31 32							
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-6 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
A	X	Z	Z	0	0	0	0	0	Y	N	A	A	3	9	1		
33 34		35 36		37 38		39 40		41 42		43 44		45 46		47 48			

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (2)

The leakage was a result of gaps found on the perimeter of the disc seal material.

These gaps appeared at the seam, or "vulcanized" points of the seal. Alignment problems were identified that would have prevented the discs from closing squarely against the seal. The Mfr. is supplying LSCS with "one piece" seals, & the alignment problems are being resolved. Other corrective action outlined in confirmatory letter from J. Keppler dated 11-28-83.

7 8 9
FACILITY STATUS 1 5 B 28 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
% POWER 0 0 0 29 NA
OTHER STATUS 30
METHOD OF DISCOVERY C 31 LLRT
DISCOVERY DESCRIPTION 32
ACTIVITY CONTENT 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
RELEASED OF RELEASE Z 33 Z 34 NA
AMOUNT OF ACTIVITY 35
LOCATION OF RELEASE 36
PERSONNEL EXPOSURES 37 38 39 40 41 42 43 44 45 46 47 48 49 50
NUMBER TYPE DESCRIPTION 39 NA
PERSONNEL INJURIES 40 41 42 43 44 45 46 47 48 49 50
NUMBER DESCRIPTION 41 NA
LOSS OF OR DAMAGE TO FACILITY 42 43 44 45 46 47 48 49 50
TYPE DESCRIPTION 42 NA
PUBLICATION 44 45 46 47 48 49 50
ISSUED DESCRIPTION 45 NA
2 0 N 44 NA
8312190170 831209
PDR ADOCK 05000373
S PDR
NRC USE ONLY
8 69
815/257-6761

NAME OF PREPARER

Randy Dus

8312190170 831209
PDR ADDCK 05000373
S PDR

PHONE:

815/357-6761

- I. LER NUMBER: 83-146/03L-0
- II. LASALLE COUNTY STATION: Unit 1
- III. DOCKET NUMBER: 050-373
- IV. EVENT DESCRIPTION:

On November 9, 1983, with Unit One shutdown for a planned outage, Local Leak Rate Tests were performed on the inboard feedwater check valves (1B21-F010A/B). It was determined that the Technical Specification 3.6.1.2 Limit of .6 La (231.4 SCFH) was exceeded.

V. PROBABLE CONSEQUENCES OF THE OCCURRENCE:

The feedwater lines still have two isolation valves in each line which meet the requirements of Appendix J to 10CFR50 criteria as containment isolation valves.

The feedwater lines between the inboard and outboard check valves as well as the valves themselves are specially designed and constructed in accordance with Standard Review Plan 3.6.2-10 and ASME Section 3, so as to preclude the possibility of a credible line break between the check valves. Therefore, it is believed that the check valves would serve their original procured function of preventing a significant loss of vessel inventory in the event of a feedwater line break.

It is, therefore, believed that no immediate safety hazards existed, and that the plant was maintained in a safe condition at all times.

VI. CAUSE:

The subject valves are tilting disc check valves manufactured by the Anchor Darling Company. It was determined that the excessive leakage was a result of gaps found on the perimeter of the disc seal material, one about one-half inch long and the other about one and one-half inches in length. These gaps appeared at the seam, or "vulcanized", points of the seal. It was also noticed that one of the seal's material appeared to be hardened slightly with multiple minute cracks. In addition, alignment problems were identified that would have prevented the discs from closing squarely against the seal.

VII. CORRECTIVE ACTION:

Immediate action was taken to repair the valves. The valve manufacturer (Anchor-Darling) is now supplying LSCS with new molded (one piece) seals as was used in the original design. Also, a representative of the Anchor-Darling Co. has been on-site to resolve the alignment problems.

As of 11-30-83, an acceptable Local Leak Rate Test had been performed on 1B21-F010B after a molded (one piece) seal was installed and the disc to hinge pin horizontal clearance was adjusted to within Anchor-Darling specifications. Work is progressing on 1B21-F010A to install a molded

VIII CORRECTIVE ACTION (Cont'd):

seal and to make more critical adjustments of the vertical positioning of the disc assembly within Anchor Darling Specifications. 1B21-F010A will be Local Leak Rate Tested when the above work is completed prior to startup.

Additional corrective actions to assure that the seal failures in these valves have been identified and the problems corrected are under way. A course of action to procure and install qualified seals in accordance with the requirements of Appendix B of 10CFR Part 50 are outlined in a Confirmatory Action Letter dated 11/28/83 from J. Keppler (NRC) to C. Reed (CECo).

Prepared by: Randy S. Dus



Commonwealth Edison
LaSalle County Nuclear Station
Rural Route #1, Box 220
Marseilles, Illinois 61341
Telephone 815/357-6761

DMB

December 9, 1983

James G. Keppler
Regional Administrator
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Sir:

Reportable Occurrence Report #83-146/03L-0 Docket #050-373 is being submitted to your office in accordance with LaSalle County Nuclear Power Station Technical Specification 6.6.B.2.(b), conditions leading to operation in a degraded mode permitted by a limiting condition for operation or plant shutdown required by a limiting condition for operation.

G. J. Diederich
Superintendent
LaSalle County Station

GJD/GW/rg

Enclosure

cc: Director of Inspection & Enforcement
Director of Management Information & Program Control
U.S. NRC Document Management Branch
INPO-Records Center
File/NRC

1 E 22
11
DEC 12 1983