

LER NO. 83-64/3L
DOCKET NO. 50-318
LICENSE NO. DPR 69
EVENT DATE 11-05-83
REPORT DATE 12-02-83
ATTACHMENT _____

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (CONT'D)

Maintenance procedures did not previously require post-maintenance HPSI injection valve stroke measurements. The valves' strokes were measured and adjusted to allow the specified flow rates. To prevent recurrence, (1) the valves will be tagged to indicate the necessity of performing post-maintenance measurements/testing, (2) the valve maintenance procedure will be revised, (3) injection leg flow rates will be determined and adjustments made, if necessary, each refueling outage, and (4) a relaxation of the flow rate specification will be investigated.

BALTIMORE GAS AND ELECTRIC COMPANY

P.O. BOX 1475

BALTIMORE, MARYLAND 21203

NUCLEAR POWER DEPARTMENT
CALVERT CLIFFS NUCLEAR POWER PLANT
LUSBY, MARYLAND 20657

December 2, 1983

Dr. Thomas E. Murley
Regional Administrator
U. S. Nuclear Regulatory Commission
Region 1
631 Park Avenue
King of Prussia, PA 19406

Docket No. 50-318
License No. DPR 69

Dear Dr. Murley:

Attached is LER 83-64/3L, as required per Technical Specification 6.9.

Should you have any questions regarding this report, we would be pleased to discuss them with you.

Very truly yours,

LBR

L. B. Russell
Plant Superintendent

LBR:LFB:mst

Attachment

cc: Director, Office of Management Information
and Program Control
Messrs: A. E. Lundvall, Jr.
J. A. Tiernan

IE22
11