

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | F | L | S | L | S | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 CAT 38

CON'T

01 | L | 0 | 5 | 0 | 0 | 0 | 3 | 8 | 9 | 1 | 1 | 1 | 4 | 8 | 3 | 1 | 2 | 1 | 6 | 8 | 3 | 9

REPORT SOURCE 30 31 DOCKET NUMBER 38 39 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | On November 11, 1983, while in Mode 1, power operation, the outer door

03 | on the escape airlock was opened. The seal test was performed on November

04 | 14, 1983 after the 72 hour limit had passed. This is not in accordance

05 | with T.S.4.6.1.3. The door when tested was found to be satisfactory. The

06 | Health and Safety of the public were not in jeopardy. This is the second

07 | event of this type, see IER 83-052.

08 |

09 |

SYSTEM CODE 11 CAUSE CODE 12 CAUSE SUBCODE 13 COMPONENT CODE 14 COMP TURCODE 15 VALVE SUBCODE 16

S | D | A | X | P | E | N | E | T | R | A | Z

LER/RO REPORT NUMBER 17 EVENT YEAR 21 22 SEQUENTIAL REPORT NO. 24 25 OCCURRENCE CODE 28 29 REPORT TYPE 30 REVISION NO. 32

8 | 3 | 0 | 7 | 3 | 0 | 3 | L | 0

ACTION TAKEN 18 FUTURE ACTION 19 EFFECT ON PLANT 20 SHUTDOWN METHOD 21 HOURS 22 ATTACHMENT SUBMITTED 23 NPRO-4 FORM SUB. 24 PRIME COMP SUPPLIER 25 COMPONENT MANUFACTURER 26

X | Z | Z | Z | 0 | 0 | 0 | 0 | N | N | A | C | 3 | 1 | 0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The cause of the event was a misunderstanding by personnel. The personnel

11 | involved have been counseled as to the importance of the Tech. Spec Req

12 | uirements. Personnel involved were nonlicensed.

13 |

14 |

FACILITY STATUS 15 POWER 16 OTHER STATUS 17 METHOD OF DISCOVERY 18 DISCOVERY DESCRIPTION 19

E | 1 | 0 | 0 | NA | 31 | OBSERVATION BY PERSONNEL

ACTIVITY RELEASED 20 CONTENT 21 AMOUNT OF ACTIVITY 22 LOCATION OF RELEASE 23

Z | Z | NA | NA

PERSONNEL EXPOSURES 24 NUMBER 25 TYPE 26 DESCRIPTION 27

0 | 0 | 0 | Z | NA

PERSONNEL INJURIES 28 NUMBER 29 DESCRIPTION 30

0 | 0 | 0 | NA

LOSS OF OR DAMAGE TO FACILITY 31 TYPE 32 DESCRIPTION 33

Z | NA

PUBLICITY 34 ISSUED 35 DESCRIPTION 36

N | NA

8312280201 831216
PDR AD0CK 05000389
S PDR

NAME OF PREPARER J. Brannin PHONE (305)465-3550 ext 3427

DEC 22 11:09



December 16, 1983
PNS-LI-83-738

Mr. James P. O'Reilly
Regional Administrator, Region II
U. S. Nuclear Regulatory Commission
101 Marietta Street N.W., Suite 2900
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 389-83-73

ST. LUCIE UNIT 2

DATE OF OCCURRENCE: NOVEMBER 14, 1983

TECHNICAL SPECIFICATION 4.6.1.3

ESCAPE AIRLOCK DOOR

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30-day notification on the subject occurrence. This report is submitted beyond the required period due to an internal administrative error.

Very truly yours,

A handwritten signature in dark ink, appearing to read "J. Williams, Jr.", is written over the typed name.

J. W. Williams, Jr.
Vice President
Nuclear Energy Department

JWW/PLP/js

Attachment

cc: Director, Office of Inspection and Enforcement (30)
Harold F. Reis, Esquire
File 933.1 SL

OFFICIAL COPY

2622
111