

CONTROL BLOCK										(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)																																		
01	C	A	S	O	S	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4		5																			
LICENSEE CODE					LICENSE NUMBER					LICENSE TYPE					CAT 58																													
CONT																																												
01	L	6	0	5	0	0	0	3	6	1	7	1	1	1	4	8	3	8	1	2	1	5	8	3	9																			
REPORT SOURCE					DOCKET NUMBER					EVENT DATE					REPORT DATE																													
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)																																												
02	On 11/14/83, at 1901, with Unit 2 in Mode 1, the reactor was manually																																											
03	tripped due to an unexpected pressurizer pressure and level decrease.																																											
04	Our analysis determined that Tc had dropped below the limits of LCO																																											
05	3.2.6 for 1-1/2 minutes, but this LCO was no longer applicable following																																											
06	the trip. During plant stabilization, CST 2T-121's level dropped below																																											
07	the limit of LCO 3.7.1.3 twice. The LCO was satisfied when tank level																																											
08	was restored by 2000. Public health and safety were not affected.																																											
09																																												
SYSTEM CODE					CAUSE CODE					COMPONENT CODE					COMP. SUBCODE					VALVE SUBCODE																								
R B 11					A 12					A 13					V A L V E X 14					E 15					D 16																			
LER/RO REPORT NUMBER					EVENT YEAR					SEQUENTIAL REPORT NO.					OCCURRENCE CODE					REPORT TYPE					REVISION NO.																			
8 3					1 5 1					0 3					L					0																								
ACTION TAKEN					FUTURE ACTION					EFFECT ON PLANT					SHUTDOWN METHOD					HOURS					ATTACHMENT SUBMITTED					NPRD-4 FORM SUB					PRIME COMP. SUPPLIER					COMPONENT MANUFACTURER				
X 18					H 19					A 20					B 21					0 0 1 1					Y 23					N 24					N 25					T 1 0 2 1 0				
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)																																												
10	An operator had erroneously opened emergency boration valve 2HV-9247																																											
11	resulting in the addition of concentrated boric acid solution to the RCS																																											
12	during automatic make-up. We believe this was a result of the																																											
13	similarity in location and appearance between this switch and the																																											
14	intended switch. See Attachment																																											
15																																												
FACILITY STATUS					% POWER					OTHER STATUS					METHOD OF DISCOVERY					DISCOVERY DESCRIPTION																								
E 28					0 8 0 29					NA 30					A 31					Operator Observation 32																								
ACTIVITY CONTENT RELEASED OF RELEASE					AMOUNT OF ACTIVITY					LOCATION OF RELEASE																																		
Z 33					Z 34					NA 35					NA 36																													
PERSONNEL EXPOSURES NUMBER					TYPE					DESCRIPTION																																		
0 0 0 37					Z 38					NA 39																																		
PERSONNEL INJURIES NUMBER					DESCRIPTION																																							
0 0 0 40					NA 41																																							
LOSS OF OR DAMAGE TO FACILITY TYPE					DESCRIPTION																																							
Z 42					NA 43																																							
PUBLICATION ISSUED					DESCRIPTION																																							
N 44					NA 45																																							
2 0					N 44																																							
NAME OF PREPARER J. G. HAYNES																																												
PHONE 714/492-7700																																												

ATTACHMENT TO LER 83-151  
SOUTHERN CALIFORNIA EDISON COMPANY  
SAN ONOFRE NUCLEAR GENERATING STATION  
UNIT NO. 2, DOCKET NO. 50-361

SUPPLEMENTAL INFORMATION FOR CAUSE DESCRIPTION AND CORRECTIVE  
ACTIONS

The operator responsible has been counseled by the Plant Superintendent. To prevent recurrence, the initial license training program includes simulator training which exposes operators to similar minor malfunctions during normal evolutions. This training will also be included in the requalification program. In addition, we are examining the Control Room panels to identify controls that have similar potentially confusing locations and appearances and are considering the necessity of providing some form of unique identification or other measures to prevent recurrence of events such as described in this report.

RECEIVED  
NRC

*Southern California Edison Company*

SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

REGION V

SCE

TELEPHONE  
(714) 492-7700

J. G. HAYNES  
STATION MANAGER

December 15, 1983

U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region V  
1450 Maria Lane, Suite 210  
Walnut Creek, California 94596-5368

Attention: Mr. J. B. Martin, Regional Administrator

Dear Sir:

Subject: Docket No. 50-361  
30-Day Report  
Licensee Event Report No. 83-151  
San Onofre Nuclear Generating Station, Unit 2

Pursuant to Section 6.9.1.13.b of Appendix A, Technical Specifications to Facility Operating License NPF-10 for San Onofre Unit 2, this submittal provides the required 30-day written report and a copy of the Licensee Event Report (LER) form for an occurrence involving Limiting Conditions for Operation (LCO's) 3.2.6 and 3.7.1.3, associated with the Reactor Coolant Cold Leg Temperature ( $T_c$ ) and the Condensate Storage Tanks (CST's), respectively. This report was delayed in order to provide a complete response.

On November 14, 1983, at 1858, with Unit 2 in Mode 1 at 80% power, an unexpected pressurizer pressure and level decrease was observed by the operator. The reactor was manually tripped at 1901 when pressurizer pressure continued to decrease to 1800 psia. Concurrently, the low pressurizer pressure automatically initiated a Containment Cooling Actuation Signal (CCAS) and a Safety Injection Actuation Signal (SIAS), however, water was not injected into the RCS since RCS pressure remained higher than the High Pressure Safety Injection (HPSI) shutoff head.

Our analysis of this event determined that the pressurizer pressure and level decrease was caused by a primary-to-secondary power mismatch. This mismatch was a result of inadvertent boration which occurred when concentrated boric acid solution was pumped directly into the RCS by the charging pumps during an automatic make-up evolution. A direct flowpath existed between

Perkin  
IE-34  
11

December 15, 1983

the Boric Acid Make-Up (BAMU) tank and the charging pump suction header, thereby bypassing the Volume Control Tank (VCT) and the blending process that occurs there. The direct flowpath had been established at 1805 when an operator erroneously opened emergency boration valve 2HV-9247 instead of the intended containment sump valve. As a result of our investigation of this incident, we believe that the operator actuated the wrong control as a result of the similarity of the location and appearance of the emergency boration valve control switch as compared to that of the containment sump valve control switch.

Additionally, it was determined that during the plant transient,  $T_c$  dropped below 544°F with reactor power above 30% for approximately 1-1/2 minutes immediately preceding the reactor trip, contrary to LCO 3.2.6. LCO 3.2.6 was no longer applicable following the trip. During stabilization of plant conditions following the trip, CST 2T-121's level dropped below 144,000 gallons on two occasions, contrary to LCO 3.7.1.3. The associated Action Statement was satisfied when tank level was restored at approximately 2000.

As corrective action, the operator responsible for opening 2HV-9247 has been counseled by the Plant Superintendent. To prevent recurrence of this type of event, the initial license training program includes simulator training which exposes operators to similar minor malfunctions during normal evolutions. This training will also be included in the operator requalification training program. In addition, we are examining the Control Room panels to identify controls that have similar potentially confusing locations and appearances and are considering the necessity of providing some form of unique identification or other measures to prevent recurrence of events such as described in this report.

There was no impact on the health and safety of plant personnel or the public associated with this event.

If you require any additional information, please so advise.

Sincerely,

*J. B. Haynes*

Enclosure: LER No. 83-151

cc: A. E. Chaffee (USNRC Resident Inspector, Units 1, 2 and 3)  
J. P. Stewart (USNRC Resident Inspector, Units 2 and 3)

U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement

U. S. Nuclear Regulatory Commission  
Division of Technical Information and Document Control

Institute of Nuclear Power Operations (INPO)