

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 F L T P S 4 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31 CAT 38

CON'T

01 L 5 0 5 0 0 0 2 5 1 7 1 2 0 7 8 3 8 1 2 3 0 8 3 9

REPORT SOURCE 80 81 DOCKET NUMBER 88 89 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 While adding nitrogen to the Unit 4 accumulators, the relief valve on the 4B

03 accumulator lifted prematurely at approx. 660 psig instead of the 700 psig setpoint.

04 Consequently, the 4B accumulator was depressurized to approx. 550 psig. This is below

05 the minimum pressure of 600 psig required by T.S.3.4.1.a.3 and is reportable under

06 T.S.6.9.2.b.2. The health and safety of the public were not affected. A similar LER

07 was 251-83-006.

08

09

SYSTEM CODE C F 11 CAUSE CODE E 12 CAUSE SUBCODE X 13 COMPONENT CODE V A L V E X 14 COMP SUBCODE X 15 VALVE SUBCODE B 16

LER/RO REPORT NUMBER 17 8 3 21 22 SEQUENTIAL REPORT NO. 0 2 1 24 25 OCCURRENCE CODE 0 3 28 29 REPORT TYPE L 30 REVISION NO. 0 32

ACTION TAKEN Z 18 FUTURE ACTION D 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED N 23 NPRO-4 FORM SUB Y 24 PRIME COMP SUPPLIER L 25 COMPONENT MANUFACTURER C 7 1 1 25

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 The accumulator pressure was returned to the required 600 psig in approx. 4 minutes.

11 The root cause was the apparent premature lifting of relief valve 858B. A plant work

12 order has been written to inspect the valve and take corrective action as necessary

13 during the next available outage.

14

15

FACILITY STATUS E 23 % POWER 1 0 0 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operator observation 32

ACTIVITY CONTENT Z 33 Z 34 N/A AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36

PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION N/A 39

PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION N/A 41

LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43

PUBLICITY ISSUED N 44 DESCRIPTION N/A 45

20

NAME OF PREPARER Z. E. Berry8401050564 831230
PDR ADOCK 05000251
PDR
SPHONE: 305/245-2910 ext. 353

USNRC REGION II
ATLANTA, GEORGIA

84 JAN 3 P2:23



December 30, 1983
PNS-LI-83-758

Mr. James P. O'Reilly
Regional Administrator, Region II
U.S. Nuclear Regulatory Commission
101 Marietta Street N.W., Suite 2900
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 251-83-021

TURKEY POINT UNIT 4

DATE OF OCCURRENCE: DECEMBER 7, 1983

TECHNICAL SPECIFICATION 3.4.1.a.3

4B ACCUMULATOR

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30-day notification of the subject occurrence.

Very truly yours,

A handwritten signature in dark ink, appearing to read "J. W. Williams, Jr.", is written over the typed name.

J. W. Williams, Jr.
Vice President
Nuclear Energy Department

JWW/PKG/js

Attachment

cc: Director, Office of Inspection and Enforcement (30)
Harold F. Reis, Esquire
File 933.1 TP

A rectangular stamp with the word "RECEIVED" is partially visible. Below it, the handwritten initials "Jkz 2/11" are written in dark ink.