

## LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 M I D C C 1 2 0 0 - 0 0 0 0 0 0 - 0 0 0 3 4 1 1 1 1 4 5  
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T  
01 REPORT SOURCE L 6 0 5 0 0 0 3 1 5 7 1 1 2 3 8 3 8 1 2 2 2 8 3 9  
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 DURING A VISUAL LEAK INSPECTION IN CONTAINMENT, WHILE IN OPERATIONAL MODE 4, IT

03 WAS DISCOVERED THAT THE RESERVOIR AND HALF OF ITS RETAINING CLAMP FOR

04 SNUBBER #1-GRC-S594 WERE FOUND DETACHED FROM THE SNUBBER. THIS CONDITION

05 RENDERED THE SNUBBER INOPERABLE WHICH IS NONCONSERVATIVE WITH RESPECT TO

06 T.S. 3.7.8. THE ACTION REQUIREMENTS WERE MET. PUBLIC HEALTH AND SAFETY WERE

07 NOT AFFECTED. THIS IS A FIRST OCCURRENCE OF THIS TYPE.

08

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE  
C J 11 E 12 B 13 S U P P O R T 14 D 15 Z 16  
9 10 11 12 13 18 19 20

17 LER/RO REPORT NUMBER 8 3 1 1 9 0 3 L 0  
21 22 23 24 26 27 28 29 30 31 32

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB ME COMP SUPPLIER COMPONENT MANUFACTURER  
C 18 Z 19 Z 20 Z 21 0 0 0 0 N 23 Y 24 A 25 I 2 0 7 26  
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 THE RESERVOIR RETAINING CLAMP FASTENERS HAD LOOSENED, ALLOWING THE RESERVOIR

11 TO HANG UNSUPPORTED ON THE SUPPLY LINE. VIBRATION DUE TO PREMATURE LIFTING OF

12 PZR SAFETY VALVE SV 45B APPARENTLY CAUSED THE RESERVOIR SUPPLY LINE TO FRACTURE.

13 A NEW SNUBBER WAS TESTED AND INSTALLED. THE REMAINING HYDRAULIC SNUBBERS WERE

14 INSPECTED AND LOCK WASHERS INSTALLED ON THE RESERVOIR RETAINING CLAMP FASTENERS.

15 FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DISCOVERY DESCRIPTION 32  
D 28 0 0 0 29 NA B 31 MAINTENANCE ENGINEER OBSERVATION  
7 8 9 10 12 13 44 45 46 80

16 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36  
Z 33 Z 34 NA NA  
7 8 9 10 11 44 45 80

17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39  
0 0 0 37 Z 38 NA  
7 8 9 11 12 13 80

18 PERSONNEL INJURIES NUMBER DESCRIPTION 41  
0 0 0 40 NA  
7 8 9 11 12 80

19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43  
Z 42 NA  
7 8 9 10 80

20 PUBLICITY ISSUED DESCRIPTION 45  
N 44 NA  
7 8 9 10 80

8401050636 831222  
PDR ADOCK 05000315  
S PDR

NAME OF PREPARER W. J. FLAGA PHONE 616-465-5901

NRC USE ONLY

**INDIANA & MICHIGAN ELECTRIC COMPANY**

DONALD C. COOK NUCLEAR PLANT  
P.O. Box 458, Bridgman, Michigan 49106  
(616) 465-5901

December 22, 1983

Mr. J.G. Keppler, Regional Administrator  
United States Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Operating License DPR-58  
Docket No. 50-315

Dear Mr. Keppler:

Pursuant to the requirements of the Appendix A Technical Specifications, the following report/s are submitted:

RO 83-119/03L-0

Sincerely,

W.G. Smith, Jr.  
Plant Manager

/cbm

Attachment

cc: John E. Dolan  
M.P. Alexich  
R.F. Kroeger  
H. Brugger  
E.R. Swanson, RO:III  
R.C. Callen, MPSC  
G. Charnoff, Esq.  
J.M. Hennigan  
R.O. Bruggee, EPRI  
INPO  
PNSRC  
J.F. Stietzel  
E.L. Townley  
Dir., IE (30 copies)  
Dir., MIPC (3 copies)

DEC 29 1983

IE 2211