

CONTROL BLOCK: ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)01 C A S I O S 3 2 0 0 1 - 0 0 0 0 0 - 0 0 0 3 4 1 1 1 1 1 4 5  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100  
LICENSEE CODE 14 15 LICENSE NUMBER 23 24 LICENSE TYPE 30 31 CAT 38

CONT

01 REPORT SOURCE L 8 0 5 0 0 0 3 6 2 7 1 1 1 1 9 8 3 8 1 2 1 6 8 3 9  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100  
DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 On 11/19/83, at 1810, with Unit 3 in Mode 3, and on 11/29/83, at 2139,  
03 with Unit 3 in Mode 1, mini-purge exhaust Containment Isolation Valve  
04 3HV9825 failed to close within its maximum isolation time during perfor-  
05 mance of Surveillance Procedure S023-3-3.30. In each event, 3HV9825 was  
06 declared inoperable and the affected penetration was isolated in accor-  
07 dance with LCO 3.6.3, Action Statement 'b'. There was no impact on  
08 public health and safety associated with these events.

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
S D 11 E 12 X 13 V A L V O P 14 D 15 Z 16  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100  
17 LEAKING REPORT NUMBER 18 3 19 10 20 5 21 1 22 0 23 3 24 1 25 0 26 1 27 0 28 3 29 1 30 1 31 0 32 0 33 0 34 0 35 0 36 0 37 0 38 0 39 0 40 0 41 0 42 0 43 0 44 0 45 0 46 0 47 0 48 0 49 0 50 0 51 0 52 0 53 0 54 0 55 0 56 0 57 0 58 0 59 0 60 0 61 0 62 0 63 0 64 0 65 0 66 0 67 0 68 0 69 0 70 0 71 0 72 0 73 0 74 0 75 0 76 0 77 0 78 0 79 0 80 0 81 0 82 0 83 0 84 0 85 0 86 0 87 0 88 0 89 0 90 0 91 0 92 0 93 0 94 0 95 0 96 0 97 0 98 0 99 0 100  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NFRD-4 FORM SUB PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
E 18 Z 19 Z 20 Z 21 0 22 0 23 0 24 0 25 0 26 0 27 0 28 0 29 0 30 0 31 0 32 0 33 0 34 0 35 0 36 0 37 0 38 0 39 0 40 0 41 0 42 0 43 0 44 0 45 0 46 0 47 0 48 0 49 0 50 0 51 0 52 0 53 0 54 0 55 0 56 0 57 0 58 0 59 0 60 0 61 0 62 0 63 0 64 0 65 0 66 0 67 0 68 0 69 0 70 0 71 0 72 0 73 0 74 0 75 0 76 0 77 0 78 0 79 0 80 0 81 0 82 0 83 0 84 0 85 0 86 0 87 0 88 0 89 0 90 0 91 0 92 0 93 0 94 0 95 0 96 0 97 0 98 0 99 0 100  
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 These events were caused by an imbalance between opening air supply  
11 pressure and closing spring tension. The necessary adjustments were  
12 made and 3HV9825 was declared operable on 11/21/83 at 0425, and on  
13 11/30/83 at 0531, respectively. No further corrective action is planned.

14

15 FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)  
B 28 0 0 0 29 NA B 31 Surveillance Test  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

16 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)  
Z 33 Z 34 NA NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)  
0 0 0 37 Z 38 NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

18 PERSONNEL INJURIES NUMBER DESCRIPTION (41)  
0 0 0 40 NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43) NA  
Z 42  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

20 PUBLICITY ISSUED DESCRIPTION (45) NA  
N 44  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

NAME OF PREPARER J. G. HAYNES

PHONE 714/492-7700

8401040306 831216  
PDR ADOCK 05000362  
S PDR

RECEIVED  
RRC

*Southern California Edison Company*

SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

REGION V I&E

SCE

J. G. HAYNES  
STATION MANAGER

TELEPHONE  
(714) 492-7700

December 16, 1983

U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region V  
1450 Maria Lane, Suite 210  
Walnut Creek, California 94596-5368

Attention: Mr. J. B. Martin, Regional Administrator

Dear Sir:

Subject: Docket No. 50-362  
30-Day Report  
Licensee Event Report No. 83-105  
San Onofre Nuclear Generating Station, Unit 3

Pursuant to Section 6.9.1.13.b of Appendix A, Technical Specifications to Facility Operating License NPF-15 for San Onofre Unit 3, this submittal provides the required 30-day written report and a copy of the Licensee Event Report (LER) form for two occurrences involving Limiting Condition for Operation (LCO) 3.6.3 associated with Containment Isolation Valves. Since the two occurrences involve the same component, system, cause and method of discovery, these events have been combined into a single report in accordance with NUREG-0161.

On November 19, 1983, at 1810, with Unit 3 in Mode 3, and on November 29, 1983, at 2139, with Unit 3 in Mode 1 at 93% power, mini-purge exhaust Containment Isolation Valve 3HV9825 failed to close within its maximum isolation time of 5 seconds during performance of Surveillance Procedure SO23-3-3.30. In each event, 3HV9825 was declared inoperable and the affected penetration was isolated in accordance with LCO 3.6.3, Action Statement 'b'.

In the first event, 3HV9825 was found to close in 5.5 seconds. The opening air supply pressure was decreased and the closing spring tension was increased. 3HV9825 was demonstrated to close in 4.85 seconds and was declared operable on November 21, 1983, at 0425. In the second event, 3HV9825 was found to close in 5.24 seconds, and closing spring tension was again increased. 3HV9825 was demonstrated to close in 4.43 seconds and was declared operable on November 30, 1983, at 0531.


11 IE-22

December 16, 1983

These events were caused by an imbalance between opening air supply pressure and closing spring tension. No further corrective action is planned. There was no impact on the health and safety of plant personnel or the public associated with these events.

If you require any additional information, please so advise.

Sincerely,



Enclosure: LER No. 83-105

cc: A. E. Chaffee (USNRC Resident Inspector, Units 1, 2 and 3)  
J. P. Stewart (USNRC Resident Inspector, Units 2 and 3)

U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement

U. S. Nuclear Regulatory Commission  
Division of Technical Information and Document Control

Institute of Nuclear Power Operations (INPO)