

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

9 W I K N P 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CONT

REPORT SOURCE: L 6 0 5 0 0 0 3 0 5 7 1 1 2 1 8 3 3 1 2 2 1 8 3 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

During full power operation the IRPI channel for Rod J-10 was removed from service for maintenance. TS 3.10.f.1.A allows operation between 50 and 100 percent power with an RPI channel out of service provided that the RCC positions are checked indirectly every shift or subsequent to rod motion exceeding 24 steps. This is reportable per TS 6.9.2.b(2) as operation in a degraded mode permitted by an LCO. Since RPI was available on the plant process computer there was no effect on public health and safety.

SYSTEM CODE I F 11		CAUSE CODE X 12		CAUSE SUBCODE Z 13		COMPONENT CODE I N S T R U 14				COMP. SUBCODE X 15		VALVE SUBCODE Z 16	
LER/RO REPORT NUMBER 8 9 17		EVENT YEAR 8 3 21 22		SEQUENTIAL REPORT NO. 0 3 1 24 26		OCCURRENCE CODE 0 3 28 29		REPORT TYPE L 30		REVISION NO. 0 32			
ACTION TAKEN E 18		FUTURE ACTION Z 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22 40		ATTACHMENT SUBMITTED N 23		NPRD-4 FORM SUB. Y 24	
PRIME COMP. SUPPLIER N 25		COMPONENT MANUFACTURER W 1 2 0 26											

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Instrument maintenance was required because the IRPI for rod J-10 had failed high.

1 1 Investigation revealed that the conditioning module was good, but the remote

1 2 indicator span had drifted high. The indicator span was recalibrated and the module

1 3 returned to service. A spot check on the calibration points was performed with

1 4 acceptable results. No further action is required.

8 9 FACILITY STATUS (28) 10 11 12 13 % POWER 1 0 0 (29) 14 15 16 17 OTHER STATUS (30) NA 18 19 20 21 22 23 24 25 26 27 METHOD OF DISCOVERY (31) A 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 DISCOVERY DESCRIPTION (32) Operator Observation 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 2 9 10 11

NA

AMOUNT OF ACTIVITY (35)

44

45

80

LOCATION OF RELEASE (36)

PERSONNEL EXPOSURES

NUMBER			TYPE	DESCRIPTION
0	0	0	Z	NA

PERSONNEL INJURIES	
NUMBER	DESCRIPTION
000	NA

1	2	3	4	5	6	7	8	9	10	11	12
LOSS OF OR DAMAGE TO FACILITY (43)											
TYPE		DESCRIPTION									
Z (42)		NA									
S 8401040309 831221 PDR ADOCK 05000305 PDR											

8 9 10
PUBLICITY
ISSUED (44) DESCRIPTION (45) _____
2 7 N NA _____
NRC USE ONLY

NAME OF PREPARER

S.L. Bernhoft /J.G. Thorgersen

PHONE: (414) 388-2560

NRC USE ONLY

NO 917-925

WISCONSIN PUBLIC SERVICE CORPORATION



P.O. Box 1200, Green Bay, Wisconsin 54305

December 21, 1983

Mr. J. G. Keppler, Regional Administrator
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr. Keppler:

Docket 50-305
Operating License DPR-43
Reportable Occurrence 83-031/03L-0

In accordance with the requirements of the Technical Specifications, Section 6.9, the attached Licensee Event Report for reportable occurrence 83-031/03L-0 is being submitted.

Very truly yours,

C. W. Giesler
Vice President - Nuclear Power

JGT/jks

Attach.

cc - Dir, Office of Inspection & Enforcement
US NRC, Washington, DC 20555
Dir, Office of Mgt Info & Program Control
US NRC, Washington, DC 20555
INPO Records Center
Suite 1500, 1100 Circle 75 Parkway
Atlanta, GA 30339
Mr. Robert Nelson, NRC Resident Inspector
RR #1, Box 999, Kewaunee, WI 54216
Mr. S. A. Varga, Chief
US NRC, Washington, DC 20555

11 IEJ2
DEC 23 1983