

### LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	-	0	3	2	5	7	1	1	2	7	8	3	8	1	2	2	7	8	3	9
60	61									68	69						74	75						80
DOCKET NUMBER											EVENT DATE							REPORT DATE						

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During a unit reactor startup, reactor power intermediate range monitor (IRM), C51-IRM-K601H was deter-

0 3 | mined to be inoperable due to downscale indications. At the time, IRM K601A had been inoperable since Aug-

0 4 | ust 10, 1983, due to intermittent indications and IRM K601D had been inoperable since November 16, 1983,

0 5 | as a control rod block input due to incomplete surveillance requirements. This event rendered the IRM

0 6 | control rod block function inoperable due to less than six (6) operable IRMs, the specified minimum re-

0 7 | quired number of operable IRMs. This event did not affect the health and safety of the public.

Technical Specifications 3.3.4, 6.9.1.9b

SYSTEM CODE I B 11		CAUSE CODE E 12		CAUSE SUBCODE E 13		COMPONENT CODE I N S T R U 14		COMP. SUBCODE Y 15		VALVE SUBCODE Z 16	
EVENT YEAR 8 3 21 22		SEQUENTIAL REPORT NO. 0 6 1 24 25 26		OCCURRENCE CODE 0 3 28 29		REPORT TYPE L 30		REVISION NO. 0 32			
ACTION TAKEN X 18		FUTURE ACTION Z 19		EFFECT ON PLANT C 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 22		ATTACHMENT SUBMITTED N 23	
NPRD-4 FORM SUB Y 24		PRIME COMP. SUPPLIER N 25		COMPONENT MANUFACTURER G 0 8 0 26							

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The signal preamplifier low/high range gain of K601H, Part No. 194X672G8, was out of adjustment. The

1 1 | problem with K601A is attributed to a defective instrument cable. K601D was inoperable as a control rod

1 2 | block input because the monitor detector position control rod block functional test, PI-01.10, was pending

1 3 | performance. PI-01.10 was satisfactorily completed and the system was returned to service within 2 hours

1 4 | and 36 minutes of the event.

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	C	0 0 3	NA	A	Operational Event			
7	8	9	10	11	12	13	14	15	16
ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
1	6	Z	Z	NA	NA				
7	8	9	10	11	12	13	14	15	16
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION			
1	7	0 0 0	Z	NA					
7	8	9	10	11	12	13	14	15	16
PERSONNEL INJURIES		NUMBER		DESCRIPTION					
1	8	0 0 0	NA						
7	8	9	10	11	12	13	14	15	16
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION					
1	9	Z	NA						
7	8	9	10	11	12	13	14	15	16
PUBLICITY ISSUED		DESCRIPTION							
2	0	N	NA						
7	8	9	10	11	12	13	14	15	16

8401040315 831227  
PDR ADOCK 05000325  
S PDR

NRC USE ONLY

NAME OF PREPARER M. J. Pastva, Jr.

PHONE: 919-457-9521



Carolina Power & Light Company

DEC 29 8:58

Brunswick Steam Electric Plant  
P. O. Box 10429  
Southport, NC 28461-0429

December 27, 1983

FILE: B09-13510C  
SERIAL: BSEP/83-4037

Mr. James P. O'Reilly, Administrator  
U. S. Nuclear Regulatory Commission  
Region II, Suite 3100  
101 Marietta Street N.W.  
Atlanta, GA 30303

BRUNSWICK STEAM ELECTRIC PLANT, UNIT NO. 1  
DOCKET NO. 50-325  
LICENSE NO. DPR-71  
LICENSEE EVENT REPORT 1-83-61

Dear Mr. O'Reilly:

In accordance with Section 6.9.1.9b of the Technical Specifications for Brunswick Steam Electric Plant, Unit No. 1, the enclosed Licensee Event Report is submitted. This report fulfills the requirement for a written report within thirty (30) days of a reportable occurrence and is in accordance with the format set forth in NUREG-0161, July 1977.

Very truly yours,

C. R. Dietz, General Manager  
Brunswick Steam Electric Plant

MJP/joh/LETJH1

Enclosure

cc: Mr. R. C. DeYoung  
NRC Document Control Desk

OFFICIAL COPY

IE 22

11