

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 WIKNP1 200-00000-00 3411111 4 5

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CONT

01 REPORT SOURCE L 6050003 57111783 8121683 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 During full power operation the sampling pump for the containment gaseous and
03 particulate radiation monitor (R-11) failed to operate. This placed the plant
04 in an LCO per TS 3.1.d.5 which allows the reactor coolant leak detection system
05 sensitive to radiation to be out of service for up to 12 hours. The failure is
06 reportable per TS 6.9.2.b.(2) as operation in a degraded mode permitted by an LCO.
07 The backup detection system sensitive to radiation (R-21) was aligned for sampling,
08 hence, there was no effect on public health and safety.

09 SYSTEM CODE BB 11 CAUSE CODE E 12 CAUSE SUBCODE F 13 COMPONENT CODE MOTORX 14 COMP. SUBCODE Z 15 VALVE SUBCODE Z 16

17 LER/RO REPORT NUMBER 83 EVENT YEAR 030 SEQUENTIAL REPORT NO. 03 OCCURRENCE CODE 03 REPORT TYPE L REVISION NO. 0

ACTION TAKEN C 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0000 ATTACHMENT SUBMITTED N 23 NPD-4 FORM SUB. Y 24 PRIME COMP. SUPPLIER N 25 COMPONENT MANUFACTURER W120 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 Investigation revealed that the paper drive fast speed motor had shorted out due
11 to bare wires. The motor shorting out caused the control power fuse to blow which
12 caused the pump to stop. Both the fast and slow speed motors were replaced. In
13 addition, maintenance found the pump to be slightly out of alignment and replaced
14 the pump and coupling. The system was placed back in service; no further action is

required. 80

15 FACILITY STATUS E 28 % POWER 100 29 OTHER STATUS NA 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operator Observation 32

16 ACTIVITY CONTENT Z 33 RELEASED OF RELEASE Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36

17 PERSONNEL EXPOSURES NUMBER 000 37 TYPE Z 38 DESCRIPTION NA 39

18 PERSONNEL INJURIES NUMBER 000 40 DESCRIPTION NA 41

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43

20 PUBLICITY N 44 DESCRIPTION NA 45

8401040321 831215
PDR ADOCK 05000305
S PDR

IE225

NAME OF PREPARER S.L. Bernhoft/J.G. Thorgersen

PHONE: (414) 388-2560

NRC USE ONLY

9-22-16 C-3

WISCONSIN PUBLIC SERVICE CORPORATION



P.O. Box 1200, Green Bay, Wisconsin 54305

December 16, 1983

Mr. J. G. Keppler, Regional Administrator
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr. Keppler:

Docket 50-305
Operating License DPR-43
Reportable Occurrence 83-030/03L-0

In accordance with the requirements of the Technical Specifications, Section 6.9, the attached Licensee Event Report for reportable occurrence 83-030/03L-0 is being submitted.

Very truly yours,

A handwritten signature in cursive script, appearing to read "C. W. Giesler".

C. W. Giesler
Vice President - Nuclear Power

JGT/jks

Attach.

cc - Dir, Office of Inspection & Enforcement
US NRC, Washington, DC 20555
Dir, Office of Mgt Info & Program Control
US NRC, Washington, DC 20555
INPO Records Center
Suite 1500, 1100 Circle 75 Parkway
Atlanta, GA 30339
Mr. Robert Nelson, NRC Resident Inspector
RR #1, Box 999, Kewaunee, WI 54216
Mr. S. A. Varga, Chief
US NRC, Washington, DC 20555

1/1 IE22
DEC 19 1983