

CONTROL BLOCK:  (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 M A P P S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
7 8 9 14 15 25 26 30 37 38

CONT

01 REPORT SOURCE 60 61 0 5 0 - 0 2 9 3 7 1 0 1 2 8 3 8 1 2 2 1 8 3 9  
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 On 10/12/83, during steady state operation, the mainstack monitor system lost  
03 flow when the sample pump tripped. Flow was restored within one hour (20 min-  
04 utes) by changing over to the standby pumps, thereby avoiding a T.S. required  
05 plant shutdown for an inoperable stack monitor system (T.S. 3.8.B.5). This  
06 event caused no threat to the public health and safety.

07  
08

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
M C 11 E 12 F 13 P U M P E X 14 H 15 Z 16  
7 8 9 10 11 12 13 14 15 16  
17 LER/RO REPORT NUMBER 21 22 8 3 23 24 0 5 8 25 26 0 3 27 28 0 3 29 30 L 31 32 0 33  
18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS 22 ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER 26  
C 18 D 19 Z 20 Z 21 0 0 0 0 N 23 N 24 L 25 G 2 0 0 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Low output pressure from the newly installed rebuilt pump caused a pressure  
11 switch to trip the pump within one half hour after a routine changeout. A second  
12 rebuilt pump was installed and has operated satisfactorily. These pumps are  
13 periodically changed out and rebuilt to reduce a recurrence of this type of  
14 event. The failed pump was rebuilt with no cause or failure apparent.

15 FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DISCOVERY DESCRIPTION 32  
E 28 0 9 7 29 N/A A 31 Annunciation  
7 8 9 10 11 12 13 44 45 46 80

16 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36  
Z 33 Z 34 N/A N/A  
7 8 9 10 11 12 13 44 45 80

17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39  
0 0 0 37 Z 38 N/A  
7 8 9 10 11 12 13 80

18 PERSONNEL INJURIES NUMBER DESCRIPTION 41  
0 0 0 40 N/A  
7 8 9 10 11 12 80

19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43  
Z 42 N/A  
7 8 9 10 80

20 PUBLICITY ISSUED DESCRIPTION 45  
N 44 N/A  
7 8 9 10 80

IE22

NAME OF PREPARED  
8401120208 831221  
PDR ADOCK 05000293  
S PDR

G.G. Whitney

PHONE 617-746-7900

NRC USE ONLY

BOSTON EDISON COMPANY  
800 BOYLSTON STREET  
BOSTON, MASSACHUSETTS 02199

WILLIAM D. HARRINGTON  
SENIOR VICE PRESIDENT  
NUCLEAR

December 21, 1983

BECO Ltr. #83-298

Regional Administrator, Region 1  
U. S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406

Docket Number 50-293  
License DPR-35

Dear Sir:

The attached Licensee Event Report 83-058/03L-0 "Main Stack Sample Pump" is hereby submitted in accordance with the requirements of Pilgrim Nuclear Power Station Technical Specification 6.9.B.2.b.

This event is being reported late because the original determination (not reportable) was found to be incorrect. The late report is due to personnel error and was an isolated incident. Existing procedures combined with recent discussion on the definition of stack sample pump operability are considered adequate to prevent recurrence of a late report on this subject.

If there any questions on this subject, please do not hesitate to contact the undersigned.

Respectfully submitted,

*W D Harrington*  
W. D. Harrington

/ko

Enclosure: LER 83-058/03L-0

cc: Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Standard BECO LER Distribution

IE22  
11