

CONTROL BLOCK: ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)0 1 P A S E S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 38

CONT

0 1 REPORT SOURCE L 6 0 5 0 0 0 3 8 7 7 1 1 2 6 8 3 8 1 2 2 2 8 3 9
7 8 9 DOCKET NUMBER 60 61 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While performing surveillance on valve SV-15736A located in the return line from
0 3 the PASS Containment Radiation Detection System, and H₂/O₂ Analyzers, a dual indi-
0 4 cation was received when the valve position switch was placed in the "close" pos-
0 5 ition; resulting in the LCO as specified in T.S. 3.6.3.a. During this event a sec-
0 6 ond return line isolation valve remained closed; there were no consequences to the
0 7 health and safety of the public.

0 8

0 9 P E 11 B 12 X 13 V A L V E X 14 X 15 H 16
7 8 9 SYSTEM CODE 10 CAUSE CODE 11 CAUSE SUBCODE 12 COMPONENT CODE 13 COMP. SUBCODE 14 VALVE SUBCODE 15

17 LER/RO REPORT NUMBER 8 3 1 5 9 0 3 L 0
21 22 23 24 25 26 27 28 29 30 31 32
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPR-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER (26)
Z 18 G 19 Z 20 Z 21 0 0 0 0 Y 23 N 24 A 25 T 0 2 0 0
33 34 35 36 37 38 39 40 41 42 43 44 45

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Dual indication is due to infrequent valve operation; A list of Target Rock
1 1 solenoid valves has been identified; The current cycling frequency will be
1 2 investigated and when deemed necessary, this frequency will be increased.

1 3

1 4

1 5 E 28 1 0 0 29 NA 30 B 31 Operator Observation 32
7 8 9 FACILITY STATUS 10 % POWER 11 OTHER STATUS 12 METHOD OF DISCOVERY 13 DISCOVERY DESCRIPTION 141 6 Z 33 Z 34 NA 35 NA 36
7 8 9 ACTIVITY CONTENT RELEASED OF RELEASE 10 AMOUNT OF ACTIVITY 11 LOCATION OF RELEASE 121 7 0 0 0 37 Z 38 NA 39
7 8 9 PERSONNEL EXPOSURES NUMBER 10 TYPE 11 DESCRIPTION 121 8 0 0 0 40 NA 41
7 8 9 PERSONNEL INJURIES NUMBER 10 DESCRIPTION 111 9 Z 42 NA 43
7 8 9 LOSS OF OR DAMAGE TO FACILITY TYPE 10 DESCRIPTION 112 0 N 44 NA 45
7 8 9 PUBLICITY ISSUED DESCRIPTION 10

NAME OF PREPARER B.L. Wilks

PHONE: (717) 542-2181

NRC USE ONLY

ATTACHMENT

LER # 83-159/03L-0

Pennsylvania Power & Light Company
Susquehanna Steam Electric Station
Docket Number: 50-387

While performing Surveillance Procedure SO-173-003 on November 26, 1983, Valve SV-1573A, one of two isolation valves in the return line from the Post Accident Sampling System (PASS) Containment Radiation Detection System and H₂/O₂ Analyzer gave a dual indication when its position switch was placed in the "close" position. The valve position switch was then placed in the "open" position and the correct indication was noted. The position switch was again placed in the "close" position and a dual indication was again received. A Limiting Condition for Operation in accordance with the action statement specified by Technical Specification 3.6.3.a was initiated; the second valve in the return line remained closed in compliance with this LCO.

A work authorization was written and on November 26, 1983, valve SV-15736A was retested with the valve indications operating properly every time; The LCO was cleared on this date. An additional work authorization for further investigation into the dual indication was pursued between December 7 through 12, 1983. During this investigation valve SV-15736A was again stroked successfully on December 7 and 12 with the valve indication operating properly. Investigations on December 10, 1983 revealed, after removing the valve limit switch cover, all limit switch terminations were secure and all contact/terminations free of corrosion. Dual indication is due to infrequent valve operation; A list of Target Rock solenoid valves has been identified; The current cycling frequency will be investigated and when deemed necessary, this frequency will be increased. Since the second return line isolation valve remained closed, there were no consequences to the health and safety of the public.



Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101 • 215 / 770-5151

December 22, 1983

Dr. Thomas E. Murley
Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

SUSQUEHANNA STEAM ELECTRIC STATION
LICENSEE EVENT REPORT 83-159/03L-0
ER 100450 FILE 841-23
PLA-2014

Docket No. 50-387
License No. NPF-14

Dear Dr. Murley:

Attached is Licensee Event Report No. 83-159/03L-0. This event was determined to be reportable per Technical Specification 6.9.1.9.b, in that during surveillance one of the two isolation valves in the return lines for the Post Accident Sampling System (PASS) Containment Radiation Detection System and H₂/O₂ Analyzers gave indication of not stroking fully when the select switch was placed in the "close" position. The Limiting Conditions for Operation (LCO) per Technical Specification Action Statement 3.6.3.a were implemented. Further investigation resulted in no recurrence of dual indication; the LCO was cleared and the valve returned to service.

During this event, the second isolation valve in the return line remained closed. There were no consequences to the health and safety of the public.

H.W. Keiser
Plant Superintendent-Susquehanna SES

BLW/pjg

Attachment

cc: L. Plisco
Resident Inspector
U.S. Nuclear Regulatory Commission
P.O. Box 52
Shickshinny, PA 18655

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555

IE22
11