

3150-2011

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

PHONE: (205) 899-5156

NRC USE ONLY

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 A L J M F 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 58

CONT

01 REPORT SOURCE L 6 0 5 0 0 0 3 4 8 7 1 1 2 8 8 3 8 1 2 2 7 8 3 9
7 8 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 At 0540 on 11/28/83, during performance of FNP-0-STP-26.3 (Control Room Ventilation
03 Isolation Test), the B train control room emergency air cleanup system was declared
04 inoperable when damper HV-3629 failed to close on receipt of a simulated high
05 radiation signal. Tech. Spec. 3.7.7, in part, requires this system to be operable.
06 Tech. Spec. 3.7.7 action statement requirements were met. Health/safety of the
07 public was not affected. This LER is applicable to both Units 1 and 2.

08
09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
S G 11 E 12 B 13 V A L V O P 14 E 15 Z 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20
17 LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
8 3 0 8 8 0 3 L 0
21 22 23 24 25 26 27 28 29 30 31 32
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
D X 19 Z 20 Z 21 0 0 0 0 N 23 N 24 A 25 A 4 9 9
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 This event was caused by failure of the damper solenoid valve. The solenoid
11 valve was repaired and following satisfactory completion of FNP-1-STP-26.3, the
12 B train control room emergency air cleanup system was declared operable at 0841
13 on 11/28/83. A change in design is being investigated to prevent future occurrence.

14
15 FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)
E 28 1 0 0 29 NA B 31 Surveillance Test
7 8 9 10 11 12 13 14 15 16 17 18 19 20
16 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)
Z 33 Z 34 NA NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20

17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
0 0 0 37 Z 38 NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20

18 PERSONNEL INJURIES NUMBER DESCRIPTION (41)
0 0 0 40 NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20

19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)
Z 42 NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20

20 PUBLICITY ISSUED DESCRIPTION (45)
N 44 NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20

NAME OF PREPARER W. G. Hairston, III

PHONE (205) 899-5156

NRC USE ONLY

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 A L J M F 1 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60CON'T
01 REPORT SOURCE L 0 5 0 0 0 3 4 8 7 1 1 2 8 8 3 8 1 2 2 7 8 3 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 At 0540 on 11/28/83, during performance of FNP-0-STP-26.3 (Control Room Ventilation
03 Isolation Test), the B train control room emergency air cleanup system was declared
04 inoperable when damper HV-3629 failed to close on receipt of a simulated high
05 radiation signal. Tech. Spec. 3.7.7, in part, requires this system to be operable.
06 Tech. Spec. 3.7.7 action statement requirements were met. Health/safety of the
07 public was not affected. This LER is applicable to both Units 1 and 2.

08
09
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
S G E B V A L V O P E Z
LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
8 3 0 8 8 0 3 L 0
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NFRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
D X Z Z 0 0 0 0 N N A A 4 9 9

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 This event was caused by failure of the damper solenoid valve. The solenoid
11 valve was repaired and following satisfactory completion of FNP-1-STP-26.3, the
12 B train control room emergency air cleanup system was declared operable at 0841
13 on 11/28/83. A change in design is being investigated to prevent future occurrence.

14
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
E 1 0 0 NA B Surveillance Test
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
Z Z NA NA
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
0 0 0 Z NA
PERSONNEL INJURIES NUMBER DESCRIPTION
0 0 0 NA
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
Z NA
PUBLICITY ISSUED DESCRIPTION
N NA

NAME OF PREPARER W. G. Hairston, III

PHONE (205) 899-5156