

LICENSEE EVENT REPORT

Updated Report: Original
Report Date 12/14/83CONTROL BLOCK: (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---------------|---|---|----|----|----|----|----|----|----|----|----|----|----|----------------|----|----|----|----|----|----|----|----|----|--------------|----|----|----|--|--|--|--|--|--|--------|--|
| 0 | 1 | I | L | D | R | S | 2 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | C | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5 | | | | | | | | |
| 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32 | 33 | 34 | | | | | | | | |
| LICENSEE CODE | | | | | | | | | | | | | | LICENSE NUMBER | | | | | | | | | | LICENSE TYPE | | | | | | | | | | CAT 58 | |

CONT

| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---------------|---|---------------|----|----|----|----|----|----|----|----|----|------------|----|----|----|----|----|----|----|----|----|-------------|----|----|----|----|----|--|--|--|--|
| 0 | 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 3 | 7 | 7 | 1 | 1 | 1 | 9 | 8 | 3 | 8 | 0 | 1 | 0 | 3 | 8 | 4 | 9 | | | | | |
| 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32 | 33 | 34 | | | | |
| REPORT SOURCE | | DOCKET NUMBER | | | | | | | | | | EVENT DATE | | | | | | | | | | REPORT DATE | | | | | | | | | |

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During normal operation, additional maintenance work on the drywell floor drain

0 3 | transmitter prevented the 1200 pumpdown of the drywell floor drain sump (T.S.

0 4 | 4.6.D.1). Calculated leakage from the pumpdown (2.41 gpm) at 1433 was within

0 5 | Tech Spec limits constituting minimal safety significance. There was no effect on

0 6 | public health or safety. Previous occurrence reported by R.O. 83-75/03L on

0 7 | Docket #50-237.

| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---|---|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|----|
| 0 | 8 | | | | | | | | | | | | | | | | | | | | | | | | | | | 80 |
| 7 | 8 | | | | | | | | | | | | | | | | | | | | | | | | | | | 80 |

| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|----------------------|---|--------------|----|---------------|----|-----------------|----|-----------------|----|-------|----|----------------------|----|------------------|----|----------------------|----|------------------------|----|------------|----|-----------------------|----|-----------------|----|-------------|----|--------------|--|
| 0 | 9 | M | A | 11 | E | 12 | E | 13 | I | N | S | T | R | U | 14 | T | 15 | Z | 16 | 8 | 3 | 0 | 7 | 7 | 0 | 3 | X | 1 | |
| 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32 | 33 | 34 | 35 | |
| SYSTEM CODE | | CAUSE CODE | | CAUSE SUBCODE | | COMPONENT CODE | | | | | | | | | | COMP. SUBCODE | | VALVE SUBCODE | | EVENT YEAR | | SEQUENTIAL REPORT NO. | | OCCURRENCE CODE | | REPORT TYPE | | REVISION NO. | |
| LER/RO REPORT NUMBER | | ACTION TAKEN | | FUTURE ACTION | | EFFECT ON PLANT | | SHUTDOWN METHOD | | HOURS | | ATTACHMENT SUBMITTED | | NPRD-4 FORM SUB. | | PRIME COMP. SUPPLIER | | COMPONENT MANUFACTURER | | | | | | | | | | | |
| C | | Z | | Z | | Z | | 0 | | 0 | | N | | N | | N | | G | | 0 | | 8 | | 0 | | 0 | | | |
| 33 | | 34 | | 35 | | 36 | | 37 | | 38 | | 39 | | 40 | | 41 | | 42 | | 43 | | 44 | | 45 | | 46 | | | |

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The noise that was sending an elevated DC signal to the drywell floor drain

1 1 | integrator did not cease upon replacement of the transmitter amplifier the

1 2 | previous day. The entire transmitter was replaced with a Rosemont DP transmitter

1 3 | and the integrator functioned properly. No further action deemed necessary.

| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---|---|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|----|
| 1 | 4 | | | | | | | | | | | | | | | | | | | | | | | | | | | 80 |
| 7 | 8 | | | | | | | | | | | | | | | | | | | | | | | | | | | 80 |

| | | | | | | | | | | | | | | | | | | | | | | | | | | |
|-----------------|---|---------|----|--------------|----|---------------------|----|-----------------------|----|----|----------------------|--|--|--|--|--|--|--|--|--|--|--|--|--|--|----|
| 1 | 5 | E | 28 | 0 | 8 | 0 | 29 | N/A | A | 31 | Operator Observation | | | | | | | | | | | | | | | 32 |
| 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | | | | | | | | | | | | | | | | 80 |
| FACILITY STATUS | | % POWER | | OTHER STATUS | | METHOD OF DISCOVERY | | DISCOVERY DESCRIPTION | | | | | | | | | | | | | | | | | | |

| | | | | | | | | | | | | | | | | | | | | | | | |
|----------------|---|------------------|----|--------------------|----|---------------------|-----|--|--|--|--|--|--|--|--|--|--|--|--|--|--|----|--|
| 1 | 6 | Z | 33 | Z | 34 | N/A | N/A | | | | | | | | | | | | | | | 36 | |
| 7 | 8 | 9 | 10 | 11 | 12 | 13 | | | | | | | | | | | | | | | | 80 | |
| ACTIVITY TAKEN | | CONTENT RELEASED | | AMOUNT OF ACTIVITY | | LOCATION OF RELEASE | | | | | | | | | | | | | | | | | |

| | | | | | | | | | | | | | | | | | | | | | | | | | | |
|----------------------------|---|------|----|-------------|----|----|----|-----|--|--|--|--|--|--|--|--|--|--|--|--|--|----|--|--|--|----|
| 1 | 7 | 0 | 0 | 0 | 37 | Z | 38 | N/A | | | | | | | | | | | | | | | | | | 39 |
| 7 | 8 | 9 | 10 | 11 | 12 | 13 | | | | | | | | | | | | | | | | 80 | | | | |
| PERSONNEL EXPOSURES NUMBER | | TYPE | | DESCRIPTION | | | | | | | | | | | | | | | | | | | | | | |

| | | | | | | | | | | | | | | | | | | | | | | | | |
|---------------------------|---|------|----|-------------|----|-----|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|----|--|----|
| 1 | 8 | 0 | 0 | 0 | 40 | N/A | | | | | | | | | | | | | | | | | | 41 |
| 7 | 8 | 9 | 10 | 11 | 12 | 13 | | | | | | | | | | | | | | | | 80 | | |
| PERSONNEL INJURIES NUMBER | | TYPE | | DESCRIPTION | | | | | | | | | | | | | | | | | | | | |

| | | | | | | | | | | | | | | | | | | | | | | |
|------------------------------------|---|-------------|----|-----|----|----|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|----|
| 1 | 9 | Z | 42 | N/A | | | | | | | | | | | | | | | | | | 43 |
| 7 | 8 | 9 | 10 | 11 | 12 | 13 | | | | | | | | | | | | | | | | 80 |
| LOSS OF OR DAMAGE TO FACILITY TYPE | | DESCRIPTION | | | | | | | | | | | | | | | | | | | | |

| | | | | | | | | | | | | | | | | | | | | | | |
|--------------------|---|-------------|----|-----|----|----|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|----|
| 2 | 0 | N | 44 | N/A | | | | | | | | | | | | | | | | | | 45 |
| 7 | 8 | 9 | 10 | 11 | 12 | 13 | | | | | | | | | | | | | | | | 80 |
| PUBLICATION ISSUED | | DESCRIPTION | | | | | | | | | | | | | | | | | | | | |

8401130184 840103
PDR ADOCK 05000237
S PDR

NRC USE ONLY

NAME OF PREPARER L. Turnquest

PH JNE: (815) 942-2920 x489



Commonwealth Edison

Dresden Nuclear Power Station

R.R. #1

Morris, Illinois 60450

Telephone 815/942-2920

DMB

January 3, 1984

DJS Ltr #84-1

James G. Keppler, Regional Administrator
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Updated Reportable Occurrence Report #83-77/03X-1, Docket #050-237 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.2.(b), conditions leading to operation in a degraded mode permitted by a limiting condition for operation or plant shutdown required by a limiting condition for operation. Error was made in reporting Deviation number instead of the L.E.R. number.

D.J. Scott
Station Superintendent
Dresden Nuclear Power Station

DJS/kjl

Enclosure

cc: Director of Inspection & Enforcement
Director of Management Information & Program Control
U.S. NRC, Document Management Branch
File/NRC

IEJ211

SUPPLEMENT TO DVR

| | | | | |
|---------|-----|-------|------|----------|
| DVR NO. | STA | UNIT, | YEAR | NO. |
| D - 12 | - | 2 | - | 83 - 155 |

| | | | | | |
|---|--|---|--|-----------------------|------|
| PART 1 | | TITLE OF EVENT | | OCCURRED | |
| | | Failure to Pump Drywell Floor Drain Within Alotted Time | | 11/19/83 | 1230 |
| REASON FOR SUPPLEMENTAL REPORT | | | | DATE | TIME |
| | | Deviation number was reported instead of L.E.R. number. | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| PART 2 | | | | | |
| ACCEPTANCE BY STATION REVIEW | | <i>J. Brunner</i> | | <i>John M. Alcorn</i> | |
| DATE | | <i>1/5/84</i> | | <i>1/6/84</i> | |
| SUPPLEMENTAL REPORT APPROVED AND AUTHORIZED FOR DISTRIBUTION | | <i>Douglas Diet</i> | | <i>1/6/84</i> | |
| | | STATION SUPERINTENDENT | | DATE | |

JAN 9 1984