

CONTROL BLOCK										(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)																																																																															
01 C A D C P 1 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4										5																																																																															
7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33										34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50																																																																															
CONT																																																																																									
01 REPORT SOURCE L 0 5 0 0 0 2 7 5 7 1 1 1 4 8 3 8 1 2 1 4 8 3 9																																																																																									
7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33										34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50																																																																															
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10																																																																																									
02 Prior to fuel load, the power switch to the Plant Vent Iodine Sampler (RE-24) was																																																																																									
03 found in the off position. The instrument was declared Inoperable under Technical																																																																																									
04 Specification Section 3.3.3.10. There was no release of radioactive gaseous																																																																																									
05 effluents. RE-24 was Inoperable for a total period of three (3) minutes, and the																																																																																									
06 instrument was returned to service. A similar event was reported in LER83-009.																																																																																									
07 Reportable per Technical Specification Section 6.9.1.13.b.																																																																																									
08																																																																																									
7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50																																																																																									
SYSTEM CODE										CAUSE CODE										CAUSE SUBCODE										COMPONENT CODE										COMP SUBCODE										VALVE SUBCODE																																							
09 B B 11 A 12 E 13 I N S T R U 14 P 15 Z 16																																																																																									
7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33										34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50										51 52 53 54 55 56 57 58 59 60										61 62 63 64 65 66 67 68 69 70																																																											
17 LER/RO REPORT NUMBER										EVENT YEAR										SEQUENTIAL REPORT NO.										OCCURRENCE CODE										REPORT TYPE										REVISION NO.																																							
8 3										—										0 2 6										0 3										L										—										0																													
21 22 23 24 25 26 27 28 29 30 31 32 33										34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50										51 52 53 54 55 56 57 58 59 60										61 62 63 64 65 66 67 68 69 70																																																											
ACTION TAKEN										FUTURE ACTION										EFFECT ON PLANT										SHUTDOWN METHOD										HOURS										ATTACHMENT SUBMITTED										NPRD-4 FORM SUB.										PRIME COMP SUPPLIER										COMPONENT MANUFACTURER									
Z 18 F 19										Z 20										Z 21										0 0 0 0 0										N 23										N 24										L 25										R 0 1 2																			
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50										51 52 53 54 55 56 57 58 59 60										61 62 63 64 65 66 67 68 69 70										71 72 73 74 75 76 77 78 79 80																																																											
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27																																																																																									
10 Power switch was inadvertently switched off during a period of heavy construction																																																																																									
11 activity in the immediate vicinity. To prevent recurrence, a protective cover																																																																																									
12 will be installed over the power switch, additional supervision will be placed																																																																																									
13 over construction personnel and a memo will be distributed reminding construction																																																																																									
14 personnel to use caution while working in the vicinity of operating equipment.																																																																																									
7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50																																																																																									
FACILITY STATUS										% POWER										OTHER STATUS										METHOD OF DISCOVERY										DISCOVERY DESCRIPTION																																																	
15 B 28 0 0 0 0 29										NA										A 31										Alarm in Control Room										32																																																	
7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33										34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50										51 52 53 54 55 56 57 58 59 60										61 62 63 64 65 66 67 68 69 70																																																											
ACTIVITY CONTENT										RELEASED OF RELEASE										AMOUNT OF ACTIVITY										LOCATION OF RELEASE																																																											
16 Z 33 Z 34										NA										NA										36																																																											
7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33										34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50										51 52 53 54 55 56 57 58 59 60										61 62 63 64 65 66 67 68 69 70																																																											
PERSONNEL EXPOSURES										NUMBER										TYPE										DESCRIPTION																																																											
17 0 0 0 37										Z 38										NA																																																																					
7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33										34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50										51 52 53 54 55 56 57 58 59 60										61 62 63 64 65 66 67 68 69 70																																																											
PERSONNEL INJURIES										NUMBER										DESCRIPTION																																																																					
18 0 0 0 40																																																																																									
7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33										34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50										51 52 53 54 55 56 57 58 59 60										61 62 63 64 65 66 67 68 69 70																																																											
LOSS OF OR DAMAGE TO FACILITY										TYPE										DESCRIPTION																																																																					
19 Z 42																																																																																									
7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33										34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50										51 52 53 54 55 56 57 58 59 60										61 62 63 64 65 66 67 68 69 70																																																											
PUBLICITY ISSUED										DESCRIPTION																																																																															
20 N 44																																																																																									
7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33										34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50										51 52 53 54 55 56 57 58 59 60										61 62 63 64 65 66 67 68 69 70																																																											
NAME OF PREPARER										William J. Kelly										PHONE										805-595-7351																																																											
7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33										34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50										51 52 53 54 55 56 57 58 59 60										61 62 63 64 65 66 67 68 69 70																																																											

JE22

RECEIVED
NRC

PACIFIC GAS AND ELECTRIC COMPANY

PG&E

77 BEALE STREET • SAN FRANCISCO, CALIFORNIA 94106 • (415) 781-4211 • TWX 910-372-6587

1983 DEC 15 AM 10:53

JAMES D. SHIFFER
MANAGER

DEPARTMENT OF NUCLEAR PLANT OPERATIONS
NUCLEAR POWER GENERATION

REGION V I&E

December 14, 1983

Mr. John B. Martin, Regional Administrator
U. S. Nuclear Regulatory Commission, Region V
1450 Maria Lane, Suite 210
Walnut Creek, CA 94596-5368


Re: Docket No. 50-275, OL-DPR-76
Diablo Canyon Unit 1
Licensee Event Report 83-026/03L-0
Loss of Power to Iodine Sampler

Dear Mr. Martin:

Pursuant to Section 6.9.1.13.b, of the Technical Specifications, Appendix A to the Diablo Canyon Unit 1 Operating License, the enclosed Licensee Event Report is submitted concerning a temporary loss of power to the Plant Vent Iodine Sampler (RE-24).

This event has in no way affected the public's health and safety.

Sincerely,



Enclosure

cc: G. W. Knighton

Director, Office of Management Information
and Program Control

Service List

IE-22.11