

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 1 1 1 1 1 1 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

<u>0</u>	<u>1</u>		<u>A</u>	<u>R</u>	<u>A</u>	<u>N</u>	<u>O</u>	<u>1</u>	<u>2</u>	<u>0</u>	<u>0</u>	<u>-</u>	<u>0</u>	<u>0</u>	<u>0</u>	<u>0</u>	<u>0</u>	<u>-</u>	<u>0</u>	<u>0</u>	<u>1</u>	<u>4</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>5</u>
7		8	9 LICENSEE CODE 14						15	LICENSE NUMBER 25						26	LICENSE TYPE 30						57	CAT	58				
<u>0</u>	<u>1</u>		REPORT SOURCE 60			<u>L</u>	<u>1</u>	<u>0</u>	<u>5</u>	<u>0</u>	<u>0</u>	<u>0</u>	<u>3</u>	<u>1</u>	<u>3</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>2</u>	<u>8</u>	<u>8</u>	<u>3</u>	<u>1</u>	<u>2</u>	<u>2</u>	<u>8</u>	<u>8</u>	<u>3</u>	<u>1</u>
7		8				61	DOCKET NUMBER 68						69	EVENT DATE 74						75	REPORT DATE 80								

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

On 11/28/83, with Unit 1 at 100% full power (FP) and Unit 2 in Mode 6, a weekly surveillance of the control room ventilation system revealed that control room Ventilation System Fan 2VSF-9 had operated for greater than 1720 hours since the last filter test. 2VSF-9 had operated for 877 hours at the time the discrepancy was detected. Redundant Fan VSF-9 was operable. This occurrence is reportable per Unit 1 Technical Specification (T.S.) 6.12.3.2.b and Unit 2 TS 6.9.1.9.b. A similar occurrence was reported in LER (50-313) 76-019/03L-0.

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE		COMP SUBCODE		VALVE SUBCODE	
0	9	5	G	0	12	Z	13	F	I	L	T
7	8	9	10	11		12		13		14	
LER/RO		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO	
17	REPORT	8	3	---		0	2	7	1	0	3
NUMBER		21	22	23		24	26	27	1	28	29
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB	
X	18	G	19	Z	20	Z	21	0	0	0	12
33		34		35		36		37	40	41	23
PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER									
A	25	C	0	1	0	26		42		43	
44		45		46		47		48		49	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 | 0 | The prediction from the previous week's readings did not indicate that the limit would be exceeded due to an
1 | 1 | erroneous reading. The weekly surveillance procedure does not contain a method of data collection that has pro-
1 | 2 | visions for cross-check of data from previous readings during the data collection. As required by TS 4.10.3.A,
1 | 3 | a sample of carbon from the filter of 2VSF-9 was taken and sent to the laboratory for determination of iodine
1 | 4 | removal efficiency. A procedure revision will be made to provide a method to allow cross-checking of the data.
7 8 9

FACILITY STATUS				% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION						
1	5	E	28	1	0	0	29	Unit 2 Status = H	30	B	31	Routine Surveillance	32
7	8	9	10	11	12	13	14	15	16	17	18	19	20

ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
1	6	2	34	NA	35	NA	36
7	8	9	10	11	44	45	80

PERSONNEL EXPOSURES									
NUMBER		TYPE		DESCRIPTION					
1	7	0	0	0	37	2	38	NA	39
7	8	9	11	12	13				20

PERSONNEL INJURIES									
NUMBER					DESCRIPTION				
1	2	3	4	5	6	7	8	9	10
1	8	0	0	0	40	NA			
7	8	9	11	12					

LOSS OF OR DAMAGE TO FACILITY	
TYPE	DESCRIPTION
1 9	2 42 NA

[illegible]

NAME OF PREPARER: Patrick Rogers

PHONE: (501) 964-3100

B401130318 831228
PDR ADOCK 05000313
S PDR




ARKANSAS POWER & LIGHT COMPANY

POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

December 28, 1983

1CAN125311

Mr. J. E. Gagliardo, Director
Division of Resident Reactor Projects
and Engineering Programs
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76011



Subject: Arkansas Nuclear One - Unit 1
Docket No. 50-313
License No. DPR-51
Licensee Event Report
No. 83-027/03L-0

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 1 Technical Specification 6.12.3.2.b, and Unit 2 Technical Specification 6.9.1.9.b, attached is the subject report concerning a discrepancy in the surveillance testing.

Very truly yours,

John R. Marshall
John R. Marshall
Manager, Licensing

JRM:RJS:s1

Attachment

cc: Mr. Richard C. DeYoung
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. Norman M. Haller, Director
Office of Management & Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

13-22
11